


USNRC REGION II
ATLANTA, GA

79 OCT 26 AII: 17



October 22, 1979.
L-79-294

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-250, 50-251
IE Bulletin 79-03

The purpose of this letter is to confirm our June 5, 1979 commitment (L-79-154) to perform periodic inspections of piping spool pieces as required by IE Bulletin 79-03. One-third of the piping sample will be inspected at each of the next three refueling outages for each unit. The first inspection will be performed during the upcoming Turkey Point Unit 3 refueling outage scheduled to begin approximately November 20, 1979.

The inspection program used during each outage and the results of each inspection will be maintained at the Turkey Point site for review by your inspectors.

Very truly yours,

R. E. Uhrig

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/cph

cc: Harold Reis, Esquire

AOI
2
CCP
790776
7911130137
PEOPLE...SERVING PEOPLE

