



FLORIDA POWER & LIGHT COMPANY

November 30, 1979  
L-79-333

*Central File*  
50-250  
351

37

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection of Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO  
50-250, 50-251  
IE Bulletin 79-17

Our letter L-79-237 dated August 27, 1979 provided color coded drawings that identified the safety related Type 304 stainless steel piping systems that contain stagnant oxygenated borated water.

As a result of revision 1 to the subject Bulletin, we have extended the scope of our inspection program to include Type 316 stainless steel piping. One set of drawings, color coded in yellow, is enclosed to identify the safety related Type 316 piping systems that contain stagnant oxygenated borated water.

Very truly yours,

*Robert E. Uhrig*

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/MAS/paf

Attachment

cc: Director, Division of Operating Reactors, Office of Inspection  
and Enforcement (w/o drawings)  
Harold Reis, Esquire (w/o drawings)

AO/I  
2

**OFFICIAL COPY**

PEOPLE ... SERVING PEOPLE

7912200 C004

128

