



January 11, 1980
L-80-13

Central File
50-250
251

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

Re: RII:JP0
50-250, 50-251
IE BULLETIN 79-28

The subject Bulletin has been reviewed, and we have determined that no NAMCO Model EA 180 Limit Switches are currently installed in safety related systems at Turkey Point Units 3 and 4.

Thirty-six (36) of these switches are being procured in conjunction with planned modifications. A document source inspection has indicated that the switches are free of the condition described in the Bulletin. The switches will be checked again during the receipt inspection.

Very truly yours,


Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS/cph

cc: Harold Reis, Esquire

8002010 02-3

8068 ✓

OFFICIAL COPY
PEOPLE...SERVING PEOPLE

102

