

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8006190285 DOC.DATE: 80/05/30 NOTARIZED: NO DOCKET #
 FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH.NAME AUTHOR AFFILIATION
 SCHOPPMAN,M.A. Florida Power & Light Co..
 RECIP.NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

SUBJECT: Updated LER 80-003/03L-0: on 800215, while testing 4C steam generator feedwater control valve, change in steam generator level lifted low setpoint valve. Valve did not fully reseal. Caused by binding between lifting gear & release nut.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1
 TITLE: Incident Reports

NOTES: _____

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	BC VARGA, S. 05	4	4			
INTERNAL:	A/D RAD PROT	1	1	A/D REACT SYS	1	1
	A/D TECHNOLOGY	1	1	AEOD	10	10
	AUX SYS BR	1	1	CHEM ENG BR	1	1
	CONT SYS BR	1	1	EISENHUT, D.	1	1
	EMERG PREP	1	1	EQUIP QUAL BR	1	1
	HANAUER, S.	1	1	I&C SYS BR	1	1
	I&E 09	2	2	JORDAN, E./IE	1	1
	MPA 11	3	3	NRC PDR 02	1	1
	OP EX EVAL BR	3	3	OR ASSESS BR	1	1
	PPAS	1	1	QA BR	1	1
	<u>REG FILE</u> 01	1	1	SIT ANAL BR	1	1
	SYS INTERAC BR	1	1	TERA: DOUG MAY	1	1
EXTERNAL:	ACRS	16	16	LPDR	03	1
	NSIC 04	1	1			

JUN 20 1980

T

TOTAL NUMBER OF COPIES REQUIRED: LTTR 60 ENCL 60

290