



September 2, 1980

PRN-LI-80-359

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-80-15  
TURKEY POINT UNIT 3

3A SAFETY INJECTION PUMP BREAKER

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30 day notification of the subject occurrence.

Very truly yours,

*J.R. Bensen*  
for A.D. Schmidt  
Vice President  
Power Resources

PLP/md

Attachment

cc: Director, Office of Inspection and Enforcement (40)  
Director, Office of Management Information and  
Program Control (3)  
Harold F. Reis, Esquire  
File 933.1 TP

*1002 5/1*

*50-250*

*8009120350*

*5*

