

CONTROL BLOCK:                      (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01		F L T P S 3 2 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5										L I C E N S E N U M B E R		L I C E N S E T Y P E		C A T					
01		L 6 0 5 0 0 0 2 5 0 7 1 2 1 1 8 0 3 1 2 2 3 8 0 9										R E P O R T S O U R C E		D O C K E T N U M B E R		E V E N T D A T E		R E P O R T D A T E			
E V E N T D E S C R I P T I O N A N D P R O B A B L E C O N S E Q U E N C E S 10																					
02 During power operation of Unit No. 3 and refueling shutdown on Unit No. 4,																					
03 the 4B 125 VDC battery was out of service for approximately 25 hours 18																					
04 minutes. This interval exceeded the 24 hours allowed by TS 3.7.2.c. The																					
05 battery had been out of service for the annual discharge test. Restoring																					
06 the battery to full charge prior to returning it to service following the																					
07 test was delayed by a problem with the associated battery charger.																					
08																					
09																					
10																					
11																					
12																					
13																					
14																					
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					
25																					
26																					
27																					
28																					
29																					
30																					
31																					
32																					
33																					
34																					
35																					
36																					
37																					
38																					
39																					
40																					
41																					
42																					
43																					
44																					
45																					
46																					
47																					
48																					
49																					
50																					
51																					
52																					
53																					
54																					
55																					
56																					
57																					
58																					
59																					
60																					
61																					
62																					
63																					
64																					
65																					
66																					
67																					
68																					
69																					
70																					
71																					
72																					
73																					
74																					
75																					
76																					
77																					
78																					
79																					
80																					
81																					
82																					
83																					
84																					
85																					
86																					
87																					
88																					
89																					
90																					
91																					
92																					
93																					
94																					
95																					
96																					
97																					
98																					
99																					
100																					

During power operation of Unit No. 3 and refueling shutdown on Unit No. 4, the 4B 125 VDC battery was out of service for approximately 25 hours 18 minutes. This interval exceeded the 24 hours allowed by TS 3.7.2.c. The battery had been out of service for the annual discharge test. Restoring the battery to full charge prior to returning it to service following the test was delayed by a problem with the associated battery charger.

A shutdown of Unit No. 3 was initiated in accordance with procedure. The power reduction was terminated at approximately 86 percent power when the battery was returned to service. The unit was then returned to full power.

Facility Status: E, % Power: 100, Other Status: NA, Method of Discovery: B, Discovery Description: Surveillance test, Activity Content Released: Z, Amount of Activity: NA, Location of Release: NA, Personnel Exposures: 0, Description: NA, Personnel Injuries: 0, Description: NA, Loss of or Damage to Facility: Z, Description: NA, Publicity Issued: N, Description: NA.

NAME OF PREPARER: P.L. Pace

PHONE: (305) 552-3801