



December 17, 1980
L-80-409

Central File

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII-JPO
50-250, 50-251
IE Bulletin 80-23

Florida Power & Light has reviewed the subject Bulletin and has determined that Turkey Point Units 3 & 4 do not use Valcor solenoid valves with Part Numbers V70900-21-1 and 21-3. Five man hours were required to prepare this report.

Very truly yours,

J. A. De Mastey
for

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/md

cc: Director, Office of Inspection and Enforcement
Director, Division of Reactor Operations Inspection, Office
of Inspection and Enforcement
Harold F. Reis, Esquire

8101150125

Q

PEOPLE SERVING PEOPLE

