


FLORIDA DISTRIBUTION
SERVICES UNIT

1981 FEB 3 PM 3 33

FLORIDA DISTRIBUTION
SERVICES UNIT



January 28, 1981

PRN-LI-81-42

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 250-80-28
TURKEY POINT UNIT 3
DATE OF OCCURRENCE: DECEMBER 29, 1980

TECHNICAL SPECIFICATION 6.9.2.b

HEATER DRAIN PUMP BREAKER

The attached Licensee Event Report is being submitted in accordance with
Technical Specification 6.9 to provide 30 day notification of the subject
occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

PLP/mrs

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 TP

A002
S
1/1

8102040486

5

100-4