

CONTROL BLOCK:

--	--	--	--	--	--

 ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CCN'T

0	1
---	---

REPORT SOURCE

L	6	0	1	5	10	10	10	2	5	10	7	1	1	2	2	9	8	1	0	3	1	0	1	1	2	1	8	8	1	1	9
---	---	---	---	---	----	----	----	---	---	----	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 During power operation, a DC ground was experienced on the 3B battery bus.

013 Investigation showed a problem with the control power to 4160 V breaker

014 3AB10, for the 3B Heater Drain Pump, which prevented the breaker from

015 being remotely tripped. This is reportable pursuant to TS 6.9.2.b in that

016 this breaker would not have tripped to clear the 3B 4160 V bus in response

017 to a bus stripping signal. The breaker was tripped manually.

ACTION TAKEN		FUTURE ACTION	EFFECT CN PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NFROM FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B	Z	Z	Z	O O O O	N	N	A	G O B O	
(18)	(19)	(20)	(21)	(22)	(23)	(24)	(25)	(26)	

LEAD REPORT NUMBER
EVENT YEAR
SEQUENTIAL REPORT NO.
OCCURRENCE CODE
REPORT TYPE
REVISION NO.

SYSTEM CODE
CAUSE CODE
CAUSE SUBCODE
COMP. SUBCODE
VALVE SUBCODE

0 1 2 3 9 .

0 9

9 E G 11

11 E 12

12 A 13

C K T B K R 14

19 A 15

20 Z 16

21 L 8 0 22

23 — 24 0 2 8 26

27 ✓ 28 0 3 29

30 L 31 — 32 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Investigation showed shorted control circuit wiring between 3AB10 and
11 its local start station. The failure was caused by steam entering the
12 electrical box and shorting out the circuit. This resulted in burning out
13 the trip coil of the breaker. The circuit and conduit have been rerouted
14 and the breaker was replaced with a spare.

7 8 9 10 11 12 13 14 15 16 17 18 19 20

FACILITY STATUS 1 5 E 23 11 0 0 29 OTHER STATUS 30 NA METHOD OF DISCOVERY 31 A 32 DISCOVERY DESCRIPTION Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z 33 Z 34 NA NA

PERSONNEL EXPOSURES				
NUMBER	TYPE	DESCRIPTION	39	
17	00037	Z	33	NA

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30						
PERSONNEL INJURIES																													
NUMBER											DESCRIPTION (41)																		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
1																													

7		3		9		11		12		30	
LOSS OF OR DAMAGE TO FACILITY		(43)									
TYPE		DESCRIPTION									
1		TH									

1 9 7 8 3 10 NA
PUBLICATION (42)
ISSUED DESCRIPTION (45) NRC USE ONLY

2 0 135040 N (44) NA 68 59 10

NAME OF PREPARER P. L. Pace

PHONE: (305) 552-3801

