


USNRO REGION II
ATLANTA, GEORGIA



31 FEB 5 P2:52

February 2, 1981

L-81-34


Central File

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII-JPO

50-250, 50-251, 50-335
IE Bulletin 80-21



As mentioned in our initial response to Bulletin 80-21 (L-80-403) dated December 11, 1980, we have contacted all of the manufacturers who have supplied safety related valves for Turkey Point Units 3 & 4 and St. Lucie Unit 1. We have received written confirmation from 17 of 28 manufacturers that parts cast by Malcolm Foundry were not used in any active safety related valves for these plants. The Anchor Darling Valve Company has notified us that they have supplied some valves for St. Lucie with Malcolm Foundry parts, but none are active safety related valves.

Should any of the remaining valve manufacturers report in their responses that Malcolm Foundry parts were used in active safety related valves we will provide a further report.

Very truly yours,

Robert E. Uhrig

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/mbd

cc: Director, Office of Inspection and Enforcement
Harold Reis, Esquire

8102190 246

