


April 8, 1981

PRN-LI-81-176

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-80-10  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: JUNE 17, 1980  
TECHNICAL SPECIFICATION 3.4.4.b  
4C CCW HEAT EXCHANGER  
UPDATE REPORT NO. 1



The attached Licensee Event Report is being submitted to update our initial report of July 17, 1980.

Very truly yours,

*A.D. Schmidt*  
A.D. Schmidt  
Vice President  
Power Resources

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (40)  
Harold F. Reis, Esquire  
File 933.1 TP

81042703/5

5

*Hook  
5/11*

