

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8106050188 DOC. DATE: 81/05/26 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 EISENHUT, D.G. Division of Licensing

SUBJECT: Advises that no action warranted until Westinghouse owners group work complete re emergency procedures & training for station blackout events, in response to 810225 ltr. Review results will be submitted by 820115 per 810404 ltr.

DISTRIBUTION CODE: A0155 COPIES RECEIVED: LTR 3 ENCL 0 SIZE: 1
 TITLE: Onsite Emergency Power Systems


NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
ACTION: VARGA, S.	04	7					
INTERNAL: AEOD		1	1	I&C SYS BR	09	1	
I&E	06	2	2	MPA	18	1	
NRC PDR	02	1	1	OELD	17	1	
OR ASSESS BR	12	1	1	POWER SYS BR	14	1	
REG FILE	01	1	1				
EXTERNAL: ACRS	16	16	16	INPO, J. STEARNS		1	
LPDR	03	1		NSIC	05	1	

JUN 08 1987

TOTAL NUMBER OF COPIES REQUIRED: LTTR 36 ENCL 36

73 8 2 4




May 26, 1981
L-81-222

Office of Nuclear Reactor Regulation
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
Emergency Procedures And Training
For Station Blackout Events




As a member of the Westinghouse Owners Group, Florida Power & Light subscribes to the program and the schedule described in the Owners Group letter dated April 9, 1981 concerning "Emergency Procedures and Training for Station Blackout Events". As mentioned in that letter, we intend to submit the results of our review of procedures and training by January 15, 1982. This date will give us the time necessary to conduct our review and take any necessary actions following receipt of the Westinghouse loss of AC power guidelines and following the planned Owners Group seminar on the subject.

In the interim, in response to the request in the NRC letter dated February 25, 1981 on this subject, it is our judgement that no action on our part is warranted until the Owners Group work is completed and appropriate actions are identified.

It is our opinion that this course of action is justified because of the exceedingly low probability of a blackout event and because our current procedures and training provide adequate protection for all design bases events.

Very truly yours,


Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/cab

cc: J. P. O'Reilly, Region II
Harold F. Reis, Esquire

A015
S
3/0

8106050188



[The body of the document contains several lines of extremely faint, illegible text. The text appears to be organized into paragraphs, but the characters are too light to be transcribed accurately. There are some faint marks that could be interpreted as 'X' or '2' in the middle section.]