

LICENSEE/EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L T P S 3 2 0 0 1 0 0 1 0 0 1 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CCN'T 01

REPORT SOURCE L 5 0 5 0 0 0 2 1 5 0 7 0 5 0 1 8 1 3 0 5 2 9 8 1 9

DOCKET NUMBER 30 31 EVENT DATE 74 75 REPORT DATE 76 77

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

012 During cold shutdown, the 3A component cooling water (CCW) pump did not

013 start during routine equipment rotation. The 3B and 3C component cooling

014 water pumps remained in service. This failure resulted in 2 CCW pumps

015 operable. T.S. 3.4.4.1 requires 3 pumps to be operable. Similar

016 occurrences were reported on LERs 250-72-4, 250-73-2, 250-74-2, and

017 250-78-10.

018

019

SYSTEM CODE W B 11 CAUSE CODE E 12 CAUSE SUBCODE A 13 COMPONENT CODE C K T B R K 14 COMP SUBCODE A 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 8 1 21 SEQUENTIAL REPORT NO. 0 1 0 24 OCCURRENCE CODE 0 3 27 REPORT TYPE L 30 REVISION NO. 0 32

ACTION TAKEN B 13 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 VPRO-1 FORM SUB. N 24 PRIME COMP SUPPLIER A 25 COMPONENT MANUFACTURER G 0 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

110 Operations personnel found the 3A CCW pump circuit breaker in the trip mode.

111 The closing latch spring in the GE Magne-Blast type breaker had detached on

112 one end which prevented the charging of the closing springs. The breaker

113 was repaired and the pump was then started.

114

FACILITY STATUS G 33 % POWER 0 0 0 0 34 OTHER STATUS NA 35 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Equipment rotation 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY NA 44 DESCRIPTION NA 45

NRC USE ONLY

NAME OF PREPARER P. L. PacePHONE: (305) 552-3801

810608

