

DANTE B. FASCELL  
15TH DISTRICT, FLORIDA

CHARLES R. O'REGAN  
ADMINISTRATIVE ASSISTANT

COMMITTEES:

FOREIGN AFFAIRS

CHAIRMAN; INTERNATIONAL OPERATIONS  
SUBCOMMITTEE  
MEMBER; INTER-AMERICAN AFFAIRS  
SUBCOMMITTEE

GOVERNMENT OPERATIONS

MEMBER; LEGISLATION AND NATIONAL  
SECURITY SUBCOMMITTEE

COMMISSION ON SECURITY AND  
COOPERATION IN EUROPE

CHAIRMAN

CANADIAN-UNITED STATES  
INTERPARLIAMENTARY GROUP  
CHAIRMAN, U.S. DELEGATION

Congress of the United States  
House of Representatives  
Washington, D.C. 20515

December 5, 1980

Mr. Carlton C. Kammerer, Director  
Office of Congressional Affairs  
Nuclear Regulatory Commission  
1717 H Street, NW  
Washington, D. C. 20555


Dear Mr. Kammerer:

Enclosed, for your information, is a copy of a letter which has come to me from one of my constituents, Mr. Warren Hoskins, President, Conchshell Alliance, Miami, Florida.

I would very much appreciate having the Nuclear Regulatory Commission's comments on the points raised in Mr. Hoskins' letter, and any other comments you may wish to make.


Thank you.

Sincerely,

  
DANTE B. FASCELL  
Member of Congress

DBF:RT  
Enclosure

8102280 246





December 2, 1980

Dear Congressman Fascell,


The Conchshell Alliance is calling for a Congressional investigation into the Nuclear Regulatory Commission's handling of the situation at Turkey Point Unit Number 3. Specifically, the N.R.C. was required to have the plant shut down and investigated but those requirements have been ignored.

Beginning Wednesday, November 19th, a series of events at Turkey Point Unit No. 3 caused the shutdown of that unit two times. During the initial accident, an earthquake-like shudder shook the control room, and a pipe ruptured pouring 20,000 gallons of steam and hot water onto the turbine deck. After repairs, Unit 3 was re-started but shut down again because of leaks inside the steam generator (if radioactive water from the primary system in the steam generator gets into the secondary system, leaks of radioactive gases can occur at the turbines). It has been reported that now, radioactive leaks have occurred and the unit has again been shut down for repair.

We call for a Congressional investigation into the extensions granted by the N.R.C. to Florida Power and Light to continue the operation at the plant even after pipe corrosion and other defects were discovered.

This matter is urgent. We look forward to your prompt reply and we thank you for your work in the past on this matter.

Very truly yours,

  
Warren Hoskins, presi:  
Conchshell Alliance

CONCHSHELL ALLIANCE  
PHONE: (305) 253-9458  
P. O. BOX 970405  
MIAMI, FLA. 33197

~~P.O. BOX 420405 - SO. MIAMI, FLA. 33143~~ (305) 253-9458

JAN 30 1981