


USNRC RECD
ATLANTA, GEORGIA

31 OCT 13 AIO: 14



October 6, 1981
L-81-434

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
IE Inspection Report 81-17

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Robert E. Uhrig", is written over the typed name.

Robert E. Uhrig
Vice President
Advanced Systems and Technology

REU/PLP/mbd

Attachment

cc: Harold F. Reis, Esquire

8111130490 811103
PDR ADDCK 05000250
PDR
Q

לר. רכפפ יא ט' ז' . כזרפס:כס"

לא ג' יארנפ

ATTACHMENT

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
IE Inspection Report 81-17

Finding

10 CFR 19.11 requires that licensees post 10CFR19, 10CFR20, the license, license conditions, operating procedures applicable to licensed activities, any notice of violation involving radiological activities, civil penalties, or orders. Documents, which are not feasible to post, may be listed in a notice stating where they may be examined. Notice of Violations, civil penalties and orders are to be posted within two working days after receipt and remain posted at least five days or until corrective action has been completed, whichever is greater.

Contrary to the above, notices to workers were not posted as required in areas of sufficient number to permit individuals engaged in licensed activities to observe them going to and from their work locations in that:

- (1) the Notice of Violation, issued on July 17, 1981, was not posted within two days of receipt and did not remain posted the minimum of five days;
- (2) the order, issued July 22, 1981, to suspend use of the NFS-4 fuel element transfer cask was not posted within two days of receipt and did not remain posted until corrective action was taken; and,
- (3) Parts 19 and 20 or the notice stating where these documents could be examined were not posted in the Nuclear Maintenance Building in a manner such that workers could review this notice going to and from their work locations.

Response

1. FPL concurs with the finding.
2. The reason for the finding was a lapse of application of administrative controls to the New Nuclear Maintenance Building.

3. As corrective action, on August 21, 1981, a notice stating where the following documents could be examined was posted in the new Nuclear Maintenance Building

- 10 CFR 19
- 10 CFR 20
- Facility Operation Licenses
- Construction permits
- Atomic Energy Act, 1954
- Energy Reorganization Act of 1974
- Technical Specifications
- Environmental Technical Specifications
- FSAR
- Final Environmental Statement, Units 3 & 4
- Operating Procedures applicable to Units 3 & 4
- 10 CFR


4. In order to avoid further problems, the documents or a notice stating where they could be examined will be posted in areas of sufficient number to permit individuals engaged in licensed activities to observe them going to and from their work locations.
5. Full compliance will be achieved by October 31, 1981.

STATE OF FLORIDA)
)
COUNTY OF DADE) ss.

Robert E. Uhrig, being first duly sworn, deposes and says:


That he is Vice President of Florida Power & Light Company, the Licensee herein;

That he has executed the foregoing document; that the statements made in this said document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said Licensee.


Robert E. Uhrig

Subscribed and sworn to before me this

6 day of October, 1981


NOTARY PUBLIC, in and for the County of Dade,
State of Florida

My commission expires: Notary Public, State of Florida at Large
My Commission Expires October 30, 1983
Bonded thru Maynard Bonding Agency

