


USNRC REGION II
ATLANTA, GEORGIA



82 JAN 4 A 8:42

December 29, 1981
L-81-540

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
IE Inspection Report 81-21

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/ras

cc: Harold F. Reis, Esquire

8201270673 820112
PDR ADCK 05000250
Q PDR



Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
IE Inspection Report 81-21

FINDING:

Technical Specification 6.11 requires that procedures for personnel radiation protection be consistent with the requirements of 10 CFR Part 20 and be approved, maintained and adhered to for all operations involving personnel radiation exposure.

Contrary to the above, on October 14, 1981, radiation protection procedures were not adhered to in that:

- (1) Four self contained breathing apparatus units had not been inspected monthly as required by Plant Procedure HP-90;
- (2) Four emergency respirators had not been inspected monthly as required by Plant Procedure HP-90;
- (3) An inventory of emergency equipment had not been performed annually as required by Plant Procedure HP-90; and
- (4) One-hundred and fifty respirators had not been properly stored as required by Plant Procedure HP-60.

RESPONSE:

- (1) FPL concurs with the finding.
- (2) The reason for the finding is that the procedures were not fully complied with.
- (3) The following indicates the corrective action for each item:

Item 1 - The four self-contained breathing apparatus units have been inspected as required.

Item 2 - The four emergency respirators have been inspected as required.

Item 3 - The annual inventory of emergency equipment will be completed by January 31, 1982.

Item 4 - Additional storage bins for respirators are being fabricated and should be complete by February 15, 1982.

- (4) As corrective action to prevent recurrences:

Items 1,2 and 3. The proper techniques for inspecting and inventory were discussed with the responsible individual.

Item 4. The construction of the additional storage bins will prevent reoccurrence.


- (5) Full compliance will be achieved by February 15, 1982.

STATE OF FLORIDA)
)
COUNTY OF DADE) ss.

Robert E. Uhrig, being first duly sworn, deposes and says:


That he is Vice President of Florida Power & Light Company, the herein;

That he has executed the foregoing document; that the statements made in this said document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said


Robert E. Uhrig

Subscribed and sworn to before me this

29 day of December, 1981


NOTARY PUBLIC, in and for the County of Dade,
State of Florida

My commission expires: Notary Public, State of Florida at Large
My Commission Expires October 30, 1983
Bonded thru Maynard Bonding Agency

RECEIVED
JAN 10 1964
U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION
WASHINGTON, D.C.