

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8204120214 DOC.DATE: 82/04/05 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH.NAME AUTHOR AFFILIATION
 UHRIG,R.E. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 VARGA,S.A. Operating Reactors Branch 1

SUBJECT: Forwards "Steam Generator Repair Program,Radiological
 Progress Rept,811231-820303."

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+22
 TITLE: General Distribution for after Issuance of Operating License

NOTES:

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
ORB #1	BC 01	13	13				
INTERNAL:	ELD	1	0	IE	06	1	1
	NRR/DHFS DEPY08	1	1	NRR/DL DIR		1	1
	NRR/DL/ORAB	1	0	NRR/DSI/RAB		1	1
	<u>REG FILE</u> 04	1	1	RGN2		1	1
EXTERNAL:	ACRS 09	10	10	LPDR	03	1	1
	NRC PDR 02	1	1	NSIC	05	1	1
	NTIS	1	1				



1. The first part of the document is a list of names and addresses. The names are listed in the first column, and the addresses are listed in the second column. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, 456 Elm St, and 789 Oak St.

2. The second part of the document is a list of names and addresses. The names are listed in the first column, and the addresses are listed in the second column. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, 456 Elm St, and 789 Oak St.

3. The third part of the document is a list of names and addresses. The names are listed in the first column, and the addresses are listed in the second column. The names are: John Doe, Jane Smith, and Bob Johnson. The addresses are: 123 Main St, 456 Elm St, and 789 Oak St.

Y

1
2
3
4
5

Y


1
2
3
4
5

Y


1
2
3
4
5

1
2
3
4
5

1
2
3
4
5



April 5, 1982
L-82-133



Office of Nuclear Reactor Regulation
Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch #1
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Varga:

Re: Turkey Point Unit 3
Docket No. 50-250
Steam Generator Repair Program
Radiological Progress Report - No. 4

Please find attached our fourth Radiological Progress Report for the
Steam Generator Repair Program as required by Section III.I.(2) of DPR-31.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JEM/ras

Attachment

cc: J. P. O'Reilly, Region II
Harold F. Reis, Esquire

A001
1/1

8204120214 820405
PDR ADDCK 05000250
R PDR

