

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8209140009 DOC. DATE: 82/09/07 NOTARIZED: NO DOCKET #  
 ACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 UHRIG, R.E. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 EISENHUT, D.G. Division of Licensing

SUBJECT: Requests that last sentence in final paragraph of 820810  
 proposed mod to turbine runback sys be replaced w/ listed  
 sentence.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR \_\_/ ENCL \_\_/ SIZE: \_\_/\_\_\_\_\_  
 TITLE: OR Submittal: General Distribution

## NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
	NRR	ORB1 BC 01	7	7					
INTERNAL:	ELD/HDS4		1	0	NRR/DHFS DEPY08		1	1	
	NRR/DL DIR		1	1	NRR/DL/ORAB		1	0	
	NRR/DSI/RAB		1	1	<u>REG FILE</u> 04		1	1	
	RGN2		1	1					
EXTERNAL:	ACRS	09	10	10	LPDR	03	1	1	
	NRC PDR	02	1	1	NSIC	05	1	1	
	NTIS		1	1					

[illegible]

1. The first step is to identify the problem. In this case, the problem is that the company is not meeting its sales targets.

[illegible][illegible]



September 7, 1982  
L-82-398

Office of Nuclear Reactor Regulation  
Attention: Mr. Darrell G. Eisenhut, Director  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: Turkey Point Units 3 & 4  
Docket No. 50-250 and 50-251  
Turbine Runback System

Our letter L-82-343, dated August 10, 1982 transmitted a proposed modification to the Turbine Runback System. The last sentence in the final paragraph was not completely correct and should be replaced with the following:

The power mismatch input to the automatic rod control circuitry has been disconnected at Turkey Point Units 3 & 4 and operation is in the manual mode.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/JEM/mbd

Attachments

cc: Mr. James P. O'Reilly, Region II  
Mr. Harold F. Reis, Esquire

A001

