

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8211230253 DOC. DATE: 82/11/17 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Informs of intention to install seismically mounted debris screens for containment purge supply & exhaust valves at next refueling outage for Unit 3 & next refueling outage following steam generator repair outage for Unit 4.


DISTRIBUTION CODE: A034S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1
 TITLE: OR Submittal: Containment Purging

NOTES:

	RECIPIENT ID CODE/NAME		COPIES			RECIPIENT ID CODE/NAME		COPIES	
			LTTR	ENCL				LTTR	ENCL
	NRR ORB1 BC 01		7	7					
INTERNAL:	NRR FIELDS, M 12		1	1		NRR REEVES, E 14		1	1
	NRR/DE/EQB 09		1	1		NRR/DSI/AEB		1	1
	<u>REG FILE</u> 04		1	1		RGN2		1	1
EXTERNAL:	ACRS 13		6	6		LPDR 03		1	1
	NRC PDR 02		1	1		NSIC 05		1	1
	NTIS		1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23


AAL



1. The first step is to identify the problem. This involves understanding the symptoms and the context in which they are occurring.

-----:3a1a -- 4041 -- 915:031711 8 4990 0000 : 1001 001111 0110 0110
0010 0010 0010 0010 : 0010 0010 0010 0010

[illegible]



November 17, 1982
L-82-512

Office of Nuclear Reactor Regulation
Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch #1
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Varga:

Re: Turkey Point Units 3 & 4
Docket No. 50-250 & 50-251
Containment Purge

Florida Power & Light Company has re-evaluated its position concerning the installation of debris screens to protect the containment purge supply and exhaust valves for Turkey Point Units 3 and 4. It is our intention to install one seismically mounted debris screen for each pair of valves in each unit. Our intended schedule for installing the screen is the next scheduled refueling outage for Turkey Point Unit 3 and the next refueling outage following the current steam generator repair outage for Turkey Point Unit 4.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Robert E. Uhrig".

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PKG/cab

cc: J. P. O'Reilly, Region II
Harold F. Reis, Esquire

A034

8211230253 821117
PDR ADOCK 05000250
P PDR

