



JUN 13 1985

L-85-231

Dr. J. Nelson Grace  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, N.W.  
Suite 2900  
Atlanta, GA 30323

Dear Dr. Grace:

Re: Turkey Point Units 3 & 4  
Docket No. 50-250 and 50-251  
Inspection Report 85-09

Our response to the above referenced Inspection Report has required more involvement than originally anticipated. Our response to Finding 1 (documented procedural requirements for thread engagement) requires additional time to allow proper internal coordination and review. For Findings 2 (accumulator pressure relief valves being included in the Pump & Valve Test Program), our engineering department has initiated an evaluation to help us resolve this issue. That evaluation is scheduled to be completed by mid to late June. We therefore require additional time to coordinate our response to your report.

Per conversation with your staff, we understand that submitting our response by July 1, 1985 is acceptable and intend on submitting it then.

Very truly yours,

*for J. W. Williams, Jr.*  
J. W. Williams, Jr.  
Group Vice President  
Nuclear Energy

JWW/SAV/bc

cc: Harold F. Reis, Esquire

8507110353 850613  
PDR ADDCK 05000250  
Q PDR

IEO1 1/0

PEOPLE...SERVING PEOPLE

