

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8709110279 DOC. DATE: 87/09/08 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 WOODY, C. D. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 860930 & 1001, scheduler exemptions for
 safe shutdown mods expired due to large number of mods being
 performed. Plant continues to implement compensatory measures
 as applicable. Rept will be updated on 30-day basis.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1		PD2-2 PD	1 1
	McDONALD, D	1 1			
INTERNAL:	ACRS MICHELSON	1 1		ACRS MOELLER	2 2
	AEOD/DOA	1 1		AEOD/DSP/NAS	1 1
	AEOD/DSP/ROAB	2 2		AEOD/DSP/TPAB	1 1
	DEDRO	1 1		NRR/DEST/ADS	1 0
	NRR/DEST/CEB	1 1		NRR/DEST/ELB	1 1
	NRR/DEST/ICSB	1 1		NRR/DEST/MEB	1 1
	NRR/DEST/MTB	1 1		NRR/DEST/PSB	1 1
	NRR/DEST/RSB	1 1		NRR/DEST/SGB	1 1
	NRR/DLPQ/HFB	1 1		NRR/DLPQ/QAB	1 1
	NRR/DOEA/EAB	1 1		NRR/DREP/RAB	1 1
	NRR/DREP/RPB	2 2		NRR/PMAS/ILRB	1 1
	REG FILE 02	1 1		RES DEPY GI	1 1
	RES TELFORD, J	1 1		RES/DE/EIB	1 1
	RGN2 FILE 01	1 1			
EXTERNAL:	EG&G GROH, M	5 5		H ST LOBBY WARD	1 1
	LPDR	1 1		NRC PDR	1 1
	NSIC HARRIS, J	1 1		NSIC MAYS, G	1 1



SEPTEMBER 08 1987

L-87-372

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3 the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,


C. O. Woody
Group Vice President
Nuclear Energy

COW/SDF/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8709110279 870908
PDR ADOCK 05000250
S PDR

IE22
11

SPECIAL REPORT

SEPTEMBER 8, 1987

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

Purpose:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 states that certain other conditions also require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC. This report will be updated on a 30 day basis.

Event:

The plant has been and is continuing to implement modifications in accordance with Appendix R Alternate Shutdown requirements and other unrelated requirements. The schedular exemptions for the Safe Shutdown modifications, which outlined the alternative compensatory measures to be taken when a barrier is breached, expired on September 30, 1986, and on October 1, 1986. Upon the expiration of the exemptions, the compensatory measures as described in Attachment 1 of our letter L-85-386 (dated October 11, 1985), are continuing to be in place until the Safe Shutdown modifications are complete. Impairments incurred during Alternate Shutdown modifications are governed by the Technical Specifications or the exemptions, as applicable. Other impairments are governed strictly by the Technical Specifications.

Cause and Corrective Actions:

The major cause of the impairments is the large number of modifications being performed. Due to the large volume of work being performed, the plant is reporting the impairments in this one report, rather than on a case-by-case basis. The impairments reported this month are either open or closed at the present time, but were open in excess of the time period permitted without requiring NRC notification (see lists on page 3).

This report includes impairments which were:

- 1) opened prior to September and
- 2) stayed open for longer than the time permitted by the Technical Specifications, and
- 3) are either still open or were closed prior to September.

The plant continues to implement the compensatory measures as applicable.

**FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE JULY REPORT WHICH
HAVE BEEN OPEN FOR LONGER THAN TECH SPEC LIMITS**

Imp#	Description	Open	Closed
1150	Water Suppression System	08/06/87	
1168	PTS 41 & 42	08/18/87	
1046	Fire Door 106.2	07/24/87	08/11/87
1160	Conduit Seal	08/14/87	08/26/87
1161	Conduit Seal	08/14/87	08/26/87
87-0326	Fire Detection System	07/30/87	08/14/87
87-0323	Penetration Seal 097F-E014	07/30/87	
87-0324	Penetration Seal 106F-E368	07/30/87	
87-0325	R. P. A384-30-0181-3271	07/30/87	

**FIRE PROTECTION SYSTEM IMPAIRMENTS CLOSED SINCE JULY REPORT BUT
WERE OPEN FOR LONGER THAN TECH SPEC LIMITS**

Imp#	Description	Open	Closed
1034	Fire Damper 72A	01/28/87	08/11/87
1071	Fire Barrier Thermal Lagging	04/02/87	08/25/87
87-0251	Penetration Seal 70C-E007	05/05/87	08/14/87
87-0314	Raceway Protection	07/07/87	08/17/87
87-0156	Conduit Seal 106E-E015	03/14/87	07/10/87
87-0290	Penetration Seal 30F-M003	06/12/87	07/10/87
87-0291	Penetration Seal 30F-M046	06/12/87	07/10/87
87-0293	Fire Door Elec. Penet. 019.1	06/15/87	07/31/87
87-0300	Penetration Seal 28E-H001	06/09/87	07/10/87
1089	Fire Door 106.1	05/08/87	07/13/87
1115	Fire Barrier	06/21/87	07/09/87
87-0154	Conduit Seal 70E-E008	03/14/87	07/24/87
87-0155	Conduit Seal 71E-E007	03/14/87	07/24/87
87-0156	Conduit Seal 106E-E015	03/14/87	07/10/87
87-0157	Conduit Seal 1084E-E003	03/14/87	07/10/87

The following impairments were incurred prior to August 1987, however they are being included in this report as they were not reported previously.

Imp#	Description	Open	Closed
87-0316	Penetration Seal 067N-E003	07/16/87	07/24/87
87-0317	Penetration Seal 068E-E002	07/16/87	07/24/87