

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8710130247 DOC. DATE: 87/10/06 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHORITY AFFILIATION
 WOODY, C. O. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 860930 & 1001, scheduler exemptions for safe shutdown mods expired resulting in fire protection impairments. Caused by number of mods being performed. Compensatory measures described in 851011 ltr in place.

DISTRIBUTION CODE: A006D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: OR/Licensing Submittal: Fire Protection

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	5 5
	McDONALD, D	1 1		
INTERNAL:	ARM/DAF/LFMB	1 0	NRR WERMEIL, J	1 0
	NRR/DEST/ADS	1 1	NRR/DEST/PSB	1 1
	OGC/HDS2	1 0	<u>REG FILE</u> 01	1 1
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 12

YAU ...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...



OCTOBER 06 1987

L-87-403

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3 the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,


C. O. Woody
Group Vice President
Nuclear Energy

COW/TCG/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8710130247 871006
PDR ADDCK 05000250
S PDR

Acob
1/1

100

100

100

100

100

100

100

100

100

100

100

SPECIAL REPORT

OCTOBER 6, 1987

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

Purpose:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 states that certain other conditions also require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC. This report will be updated on a 30 day basis.

Event:

The plant has been and is continuing to implement modifications in accordance with Appendix R Alternate Shutdown requirements and other unrelated requirements. The schedular exemptions for the Safe Shutdown modifications, which outlined the alternative compensatory measures to be taken when a barrier is breached, expired on September 30, 1986, and on October 1, 1986. Upon the expiration of the exemptions, the compensatory measures as described in Attachment 1 of our letter L-85-386 (dated October 11, 1985), are continuing to be in place until the Safe Shutdown modifications are complete. Impairments incurred during Alternate Shutdown modifications are governed by the Technical Specifications or the exemptions, as applicable. Other impairments are governed strictly by the Technical Specifications.

Cause and Corrective Actions:

The major cause of the impairments is the number of modifications being performed. Due to the volume of work being performed, the plant is reporting the impairments in this one report, rather than on a case-by-case basis. The impairments reported this month are either open or closed at the present time, but were open in excess of the time period permitted without requiring NRC notification.

This report includes impairments which were:

- 1) opened prior to October and
- 2) stayed open for longer than the time permitted by the Technical Specifications, and
- 3) are either still open or were closed prior to October.

The plant continues to implement the compensatory measures as applicable.



**FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE AUGUST REPORT WHICH
HAVE BEEN OPEN FOR LONGER THAN TECH SPEC LIMITS**

Imp#	Description	Open	Closed
87-0330	Raceway Protection	09/15/87	
87-0331	Penetration Seal 98K-E001	09/22/87	
87-0332	Penetration Seal 098N-E035	09/23/87	
87-0328	Fire Barrier 72-S	09/01/87	09/14/87

**FIRE PROTECTION SYSTEM IMPAIRMENTS CLOSED SINCE AUGUST REPORT BUT
WERE OPEN FOR LONGER THAN TECH SPEC LIMITS**

Imp#	Description	Open	Closed
1004	Penetration Seal Zone 39	10/17/86	09/30/87
1176	Water Suppression System	08/09/87	09/19/87
1146	Fire Door 106.2	07/24/87	08/11/87
87-0308	Raceway Protection	06/30/87	09/03/87
87-0327	Penetration Seal 106F-3-69	07/31/87	09/04/87
87-0323	Penetration Seal 097F-E014	07/30/87	09/04/87

The following impairment was incurred prior to August 1987, however they are being included in this report as they were not reported previously.

Imp#	Description	Open	Closed
1173	Fire Detection System	08/24/87	