

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8802120260 DOC. DATE: 88/02/08 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHORITY AFFILIATION  
 WOODY, C. O. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards original corrective action commitment re violations noted in Insp Repts 50-250/87-25 & 50-251/87-29, current status & interim actions to justify extension request. Withheld.

DISTRIBUTION CODE: IE02D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1  
 TITLE: Safeguards Inspection Rpt/NOV Response (50 DKT)-Contains SGI or 2.790

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 0
	EDISON, G	1 0		
INTERNAL:	AEOD/DOA	1 0	NRR/DLPQ/PEB	1 1
	NRR/DRIS/SGB	1 1	NRR/DRIS/SIB	1 1
	NRR/PMAS/ILRB	1 0	<u>REG FILE</u> 02	1 1
	RGN2 FILE 01	1 1		
INTERNAL:	LPDR	1 0	NRC PDR	1 0
	NSIC	1 0		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 13 ENCL 4



**FPL**

FEBRUARY 8 1988

L-88-62  
10 CFR 2.201

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Request for Extension to Corrective Actions  
Inspection Report 87-25 and 87-29 (EA 87-98)

Florida Power & Light Company issued its response to the referenced notice of violation in our letter L-87-362 dated August 26, 1987.

The status of commitment 4B made in our response to Finding B was discussed with NRC Region II security inspectors during a December 1987 inspection. A follow-up conversation was then held with members of your Region II Staff on February 4, 1988 and request for extension was discussed.

The enclosure contains details as to the original corrective action commitment, current status, and interim actions currently in place to justify this request for extension.

The enclosed material contains safeguards information as defined by 10 CFR 73.21, its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, pursuant to 10 CFR 2.790(a)(3), the enclosure is exempt from public disclosure.

Very truly yours,

*C. O. Woody*  
C. O. Woody  
Executive Vice President

COW/SDF/gp  
Attachment

8802120260 880208  
PDR ADDCK 05000250  
Q PDR

cc: Dr. J. Nelson Grace, Regional Administrator,  
Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

SDF/008.SG

ENCLOSURE CONTAINS SAFEGUARDS  
INFORMATION. UPON SEPARATION,  
THIS PAGE IS DECONTROLLED.

\*  
IE02  
11

SAFEGUARDS INFORMATION

an FPL Group company

11



THIS DOCUMENT HAS BEEN DETERMINED TO  
CONTAIN UNCLASSIFIED INFORMATION BY

*S.D. Ferrell - LICENSING ENGR*

DATE 12-13-88 BY SP-10/DAW,  
REASON FOR DECLASSIFICATION OF  
DOCUMENT OR DETERMINATION 2-8-88

U.S. DEPARTMENT OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION

SECTION 552, TITLE 5, U.S. CODE  
AND 10 C.F.R. 17.121, VOL. 100, SUBJECT  
TO CIVIL AND CRIMINAL SANCTIONS.

#### ATTACHMENT

Re: Turkey Points Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Request for Extension to Corrective Action  
Inspection Report 87-25 and 87-29 (EA 87-98)

#### CORRECTIVE ACTION:

A permanent vehicle entrapment area will be constructed at the south security gate.

#### CORRECTIVE STATUS:

Design for entrapment was issued mid-December with material procurement currently underway. Critical path appears to be the delivery of selected material (i.e., the motorized gates) which are required to complete construction.

#### INTERIM ACTIONS:

As stated in our response to this finding, Item 4A committed to providing a temporary isolation area for vehicle searches outside the south security gate. This area will remain in place until the completion of the permanent entrapment as committed previously. Additionally, modifications have been made in the vehicle traffic flow paths in the area of the south security gate which have reduced the vehicle and personnel congestion previously experienced in this area.

#### REQUESTED NEW DATE:

May 1, 1988

UNCLASSIFIED INFORMATION