

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8811080017 DOC. DATE: 88/11/01 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 CONWAY, W.F. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Provides supplemental response to NRC Bulletin 88-004 re potential safety-related pump loss.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: OR Submittal: General Distribution

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PD2-2 LA	1	0	PD2-2 PD	2	2
	EDISON, G	1	1			
INTERNAL:	ARM/DAF/LFMB	1	0	NRR/DEST/ADS 7E	1	1
	NRR/DEST/CEB 8H	1	1	NRR/DEST/ESB 8D	1	1
	NRR/DEST/MTB 9H	1	1	NRR/DEST/RSB 8E	1	1
	NRR/DOEA/TSB 11	1	1	NRR/PMAS/ILRB12	1	1
	NUDOCS-ABSTRACT	1	1	OGC/HDS2	1	0
	<u>REG FILE 01</u>	1	1	RES/DSIR/EIB	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 19 ENCL 16

R  
I  
D  
S  
/  
A  
D  
D  
S

A10 1/2





NOVEMBER 1 1988

L-88-475

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Gentlemen:

Re: Turkey Point Unit Nos. 3 and 4  
Docket Nos. 50-250 and 50-251  
Supplemental Response to NRC Bulletin  
Potential Safety-Related Pump Loss

Florida Power & Light letter L-88-295 dated July 18, 1988 provided a partial response to NRC Bulletin 88-4 "Potential Safety-Related Pump Loss for Turkey Point". To complete the remaining portion of this bulletin, the results of hydraulic instability calculations are required from the individual safety-related pump manufacturers. Due to numerous requests for similar information from other utilities, the responses from the pump manufacturers originally requested for September 1, 1988, have been delayed. It is anticipated that FPL will receive the results of these calculations and the corresponding miniflow recirculation requirements by April 1, 1989. FPL will then develop a plan and schedule for the resolution of any concerns within 30 days of receipt of the miniflow recirculation requirements. The results and schedule for resolution of any hydraulic instability concerns will be provided by May 29, 1989.

If you have any questions or comments, please contact us.

Very truly yours,

W. F. Conway  
Senior Vice President - Nuclear

WFC/SDF/jr

cc: Malcolm L. Ernst, Acting Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

8811080017 881101  
PDR ADDCK 05000250  
Q PNU

an FPL Group company

