

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)


ACCESSION NBR:8303150318 DOC DATE: 83/03/10 NOTARIZED: NO DOCKET #
 FACIL:50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP NAME RECIPIENT AFFILIATION
 EISENHUT, D.G. Division of Licensing

SUBJECT: Forwards "Steam Generator Repair Program, Radiological
 Progress Rept 2 for 821203-830202."

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+31
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	NRR ORB1 BC	01	7	7					
INTERNAL:	ELD/HDS4		1	0	NRR/DE/MTEB		1	1	
	NRR/DL DIR		1	1	NRR/DL/ORAB		1	0	
	NRR/DSI/METB		1	1	NRR/DSI/RAB		1	1	
	<u>REG FILE</u>	04	1	1	RGN2		1	1	
EXTERNAL:	ACRS	09	6	6	LPDR	03	1	1	
	NRC PDR	02	1	1	NSIC	05	1	1	
	NTIS		1	1					



March 10, 1983
L-83-136

Office of Nuclear Reactor Regulation
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Eisenhut:

Re: Turkey Point Unit 4
Docket No. 50-251
Steam Generator Repair Program
Radiological Progress Report No. 2

Please find attached our Radiological Progress Report No. 2 for the Steam Generator Repair Program, as required by Section 3.H.2(c) of DPR-41.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/JEM/js

Attachment

cc: Mr. James P. O'Reilly, Region II
Mr. Harold F. Reis, Esquire
PNS-83-LI-170-1

8303150318 830310
PDR ADCK 05000251
R PDR

Accol