

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8310110138 DOC. DATE: 83/10/03 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 UHRIG, R.E. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 EISENHUT, D.G. Division of Licensing
 O'REILLY, J.P. Region 2, Office of Director

SUBJECT: Requests approval to use 1980 Edition & Addenda through
 Winter 1981 Addenda of ASME Section XI Code, per 10CFR50.55a
 (g)(4)(iv), to extend inservice insp interval due to lengthy
 steam generator repair outages.

DISTRIBUTION CODE: A047S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: Inservice Inspection/Testing

NOTES:


	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	NRR ORB1 BC 01	7		
INTERNAL:	ELD/HDS4	1	NRR/DE/MEB	15
	NRR/DE/MTEB 14	1	REG FILE	04
	RGN2	1		
EXTERNAL:	ACRS 16	10	LPDR 03	1
	NRC PDR 02	1	NSIC 05	1
	NTIS	1		

TOTAL NUMBER OF COPIES REQUIRED: LTR 26 ENCL 0/25

[illegible]

11

[illegible]



October 3, 1983
L-83-505

Office of Nuclear Reactor Regulation
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250 & 50-251
Request to Update to Later Endorsed Code Requirements

Reference: FPL letter (L-79-261) dated September 18, 1979,
Subject: Inservice Inspection Program

Pursuant to 10 CFR 50.55a(g)(4)(iv), Florida Power & Light Company requests approval to use the 1980 Edition and Addenda through the Winter 1981 Addenda of the ASME Section XI Code pertaining to the following:

- 1) Use the System Hydro (and Temperature) Pressure tests required by IWA-5000, IWC-5000 at the end of the Inspection Interval.

Basis: The later Code provides more definitive and interpretive information consistent with the system hydro test boundaries; including, pressures and temperatures, test conditions, fracture prevention and system overpressurization. Compliance with the later Code further provides additional assurance that the Florida Power & Light Company's test program is in compliance with the regulations.

- 2) Extend the inspection interval (required by IWA-2400, IWB-2400, IWC-2400 and IWD-2400) due to the lengthy steam generator repair outages on both units.
 - o Unit 3 - The last 40-month period of the current 120-month inspection interval (August 14, 1979 extended to March 1, 1984).
 - o Unit 4 - The last 80-month period of the current 120 month inspection interval (January 7, 1977 extended to March 1, 1984).

8310110138 831003
PDR ADOCK 05000250
Q PDR



Av47
10

Page 2
Office of Nuclear Reactor Regulation
Mr. Darrell G. Eisenhut, Director

Basis: IIWA-2400(c). The inspection interval may be extended by one year, in addition to the period equivalent to the outage that the unit is out of service continuously for six months or more. The steam generator repair outages were:

◦ Unit 3 - From February 2, 1981 to April 10, 1982.

◦ Unit 4 - From October 9, 1982 to May 16, 1983.

Florida Power & Light Company's Inservice Inspection program is based on the 1974 Edition, including Addenda through Summer 1975 of Section XI of the ASME Code.

Should you or your staff have any questions on this request, please contact us.

Very truly yours,



Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/cab

Attachment

cc: J. P. O'Reilly, Region II
Harold F. Reis, Esquire

