

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8311070467 DOC. DATE: 83/10/31 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 WILLIAMS, J.W. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Informs that util has modified EOP 20001 re LOCA. NRC should
 finalize review & issue suppl to safety evaluation re ECCS
 valves & single failure concerns.


DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES:

| RECIPIENT ID CODE/NAME | | COPIES LTTR ENCL | | RECIPIENT ID CODE/NAME | | COPIES LTTR ENCL | |
|---------------------------|--------------|---------------------|---|---------------------------|-------------|---------------------|---|
| NRR ORB1 BC 01 | | 7 | 1 | | | | |
| INTERNAL: | ELD/HDS4 | 1 | 0 | | NRR/DE/MTEB | 1 | 1 |
| | NRR/DL DIR | 1 | 1 | | NRR/DL/ORAB | 1 | 0 |
| | NRR/DSI/METB | 1 | 1 | | NRR/DSI/RAB | 1 | 1 |
| | REG FILE 04 | 1 | 1 | | RGN2 | 1 | 1 |
| EXTERNAL: | ACRS 09 | 6 | 6 | | LPDR 03 | 1 | 1 |
| | NRC PDR 02 | 1 | 1 | | NSIC 05 | 1 | 1 |
| | NTIS | 1 | 1 | | | | |

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 23

| EXTRACT | | EXTRACT | | EXTRACT | | EXTRACT | |
|---------|------|---------|------|---------|------|---------|------|
| DATE | TIME | DATE | TIME | DATE | TIME | DATE | TIME |
| 1 | 1 | 1 | 1 | 1 | 1 | 1 | 1 |
| 2 | 1 | 2 | 1 | 2 | 1 | 2 | 1 |
| 3 | 1 | 3 | 1 | 3 | 1 | 3 | 1 |
| 4 | 1 | 4 | 1 | 4 | 1 | 4 | 1 |
| 5 | 1 | 5 | 1 | 5 | 1 | 5 | 1 |
| 6 | 1 | 6 | 1 | 6 | 1 | 6 | 1 |
| 7 | 1 | 7 | 1 | 7 | 1 | 7 | 1 |
| 8 | 1 | 8 | 1 | 8 | 1 | 8 | 1 |
| 9 | 1 | 9 | 1 | 9 | 1 | 9 | 1 |
| 10 | 1 | 10 | 1 | 10 | 1 | 10 | 1 |



October 31, 1983
L-83-533

Office of Nuclear Reactor Regulation
Attention: Mr. S. A. Varga, Chief
Operating Reactors Branch #1
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Varga:


Re: Turkey Point Units 3 & 4
Docket Nos. 50-250 and 50-251
Emergency Core Cooling System Valves
Single Failure Concerns

Your letter dated August 29, 1983 stated that upon receipt of our commitment to change the LOCA procedure to address the concern expressed in that letter, you would finalize your review and issue a supplement to the safety evaluation on that subject.

FPL has modified EOP 2000I to reflect the concerns expressed in your letter.

We understand the above, to have been the only outstanding concern on this issue. Please contact us should you have any further questions.

Yours very truly,


J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/SAV/cab

8311070467 831031
PDR ADOCK 05000250
F PDR

A001
1/0

