

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8706040075 DOC. DATE: 87/05/29 NOTARIZED: NO DOCKET #
 CIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME . AUTHDR AFFILIATION
 WOODY, C. O. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to violations noted in Insp Repts 50-250/87-15 &
 50-251/87-15. Corrective actions: new bulletin board placed in
 nuclear admin bldg that will contain posting requirements
 per 10CFR19 & other applicable regulations.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
	LTTR	ENCL		LTTR	ENCL
PD2-2 LA	1	0	PD2-2 PD	1	1
McDONALD, D	2	2			
INTERNAL: AEOD	1	1	DEDRO	1	1
ENF LIEBERMAN	1	1	NRR ROE, M. L	1	1
NRR/DOEA DIR	1	1	NRR/DREP/EPB	1	1
NRR/DREP/RPB	2	2	NRR/DRIS DIR	1	1
NRR/PMAS/ILRB	1	1	OGC/HDS2	1	1
REG FILE	1	1	RES DEPY GI	1	1
RGN2 FILE 01	1	1			
EXTERNAL: LPDR	1	1	NRC PDR	1	1
NSIC	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 21 ENCL 20





MAY 20 1987
L-87-228

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Inspection Report 87-15

Florida Power & Light has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,


C. O. Woody
Group Vice President
Nuclear Energy

COW/SDF/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspection, USNRC, Turkey Point Plant

8706040075 870529
PDR ADOCK 05000250
Q PDR

SDF1/020/1

an FPL Group company

1E01
11

ATTACHMENT

RE: TURKEY POINT UNITS 3 AND 4
DOCKET NO. 50-250, 50-251
IE INSPECTION REPORT 250-87-15 & 251-87-15

FINDING:

10 CFR 19.11(a)(4) requires each licensee to post current copies of any Notice of Violation involving radiological working conditions and any response from the licensee. This section further requires that these documents are to be posted within two working days after receipt of the documents from the Commission and shall remain posted for a minimum of five working days or until action correcting the violation has been completed, whichever is later.

Contrary to the above, the licensee failed to post the Notice of Violation involving radiological working conditions transmitted to the licensee in Inspection Report No. 50-250, 50-251/86-36, dated November 26, 1986, and the licensee's response to that Notice. Actions correcting the violation were not completed at the time of the inspection.

RESPONSE:

- 1) FPL concurs with the finding.
- 2) The reason for the finding was that when the responsibilities for handling inspection reports were transferred to the Technical Department from the Quality Control Department, the posting requirements were inadvertently omitted.
- 3) The final corrective actions associated with Inspection Report No. 50-250, 50-251/86-36 were completed on April 30, 1987 and posting of these items are no longer required.)
- 4) A new bulletin board has been placed in the nuclear administration building that will contain the posting requirements as specified by 10 CFR CFR Part 19 and other applicable regulations as is practicable. 10 CFR 19.11(b) states that if posting of a document specified in this part is not practicable, the licensee may post a notice which describes the document and states where it may be examined. Therefore, a notice will be placed on various bulletin boards around the plant informing employees of the new bulletin board, the documents available for their review and the location of such documents.
- 5) a) Full compliance for item 3 above was achieved on April 30, 1987.
b) Full compliance for item 4 above will be achieved by June 1, 1987..

