

REGULARY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712090252 DOC. DATE: 87/12/04 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4; Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 WOODY, C. O. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 872104, non-functional fire barrier
 penetration not returned within 7 days. Continues
 implementing plant mods. Impairments caused by number of mods
 being performed. Reporting impairments monthly.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1		PD2-2 PD	1 1
	McDONALD, D	1 1			
INTERNAL:	ACRS MICHELSON	1 1		ACRS MOELLER	2 2
	AEOD/DOA	1 1		AEOD/DSP/NAS	1 1
	AEOD/DSP/ROAB	2 2		AEOD/DSP/TPAB	1 1
	ARM/DCTS/DAB	1 1		DEDRO	1 1
	NRR/DEST/ADS	1 0		NRR/DEST/CEB	1 1
	NRR/DEST/ELB	1 1		NRR/DEST/ICSB	1 1
	NRR/DEST/MEB	1 1		NRR/DEST/MTB	1 1
	NRR/DEST/PSB	1 1		NRR/DEST/RSB	1 1
	NRR/DEST/SGB	1 1		NRR/DLPQ/HFB	1 1
	NRR/DLPQ/QAB	1 1		NRR/DOEA/EAB	1 1
	NRR/DREP/RAB	1 1		NRR/DREP/RPB	2 2
	NRR/DRIS/SIB	1 1		NRR/PMAS/ILRB	1 1
	REG FILE 02	1 1		RES DEPY GI	1 1
	RES TELFORD, J	1 1		RES/DE/EIB	1 1
	RGN2 FILE 01	1 1			
EXTERNAL:	EG&G GROH, M	5 5		FORD BLDG HOY, A	1 1
	H ST LOBBY WARD	1 1		LPDR	1 1
	NRC PDR	1 1		NSIC HARRIS, J	1 1
	NSIC MAYS, G	1 1			



DECEMBER 04 1987

L-87-501

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3 the attached
Special Report is provided for your information.

Should there be any questions on this information, please
contact us.

Very truly yours,


C. O. Woody
for Executive Vice President

COW/SDF/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator,
Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8712090252 871204
PDR ADDCK 05000250
S PDR

SDF/009.BFB

LE22
11

SPECIAL REPORT

DECEMBER 4, 1987

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

Purpose:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC. This report is being updated on a 30 day basis.

Event:

Turkey Point has been and is continuing to implement plant modifications. Fire Protection System (FPS) impairments are, at times, incurred during the performance of these modifications. Occasionally, certain FPS features fail due to random component failure.

Cause and Corrective Actions:

The primary cause of the impairments is the number of modifications being performed. Many of these modifications require the impairment of certain FPS features for their completion. The secondary cause for the impairments is FPS equipment malfunction. Because Turkey Point incurs a variable number of impairments, the plant is reporting the impairments in a monthly report, rather than on a case-by-case basis. The impairments reported this month may be either open or closed at the present time, however they were open in excess of the Technical Specification permitted time limit.

This report includes impairments not reported previously which were: .

- 1) opened prior to December and
- 2) stayed open for longer than the time permitted by the Technical Specifications, and
- 3) are either still open or were closed prior to December. The closed impairments have been reported at the time opened, unless noted otherwise.

The plant continues to implement the compensatory measures as applicable.

**FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE OCTOBER REPORT WHICH
HAVE BEEN OPEN FOR LONGER THAN TECH SPEC LIMITS**

Imp#	Desrription	Open	Closed
1232	Fire Detection	11/05/87	
1293	Conduit	11/17/87	

**FIRE PROTECTION SYSTEM IMPAIRMENTS CLOSED SINCE OCTOBER REPORT BUT
WERE OPEN FOR LONGER THAN TECH SPEC LIMITS**

Imp#	Description	Open	Closed
1215	Alarm Point 26	10/08/87	11/02/87
1216	Alarm Point 27	10/08/87	11/02/87
1221	Fire Door 41-1	10/20/87	11/07/87
87-0335	Pen. Seal 104 E2 CRN-C-1826	10/16/87	11/09/87

The following impairment was incurred prior to November 1987, however it is being included in this report as it was not reported previously.

Imp#	Description	Open	Closed
1222	Detection	10/20/87	