

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8810250439 DOC.DATE: 88/10/24 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH.NAME AUTHOR AFFILIATION
 CONWAY,W.F. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept:on 380822 fire protection impairment numbers
 1884 & 1885 issued for fire barrier & fire door.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD2-2 LA		1	1		PD2-2 PD		1	1
	EDISON,G		1	1					
INTERNAL:	ACRS MICHELSON		1	1		ACRS MOELLER		2	2
	ACRS WYLIE		1	1		AEOD/DOA		1	1
	AEOD/DSP/TPAB		1	1		ARM/DCTS/DAB		1	1
	DEDRO		1	1		NRR/DEST/ADS 7E		1	0
	NRR/DEST/CEB 8H		1	1		NRR/DEST/ESB 8D		1	1
	NRR/DEST/ICSB 7		1	1		NRR/DEST/MEB 9H		1	1
	NRR/DEST/MTB 9H		1	1		NRR/DEST/PSB 8D		1	1
	NRR/DEST/RSB 8E		1	1		NRR/DEST/SGB 8D		1	1
	NRR/DLPQ/HFB 10		1	1		NRR/DLPQ/QAB 10		1	1
	NRR/DOEA/EAB 11		1	1		NRR/DREP/RAB 10		1	1
	NRR/DREP/RPB 10		2	2		NRR/DRIS/SIB 9A		1	1
	NUDOCS-ABSTRACT		1	1		REG-FILE 02		1	1
	RES/DSIR/EIB		1	1		RES/DSR DEPY		1	1
	RES/DSR/PRAB		1	1		RGN2 FILE 01		1	1
EXTERNAL:	EG&G WILLIAMS,S		4	4		FORD BLDG HOY,A		1	1
	H ST LOBBY WARD		1	1		LPDR		1	1
	NRC PDR		1	1		NSIC HARRIS,J		1	1
	NSIC MAYS,G		1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 42

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

1/A-2

FPL

OCTOBER 18 1988

L-88-451

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3 the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

W. F. Conway

W. F. Conway
Senior Vice President - Nuclear

WFC/RHF/gp

Attachment

cc: Malcolm L. Ernst, Acting Regional Administrator, Region II,
USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8810250439 881024
PDR ADDCK 05000250
S PNU

TE22
11

SPECIAL REPORT

OCTOBER 24, 1988

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

Purpose:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

Event:

Fire Protection Impairment Numbers 1884 and 1885 were issued for a barrier and a fire door which were required to be kept open in order to run welding leads, air hoses and electrical cords to support outage work being performed during the current Unit 4 refueling outage. The duration of the work which requires the above impairments is longer than the Technical Specification limit of 7 days, thus requiring the filing of this Special Report.

Please see the Attachment 1 for details.

Cause and Corrective Actions:

The cause of the impairments is the duration of the work required to replace one of the Component Cooling Water Heat Exchangers. 7 days is not sufficient to complete this effort.

The Fire Protection Group is evaluating the possibility of adding more access sleeves which could be used to pass leads and hoses between separate areas, without impairing any of the existing fire protection features. This evaluation will be completed by October 31, 1988, with implementation of any required modifications prior to the next refueling outage for each unit, as applicable.

Attachment 2 identifies impairments which are now closed but were previously reported as open.

The plant continues to implement the compensatory measures as applicable.

ATTACHMENT 1

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE 08/22/88 REPORT
WHICH HAVE BEEN OPEN FOR LONGER THAN TECH SPEC LIMITS

FPI #	FEATURE TYPE	OPENED	CLOSED
1884	BARRIER 047F	09/17/88	/ /
1885	DOOR 015-1	09/17/88	/ /

ATTACHMENT 2

FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY
NOT REPORTED CLOSED

FPI #	FEATURE TYPE	OPENED	CLOSED
1455	BARRIER DUCT IN ZONE 61	06/08/88	09/24/88
1471	BARRIER WIREWAY 3WW115	06/17/88	09/10/88
1484	BARRIER 16W	06/23/88	09/14/88
1541	BARRIER 101N	04/12/88	09/21/88
1555	DOOR 30-2	04/18/88	09/24/88
1556	DOOR 40-2	04/18/88	09/24/88
1618	BARRIER 040F	04/06/88	09/24/88
1695	PENETRATION 071-E001	06/23/88	09/16/88
1774	DETECTOR ALARM PANEL 4C284	07/12/88	08/23/88