

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8904180137 DOC. DATE: 89/04/04 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 CONWAY, W.F. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890228, 0302, 04 & 07, listed fire protection impairments opened.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL	
	PD2-2 LA		1	1		PD2-2 PD		1	1	
	EDISON, G		1	1						
INTERNAL:	ACRS MICHELSON		1	1		ACRS MOELLER		2	2	
	ACRS WYLIE		1	1		AEOD/DOA		1	1	
	AEOD/DSP/TPAB		1	1		AEOD/ROAB/DSP		2	2	
	DEDRO		1	1		IRM/DCTS/DAB		1	1	
	NRR/DEST/ADE 8H		1	1		NRR/DEST/ADS 7E		1	0	
	NRR/DEST/CEB 8H		1	1		NRR/DEST/ESB 8D		1	1	
	NRR/DEST/ICSB 7		1	1		NRR/DEST/MEB 9H		1	1	
	NRR/DEST/MTB 9H		1	1		NRR/DEST/PSB 8D		1	1	
	NRR/DEST/RSB 8E		1	1		NRR/DEST/SGB 8D		1	1	
	NRR/DLPQ/HFB 10		1	1		NRR/DLPQ/QAB 10		1	1	
	NRR/DOEA/EAB 11		1	1		NRR/DREP/RPB 10		2	2	
	NRR/DRIS/SIB 9A		1	1		NUDOCS-ABSTRACT		1	1	
	REG FILE 02		1	1		RES/DSIR/EIB		1	1	
	RES/DSR/PRAB		1	1		RGN2 FILE 01		1	1	
EXTERNAL:	EG&G WILLIAMS, S		4	4		FORD BLDG HOY, A		1	1	
	H ST LOBBY WARD		1	1		LPDR		1	1	
	NRC PDR		1	1		NSIC MAYS, G		1	1	
	NSIC MURPHY, G.A		1	1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 43

1/A-2

ect



APRIL 4 1989

L-89-130

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Special Report - Breached Fire Barriers and
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,


W. F. Conway
Senior Vice President - Nuclear

WFC/RHF/gp

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II,
USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8904180137 890404
PDR ADOCK 05000250
S PDC

IE22
1/1

SPECIAL REPORT

APRIL 4, 1989

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

Fire Protection Impairment(FPI) 2311, opened 02/28/89, is for Detector Alarm Point 29. FPIs 2313 thru 2318, opened 03/02/89, are for fire door breaches; FPI 2313 for 67-1, 2314 for 96-1, 2315 for 94-1, 2316 for 68-1, 2317 for 70-1 and 2318 for 71-1. FPIs 2319 and 2320, opened 03/04/89, were for fire doors 104-1 and 104-2. FPI 2326, opened 03/07/89, is on Flamastic Barrier T4J41 Port 2.

CAUSE AND CORRECTIVE ACTIONS:

FPI 2311 is on an alarm that will not reset; work is ongoing. FPIs 2313 thru 2318 are for fire doors found to be impaired by security grates fastened to the doors. New fire doors are being purchased. FPIs 2319 and 2320 were on fire doors left open for ventilation due to equipment breakdown. FPIs 2319 and 2320 were closed on 03/12/89. FPI 2326 is for flamastic removal due to I&C testing; work is ongoing. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

FPI 2182, reported as open in FPL letter L-89-012, dated January 9, 1989, was closed on March 13, 1989. FPI 2304, reported as open in FPL letter L-89-114, dated March 23, 1989, was closed on March 13, 1989.