

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8907120097 DOC. DATE: 89/07/03 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 WOODY, C.O. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890505, 0607 & 08, breached fire barriers & other fire protection sys impairments.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

## NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	IRM/DCTS/DAB	1 1
	NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/PEB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RES/DSR/PRAB	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	EG&G WILLIAMS, S	4 4	FORD BLDG HOY, A	1 1
	L ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC MAYS, G	1 1
	NSIC MURPHY, G. A	1 1		

## NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 42

1/A-2  
 [Signature]



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

JULY - 3 1989

L-89-234

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Special Report - Breached Fire Barriers and  
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

C. O. Woody  
Acting Senior Vice President - Nuclear

COW/JRH/cm

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

8907120097 890703  
PDR ADOCK 05000250  
S PDC

1522  
11

Attachment:

SPECIAL REPORT

**FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION**

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being submitted in order to notify the NRC.

EVENT:

Fire Protection Impairment (FPI) 2477, opened May 5, 1989, is for Detector Alarm Point 28. FPIs 2479 and 2480, opened May 5, 1989, and FPI 2491, opened June 7, 1989, are for Thermolag breeches. FPI 2500, opened June 8, 1989, is for Penetration 019W-E014.

CAUSE AND CORRECTIVE ACTIONS:

FPI 2477 is on an alarm point taken out of service for welding in fire zone 054; work is ongoing. FPIs 2479, 2480 and 2491, closed June 14, 1989, were for Thermolag removal to find the source of water intrusion into an electrical junction box. FPI 2500 is for an incorrect penetration seal and work is ongoing. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

<u>FPI No.</u>	<u>Reported Open</u>	<u>FPL Letter</u>	<u>Date Closed</u>
1332	04/07/88	L-88-163	06/05/89
1509	04/07/88	L-88-163	05/19/89
1535	05/06/88	L-88-203	05/19/89
1803	08/29/88	L-88-383	06/01/89
2185	01/09/89	L-89-012	05/15/89
2298	03/23/89	L-89-114	05/15/89
2300	03/23/89	L-89-114	05/25/89
2379	04/21/89	L-89-154	06/09/89
2380	04/21/89	L-89-154	06/09/89
2408	04/21/89	L-89-154	06/09/89
2387	04/21/89	L-89-154	06/08/89
2412	04/21/89	L-89-154	06/08/89
2407	04/21/89	L-89-154	06/12/89
2411	04/21/89	L-89-154	06/12/89
2395	04/21/89	L-89-154	06/16/89
2397	04/21/89	L-89-154	06/16/89
2458	05/31/89	L-89-195	06/01/89