

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8909220051 DOC. DATE: 89/09/15 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME: WOODY, C.O. AUTHOR AFFILIATION: Florida Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)

SUBJECT: Advises that requirements necessary for SPDS will be completed by end of outage scheduled to begin Jan 1991.

DISTRIBUTION CODE: A003D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR/Licensing Submittal: Suppl 1 to NUREG-0737 (Generic Ltr 82-33)

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
	PD2-2	LA	1	1		PD2-2	PD	7	1
	EDISON,	G	1	1					
INTERNAL:	NRR/DLPQ/HFB	10	1	1		NUDOCS-ABSTRACT		1	1
	OC/LFMB		1	0		REG FILE	01	1	1
	RES/DSIR/EIB		1	1					
EXTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 160

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S





SEPTEMBER 15 1989

L-89-323

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Task Action Plan Item I.D.2
Safety Parameter Display System
Generic Letter 89-06

Generic Letter (GL) 89-06, "Task Action Plan Item I.D.2, Safety Parameter Display System," dated April 12, 1989, requested that licensees provide certification of the status of implementation of the safety parameter display system (SPDS) at their facilities.

By letter dated August 14, 1989 (FPL letter No. L-89-296) Florida Power & Light Company (FPL) provided the required certification for Turkey Point Units 3 and 4. At that time, FPL had not completed an evaluation of human engineering discrepancies (HEDs) identified during the recent human factors evaluation of the Turkey Point SPDS, and could not provide a schedule for completion of the remaining actions required to meet NUREG-0737, Supplement 1 requirements for the SPDS.

Based on the review completed to date, the hardware and software modifications and additional training necessary to fully meet the NUREG 0737, Supplement 1 requirements for the SPDS, will be completed by the end of the dual unit outage currently scheduled to begin January 1991.

Should there be any questions, please contact us.

Very truly yours,

C. O. Woody
Acting Senior Vice President - Nuclear

COW/TCG/gp

Attachment

8909220051 890915
PDR ADOCK 05000250
P PDC

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

A003
10