

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8911220273 DOC. DATE: 89/11/16 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION  
 HARRIS, K.N. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: on 890929, 1003, 09-13, 18, 24, 27 & 30-31, listed  
 fire protection impairments reported.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	EDISON, G	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/PEB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NUDOCS-ABSTRACT	1 1	<u>REG FILE</u> 02	1 1
	RES/DSIR/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS, G	1 1	NSIC MURPHY, G.A	1 1
	NUDOCS FULL TXT	1 1		

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 38



L-89-404

NOV 16 1989

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555


Gentlemen:

Re: Turkey Point Unit 3 and 4  
Docket Nos. 50-250 and 50-251  
Special Report - Breached Fire Barriers and  
Other Fire Protection System Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information, please contact us.

Very truly yours,

  
K. N. Harris  
Vice President  
Turkey Point Plant Nuclear

KNH/DRP/rat

Attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

8911220273 891116  
PDR ADOCK 05000230  
S FDC

IE22  
11

## SPECIAL REPORT

### FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

#### PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

#### EVENT:

See attached list for Fire Protection Impairments (FPI) being reported..

#### CAUSE AND CORRECTIVE ACTIONS:

FPI's 2919 and 2952 were issued to Mechanical Maintenance for decon work activities. FPI 2920 was issued to Construction for the installation of conduits. The remaining impairments were issued as a result of Fire Protection surveillances currently being performed. The plant continues to implement the compensatory measures as applicable.

#### STATUS UPDATE:

See attached list for Fire Protection Impairments that were previously reported and are now closed.

### SPECIAL REPORT

Fire Protection System Impairments opened since last report which have been open for longer than Tech. Spec. limits.

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
2887	Door 58-5	09/29/89	
2888	Door 22-2	09/29/89	
2892	Penetration 106F-E070	10/03/89	
2893	Penetration 106F-E069	10/03/89	
2895	Penetration 106F-E151	10/03/89	
2909	Barrier 010W3	10/09/89	10/24/89
2910	Barrier 010E7	10/09/89	
2911	Barrier 018E8	10/09/89	
2916	Door 70-2	10/10/89	
2917	Door 98-2	10/10/89	
2919	Barrier 054F Plug	10/11/89	10/19/89
2920	Barrier 067N	10/11/89	10/18/89
2952	Barrier 058C Plug	10/24/89	

FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY  
NOT REPORTED CLOSED

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER &amp; DATE</u>
2595	Barrier 108A-N1	10/31/89	L-89-301 08/16/89
2671	Penetration 073S-M003	10/13/89	L-89-333 09/14/89
2722	Barrier 011C	10/30/89	L-89-333 09/14/89
2723	Barrier 024E	10/12/89	L-89-333 09/14/89
2728	Barrier 041C	10/30/89	L-89-333 09/14/89
2729	Barrier 011S	10/30/89	L-89-333 09/14/89
2734	Barrier 028N	10/27/89	L-89-364 10/13/89
2762	Barrier 004N	10/18/89	L-89-364 10/13/89
2798	Barrier 095F	10/27/89	L-89-364 10/13/89
2815	Penetration 106F-E168	10/06/89	L-89-375 10/30/89
2818	Barrier 098F	10/24/89	L-89-375 10/30/89
2819	Barrier 071E	10/24/89	L-89-375 10/30/89
2857	Barrier 058F	10/18/89	L-89-375 10/30/89