

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8912140041 DOC. DATE: 89/12/07 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC Bulletin 88-010 "Nonconforming Molded-Case Circuit Breakers."

DISTRIBUTION CODE: IE21D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Bulletin Response 88-10 - Nonconforming Molded Case Circuit Breakers.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-2 LA	1 0	PD2-2 PD	1 1
EDISON, G	1 1		
INTERNAL: AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
NRR DOEA/GCB 11	1 1	NRR GILL, A.S.	1 1
NRR GUILLEN, J	1 1	NRR POTAPOUS, U	1 1
NRR STONE, J.C.	1 1	NRR/DET/EMEB9H3	1 1
NRR/DOEA/OEAB11	1 1	NRR/DOEA/OGCB11	1 1
NRR/DREP/PEPB9D	1 1	NRR/DST 8E2	1 1
NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RGN2 FILE 01	1 1		
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 22



FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

L-89-438

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

DEC 07 1989

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
NRC Bulletin No. 88-10
Nonconforming Molded-Case Circuit Breakers

NRC Bulletin No. 88-10, "Nonconforming Molded-Case Circuit Breakers," issued November 22, 1988, and supplemented on August 3, 1989, requested that licensees take actions to provide reasonable assurance that molded-case circuit breakers (CBs), including CBs issued with motor controllers, purchased for use in safety-related applications without verifiable traceability to the CB manufacturer perform their safety function. Florida Power & Light Company provided a response to that bulletin for Turkey Point Units 3 and 4 by letters dated April 3, 1989 (FPL letter No. L-89-119) and November 7, 1989 (FPL letter No. L-89-394).

In our November 7, 1989 letter we identified four additional breakers which were found not to meet the criteria of NRC Bulletin 88-10. As stated in that letter, one breaker is in use in a nonsafety-related application. One breaker is in stores and its use has been restricted. Of the two remaining breakers, one was transferred to the Turkey Point fossil units. The location of the remaining breaker could not be verified, however, based on a review of stores' records, we have reasonable assurance that it was not released for use in a safety-related application.

Should you have any questions, please contact us.

Very truly yours,

K. N. Harris
Vice President
Turkey Point Nuclear Plant

KNH/TCG/gp

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

8912140041 891207
PDR ADDCK 05000250
Q PNU

an FPL Group company

IF21
1/0

AD-1