



NUCLEAR ENERGY ACCOUNTABILITY PROJECT

1202 Sioux Street • Jupiter, Florida 33458 • (407) 743-0770
Environmental Protection • Involvement • Litigation • Information

Executive Director of Operations
Nuclear Regulatory Commission
Washington, D.C. 20555

December 29, 1989

Re: Turkey Point Docket Nos: 50-250 and 50-251

Dear Sir:

Pursuant to 10 CFR Part 2 Appendix C Section V.B.7, and 10 CFR 2.206, we request action by the Nuclear Regulatory Commission (NRC) as delineated below:

Specific Request:

1. Immediately investigate the recent trips of the Turkey Point nuclear units 3 and 4 on or about Christmas to determine the root cause of the events.
2. If the NRC investigation reveals that the reactors tripped off-line due to poor maintenance practices or incorrect operations of the plants, then we request that an escalated civil penalty be imposed on the licensee.
3. If the investigation reveals that these reactor trips could have been prevented through correct maintenance practices or proper operation of the plant, then we request the immediate suspension of operating licenses DPR-31 and DPR-41.

Basis and Justification:

Reasonable assurance for the continued safe operation of the Turkey Point units 3 and 4 does not exist due to the loss of administrative controls and significant plant events resulting in reactor trips which evidence deficiencies in the licensee's programmatic overall maintenance of the physical plants.

Reasonable assurance for the continued safe operation of the Turkey Point units 3 and 4 does not exist because the licensee has failed to establish a satisfactory operator training program which meets the NRC criteria of such a program. Indeed, 50% of the licensee's reactor operators at Turkey Point failed a NRC administered requalification exam in March 1989.

In the interest for public safety and the protection of the environment as a whole, the NRC must not hesitate to act responsibly as they are mandated to ensure safe commercial nuclear power.

9001300489 900123
PDR ADOCK 05000250
H PDC

cc: Stewart Ebnetter, ADM.
USNRC Region II

Sincerely,

Thomas J. Saporito, Jr.
Executive Director, NEAP

ED 6 50 25

Docket No.
(10 C.F.R. § 2.206)

Mr. Thomas J. Saporito
1202 Sioux Street
Jupiter, Florida 33458

Dear Mr. Saporito:

This letter is to acknowledge receipt of your Petition dated December 29, 1989, requesting that the Commission take action with regard to Turkey Point Units 3 and 4. Specifically, you request that the NRC immediately investigate and determine the root cause of reactor trips which you allege occurred on or about December 25, 1989, at Turkey Point Units 3 and 4; impose an escalated civil penalty on the licensee if the investigation reveals that the reactors tripped off-line due to poor maintenance practices or incorrect operations of the plants; and immediately suspend the operating licenses for Turkey Point Units 3 and 4 if the investigation reveals that these reactor trips could have been prevented through correct maintenance practices and proper operation.

You allege, as bases for these requests, that reasonable assurance for the continued safe operation of Turkey Point Units 3 and 4 does not exist because of loss of administrative controls and significant plant events resulting in reactor trips, which evidence deficiencies in the overall maintenance of the plants; and because the licensee has failed to establish a satisfactory operator training program.

Your Petition has been referred to me pursuant to 10 C.F.R. § 2.206 of the Commission's regulations. As provided by section 2.206, action will be taken on your request within a reasonable time. However, a preliminary review of the concerns in your Petition does not indicate any need to take immediate action as you request because [STAFF: PROVIDE BASIS FOR THERE BEING NO NEED TO TAKE IMMEDIATE ACTION]. I have enclosed for your information a copy of the notice that is being filed with the Office of the Federal Register for publication.

Sincerely,

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

Enclosure: As stated

cc: Florida Power Corporation



[7590-01]

U.S. NUCLEAR REGULATORY COMMISSION

Docket No.

FLORIDA POWER CORPORATION

(Turkey Point Units 3 and 4)

(License No.)

RECIEPT OF PETITION FOR DIRECTOR'S DECISION UNDER 10 C.F.R. § 2.206

Notice is hereby given that by Petition dated Decmeber 29, 1989, Thomas J. Saporito, Jr., has requested that the Commission take action with regard to Turkey Point Units 3 and 4. Specifically, Mr. Saporito requests that the NRC immediately investigate and determine the root cause of reactor trips which he alleges occurred on or about December 25, 1989, at Turkey Point Units 3 and 4; impose an escalated civil penalty on the licensee if the investigation reveals that the reactors tripped off-line due to poor maintenance practices or incorrect operations of the plants; and immediately suspend the operating licenses for Turkey point Units 3 and 4 if the investigation reveals that these reactor trips could have been prevented through correct maintenance practices or proper operation.

Mr. Saporito alleges, as bases for these requests, that reasonable assurance for the continued safe operation of Turkey Point Units 3 and 4 does not exist because of loss of administrative controls and significant plant events resulting in reactor trips, which evidence deficiencies in the overall



maintenance of the plants; and because the licensee has failed to establish a satisfactory operator training program.

The request is being treated pursuant to 10 C.F.R. § 2.206 of the Commission's regulations. The request has been referred to the Director of Nuclear Reactor Regulation (NRR). As provided by section 2.206, appropriate action will be taken on this request within a reasonable time.

A copy of the Petition is available for inspection at the Commission's Public Document Room at 2120 L. Street, N.W., Washington, D.C. 20555

Dated Rockville, Maryland this _____ day of _____, 1990.

FOR THE NUCLEAR REGULATORY COMMISSION

Thomas E. Murley, Director
Office of Nuclear Reactor Regulation