

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM.

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9004260370 DOC.DATE: 90/04/17 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH.NAME AUTHOR AFFILIATION
 HARRIS,K.N. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept re breached fire barriers & other fire protection sys impairments.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1		PD2-2 PD	1 1
	EDISON,G	1 1			
INTERNAL:	ACNW	2 2		AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1		AEOD/ROAB/DSP	2 2
	DEDRO	1 1		NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1		NRR/DET/ESGB 8D	1 1
	NRR/DLPQ/LHFB11	1 1		NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1		NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1		NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1		NRR/DST/SRXB 8E	1 1
	REG FILE 02	1 1		RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1			
EXTERNAL:	EG&G STUART,V.A	4 4		L ST LOBBY WARD	1 1
	LPDR	1 1		NRC PDR	1 1
	NSIC MAYS,G	1 1		NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1			

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 35 ENCL 35

FA-2



APR 17 1990

L-90-139

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Special Report - Breached Fire Barriers
and Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information please contact us.

Very truly yours,

K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/DRP/TB/rat

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

2004260370 200417
FDR ADDCK 05000250
S PDC

IF22
11

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC. Please refer to the attached list of Fire Protection Impairments (FPI) being reported.

CAUSE AND CORRECTIVE ACTIONS:

FPI 3306 was issued for the repair of fireproofing impaired by the removal of conduits. FPI 3279 is for a penetration impaired to allow for the routing of new heat tracing. FPI's 3301 and 3302 are for firedoor discrepancies found during a scheduled surveillance. FPI's 3237, 3256 and 3283 were issued for support of planned maintenance work. The plant continues to implement the compensatory measures where applicable.

STATUS UPDATE:

Please refer to the attached list of Fire Protection Impairments that were previously reported and are now closed.



SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE LAST REPORT WHICH HAVE BEEN OPEN FOR LONGER THAN SEVEN DAYS.

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3237	Detector Alarm PT 21	03/03/90	03/20/90
3256	Detector 30-2	03/07/90	03/27/90
3279	Penetration 055N-M006	03/16/90	
3283	Door 55-1	03/19/90	03/28/90
3301	Door 30-1	03/27/90	
3302	Door 72-2	03/27/90	
3306	Structural Steel 104	03/29/90	

FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY NOT REPORTED CLOSED

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER & DATE</u>	
2317	Door 70-1	03/12/90	L-89-130	04/04/89
2318	Door 71-1	03/12/90	L-89-130	04/04/89
2752	Door 67-1	03/12/90	L-89-364	10/13/89
2753	Door 68-1	03/12/90	L-89-364	10/13/89
2754	Barrier 040F	04/06/90	L-89-364	10/13/89
2991	Door 58-4	04/03/90	L-89-459	12/19/89
3008	Barrier 097E	03/28/90	L-90-17	01/12/90
3011	Barrier 058C Hatch	04/03/90	L-90-17	01/12/90
3178	Barrier 071N	03/16/90	L-90-100	03/20/90
3183	Barrier 068N	03/28/90	L-90-100	03/20/90
3191	Barrier 071N	04/02/90	L-90-100	03/20/90
3221	Barrier 019E	03/24/90	L-90-100	03/20/90
3222	Barrier 020N	03/24/90	L-90-100	03/20/90
3233	Barrier 019E	03/24/90	L-90-100	03/20/90
3234	Barrier 020N	03/24/90	L-90-100	03/20/90
3235	Door 58-3	03/20/90	L-90-100	03/20/90