

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9010310314 DOC. DATE: 90/10/19 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept re listed fire barrier penetrations not returned to functional status within 7 days.

DISTRIBUTION CODE: A006D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3
 TITLE: OR/Licensing Submittal: Fire Protection

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD2-2 LA		1	0		PD2-2 PD		1	1
	EDISON, G		2	2					
INTERNAL:	NRR WERMEIL, J		1	0		NRR/DET/ECMB 9H		2	2
	NRR/DST 8E2		1	1		NRR/DST/SPLB8D1		1	1
	NUDOCS-ABSTRACT		1	1		OC/LFMB		1	0
	OGC/HDS2		1	0		<u>REG FILE</u> 01		1	1
EXTERNAL:	NRC PDR		1	1		NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 15 ENCL 11

IA2
wb



OCT 19 1990

L-90-371

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Special Report - Breached Fire Barriers
and Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information please contact us.

Very truly yours,

KN. HARRIS by L. Pearce
K. N. Harris
Vice President
Turkey Point Nuclear

KNH/TB/rt

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9010310314 901019
PDR ADDCK 05000250
S PNU

000048

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION

PURPOSE:

Technical Specification (TS) 3.14.5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC. Please refer to the attached list of new Fire Protection Impairments (FPI) being reported.

CAUSE AND CORRECTIVE ACTIONS:

FPI 3505 was for a trouble alarm on the main fire panel. FPI's 3543, 3549, 3550 and 3556 were issued for the support of backfit construction work. The plant continues to implement the compensatory measures as applicable.

STATUS UPDATE:

Please refer to the attached list of Fire Protection Impairments that were previously reported and are now closed.

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS OPENED SINCE LAST REPORT
WHICH HAVE BEEN OPEN FOR LONGER THAN SEVEN DAYS. .

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3505	Detector Alarm PT. 21	08/27/90	09/20/90
3543	Detector Alarm PT. 35	09/19/90	10/08/90
3549	Structural Steel 025C	09/25/90	
3550	Barrier Thermolag 3K1759	09/25/90	
3556	Barrier 025W	09/28/90	

FIRE PROTECTION SYSTEM IMPAIRMENTS PREVIOUSLY
NOT REPORTED CLOSED

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>CLOSED</u>	<u>FPL LETTER & DATE</u>
3462	Door 25-2	10/01/90	L-90-302 08/16/90