

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9101180276 DOC. DATE: 91/01/14 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251
 AUTH. NAME AUTHOR AFFILIATION
 PLUNKETT, T.F. Florida Power & Light Co.
 RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Special rept: from 901206 to 21, listed fire barriers, doors, detector alarms, manholes & water tanks not returned to functional status within 7 days. Compensatory measures implemented.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	AULUCK, R	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB 7E	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	REG FILE 02	1 1	RES/DSIR/EIB	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	EG&G BRYCE, J.H	3 3	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MAYS, G	1 1
	NSIC MURPHY, G.A	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

IA-2
wb



JAN 14 1991

L-91-021

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Special Report - Breached Fire Barriers
and Other Fire Protection Systems Impairments

In accordance with Technical Specification 6.9.3.c, the attached Special Report is provided for your information.

Should there be any questions on this information please contact us.

Very truly yours,

T. F. Plunkett
Vice President
Turkey Point Plant - Nuclear

TFP/TB/cl

attachment

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9101180276 910114
PDR ADOCK 05000250
S PDR

SPECIAL REPORT

FIRE PROTECTION SYSTEM IMPAIRMENTS REQUIRING NRC NOTIFICATION.

PURPOSE:

Technical Specification (TS) 3.14:5.b requires the submission of a report to the NRC if a non-functional fire barrier penetration is not returned to functional status within 7 days. TS 3.14 also states that certain other conditions require NRC notification. In accordance with the above requirements, this special report is being generated in order to notify the NRC.

EVENT:

Please refer to the list below for Fire Protection Impairments (FPI) being reported.

CAUSE:

FPI's 3649 and 3697, damaged fire doors, were found on routine inspections. The remaining FPI's listed were issued for the support of backfit construction and plant maintenance work. The plant continues to implement the compensatory measures as applicable.

<u>FPI #</u>	<u>FEATURE TYPE</u>	<u>OPENED</u>	<u>CLOSED</u>
3649	DOOR 30-1	12/06/90	12/13/90
3651	BARRIER 067E	12/07/90	01/03/91
3659	WATER TANK #1	12/09/90	12/21/90
3665	BARRIER 025E	12/12/90	12/28/90
3666	BARRIER 025N	12/12/90	/ /
3667	BARRIER 028N	12/12/90	12/28/90
3668	DETECTOR ALARM PT.29	12/13/90	12/30/90
3670	MANHOLE 310	12/14/90	/ /
3671	BARRIER 026W	12/14/90	/ /
3672	BARRIER 046W	12/14/90	/ /
3673	MANHOLE 308	12/14/90	/ /
3679	BARRIER 072E	12/15/90	/ /
3680	DETECTOR ALARM PT.26	12/17/90	01/05/91
3681	DETECTOR ALARM PT.27	12/17/90	01/05/91
3682	DOOR 27-1	12/18/90	12/26/90
3683	DOOR 26-1	12/18/90	12/26/90
3684	BARRIER THERMOLAG 3F1348	12/18/90	/ /
3687	BARRIER 068N	12/19/90	/ /
3690	BARRIER 025E	12/21/90	/ /
3693	MANHOLE 304	12/20/90	/ /
3694	MANHOLE 301	12/20/90	/ /
3697	DOOR 55-2	12/21/90	/ /

