

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9102040053 DOC. DATE: 91/01/28 NOTARIZED: NO DOCKET. #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME PLUNKETT, T.F. AUTHOR AFFILIATION Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)

SUBJECT: Advises that listed tests will be performed to assure that newly installed resistance temp detectors & associated process instrumentation perform intended functions, per 900913 request to amend Tech Specs.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: OR Submittal: General Distribution

### NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD2-2 LA		1	1		PD2-2 PD		1	1
	AULUCK, R		2	2					
INTERNAL:	NRR/DET/ECMB 9H		1	1		NRR/DET/ESGB		1	1
	NRR/DOEA/OTSB11		1	1		NRR/DST 8E2		1	1
	NRR/DST/SELB 8D		1	1		NRR/DST/SICB 7E		1	1
	NRR/DST/SRXB 8E		1	1		NUDOCS-ABSTRACT		1	1
	OC/LFMB		1	0		OGC/HDS3		1	0
	REG FILE <u>OL</u>		1	1		RES/DSIR/EIB		1	1
EXTERNAL:	NRC PDR		1	1		NSIC		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 18 ENCL 16

*wt* *MA4*



JAN 28 1991

L-91-33

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket No. 50-250 and 50-251  
Resistance Temperature Detector Bypass Elimination Project

By letter L-90-68A, dated September 13, 1990, Florida Power and Light (FPL) submitted a request to amend the Turkey Point Technical Specifications by eliminating the Resistance Temperature Detector (RTD) Bypass. Following completion of this modification, FPL will perform the following tests to assure that the newly installed RTDs and associated process instrumentation perform their intended functions:

1. Time response testing (see letter L-90-442, FPL to NRC, dated December 13, 1990, for additional information).
2. RTD cross-calibration (see letter L-90-442, FPL to NRC, dated December 13, 1990, for additional information).
3. Calibration and functional checks of the process instrumentation.
4. Prior to the current dual unit outage, Turkey Point measured the elbow tap differential pressure and also performed a precision flow calorimetric measurement. Upon plant startup from the current dual unit outage, we will again take elbow tap differential pressure measurements and precision flow calorimetric measurements. These measurements will then be compared to the baseline measurements which were obtained prior to plant shutdown and differences will be reconciled.

Should there be any questions, please contact us.

Very truly yours,

T. F. Plunkett  
Vice President  
Turkey Point Plant Nuclear

TFP/GS

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC  
Senior Resident Inspector, USNRC, Turkey Point Plant

9102040053 910128  
PDR ADOCK 05000250  
P PDR

010064

an FPL Group company

*Handwritten:* A001  
11/0

