

## ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9204060127 DOC. DATE: 92/03/31 NOTARIZED: NO DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 PLUNKETT, T.F. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards nonproprietary Rept BAW-2118, "Low Upper-Shelf ~~50-250-251~~  
 Toughness Fracture Analysis of Reactor Vessels of Turkey  
 Point Units 3 & 4 for Load Level A & B Conditions," per  
 10CFR50, App G, Section VE, by 920204 ltr.

DISTRIBUTION CODE: G006D COPIES RECEIVED: LTR 1 ENCL 2 SIZE: 14100  
 TITLE: Babcock & Wilcox (B&W) Owners Group Correspondence

NOTES: NRR RAGHAVAN, L  
 NRR RAGHAVAN, L

05000250  
 05000251

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
INTERNAL: AEOD DIR	1 1	AEOD/DSB	1 1
AEOD/TTC BELL, L	1 1	<u>CENTRAL FILE 01</u>	1 1
NRR ALEXION, T	1 1	NRR HALL, R.	1 1
NRR HERNAN, R	1 1	NRR KALMAN, G	1 1
NRR SIEGEL, B	1 1	NRR SILVER, H	1 1
NRR WIENS, L.	1 1	NRR/DET/ECMB 9H	1 1
NRR/DET/ESGB 8D	1 1	NRR/DLPQ/LHFB11	1 1
NRR/DLPQ/LPEB10	1 1	NRR/DRP 1/2 14E	1 1
NRR/DRSP 3/4/5	1 1	NRR/DST 8E2	1 0
NRR/DST/EMEB9H3	1 1	NRR/DST/SELB 8D	1 1
NRR/DST/SICB8H3	1 1	NRR/DST/SPLB8D1	1 1
NRR/DST/SRXB 8E	1 1	OC/LFMB	1 0
RES DE	1 1	RES/DSIR/EIB	1 1
RGN1	1 1	RGN2	1 1
RGN3	1 1	RGN4	1 1
RGN5	1 1		
EXTERNAL: *LPDR 50-302	1 1	*LPDR 50-312	1 1
*LPDR 50-313	1 1	*LPDR 50-346	1 1
*LPDR 50-460	1 1	*LPDR OCONEE	1 1
*LPDR50-289/320	2 2	*LPDR50-329/330	1 1
NRC PDR	1 1	NSIC	1 1

NOTES: 1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL

40

MA  
 11.11





FPL

P.O. Box 029100, Miami, FL, 33102-9100

MAR 31 1992

L-92-93

10 CFR 50, Appendix G

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4  
Docket Nos. 50-250 and 50-251  
Low Upper-Shelf Toughness Fracture Analysis  
of Reactor Vessels of Turkey Point Units 3  
and 4 for Load Level A and B Conditions

In accordance with the requirements of 10 CFR 50 Appendix G, Section V.E., by letter L-92-02 dated February 4, 1992, Florida Power and Light Company (FPL) submitted an analysis on low upper-shelf toughness fracture of the Turkey Point Units 3 and 4 reactor vessels for load level A and B conditions, (BAW-2118P, dated November 1991). The information provided in that report is, proprietary to, and provided by, the B&W Owners Group. Enclosed, please find two copies of the non-proprietary version of the same report, "The B&W Owners Group Materials Committee, Low Upper-Shelf Toughness Fracture Analysis of Reactor Vessels of Turkey Point Units 3 and 4 for Load Level A & B Conditions," BAW-2118, dated November 1991.

Should there be any questions, please contact us.

Very truly yours,

T. F. Plunkett  
Vice President  
Turkey Point Nuclear

TFP/OIH

enclosure

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC  
(w/o enclosure)  
Senior Resident Inspector, USNRC, Turkey Point Plant (w/o enclosure)  
James H. Taylor, B & W Utility Owners Group, B & W Nuclear  
Service Company (w/o enclosure)

9204060127 920331  
PDR ADDCK 05000250  
P PDR

an FPL Group company

6006 1/2

4-1326-6