

● PRIORITY 1 ●

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9508080290 DOC. DATE: 95/07/17 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 AUTH. NAME AUTHOR AFFILIATION
 PLUNKETT, T.F. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 94-005 re design defect in safeguards bus sequencer logic timing places both units outside design basis.

DISTRIBUTION CODE: IE28T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+23
 TITLE: Licensee Event Report (LER) & Part 21 Rept Combination (50 Dkt)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-1 LA	1 1	PD2-1 PD	1 1
	CROTEAU, R	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/SPD/RAB	1 1	AEOD/SPD/RRAB	1 1
	DEDRO	1 1	<u>FILE CENTER</u>	1 1
	NRR/DE/EELB	1 1	NRR/DE/EMCB	1 1
	NRR/DE/EMEB	1 1	NRR/DOPS/OECB	1 1
	NRR/DOTS/TQMB/A	1 1	NRR/DOTS/TSIB/B	1 1
	NRR/DRCH/HHFBHE	1 1	NRR/DRCH/HICB	1 1
	NRR/DRPE	1 1	NRR/DRPW	1 1
	NRR/DSSA	1 0	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SPSB/B	1 1	NRR/DSSA/SRXB	1 1
	RES/DSIR/EIB	1 1	RES/DSR/HFB/HFS	1 1
	RGN 1	1 1	RGN 2	1 1
	RGN 3	1 1	RGN 4	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	INPO RECORD CTR	1 1	L ST LOBBY WARD	1 1
	LITCO STUART, VA	4 4	NOAC MAYS, G	1 1
	NOAC MURPHY, G.A	1 1	NRC PDR	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM OWEN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 41 ENCL 40

A04



FPL

JUL 17 1995
L-95-201
10 CFR 50.73

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250, 50-251
Reportable Event: 94-005-02
Design Defect in Safeguards Bus Sequencer Logic Timing
Places Both Units Outside the Design Basis

The attached revised Licensee Event Report 250/94-005-02 is being provided in accordance with 10 CFR 50.73(a)(2)(ii), (a)(2)(v), (a)(2)(vii), AND 10 CFR 21. This revision provides details on the second anomaly discovered during the performance of the corrective actions.

If there are any questions, please contact us.

Very truly yours,

T. F. Plunkett
Vice President
Turkey Point Plant

CLM

Attachment

cc: S. D. Ebnetter, Regional Administrator, Region II, USNRC
T. P. Johnson, Senior Resident Inspector, Turkey Point Plant,
USNRC

080119

