

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8302160241 DOC. DATE: 83/02/10 NOTARIZED: YES DOCKET #  
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250  
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251  
 AUTH. NAME AUTHOR AFFILIATION  
 UHRIG, R.E. Florida Power & Light Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement

SUBJECT: Responds to IE Bulletin 82-04 re deficiencies in containment electrical penetration assemblies. Bunker-Ramo electrical penetrations not in use at facility.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2  
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	NRR ORB1 BC	01	7	7					
INTERNAL:	ELD/HDS4		1	0	NRR/DE/MTEB		1	1	
	NRR/DL DIR		1	1	NRR/DL/ORAB		1	0	
	NRR/DSI/MTEB		1	1	NRR/DSI/RAB		1	1	
	REG FILE	04	1	1	RGN2		1	1	
EXTERNAL:	ACRS	09	6	6	LPDR	03	1	1	
	NRC PDR	02	1	1	NSIC	05	1	1	
	NTIS		1	1					


1. The first part of the report is a general statement of the purpose and scope of the study. It is followed by a brief review of the literature on the subject.

2. The second part of the report is a description of the methods used in the study. This includes a discussion of the subjects, the experimental design, and the data collection procedures.

3. The third part of the report is a presentation of the results of the study. This includes a discussion of the findings and their implications for the field of study.

4. The fourth part of the report is a conclusion and a list of references. The conclusion summarizes the main findings of the study, and the references list the sources of information used in the study.

Subject		Method		Results		Conclusions	
1	1	1	1	1	1	1	1
2	2	2	2	2	2	2	2
3	3	3	3	3	3	3	3
4	4	4	4	4	4	4	4
5	5	5	5	5	5	5	5
6	6	6	6	6	6	6	6
7	7	7	7	7	7	7	7
8	8	8	8	8	8	8	8
9	9	9	9	9	9	9	9
10	10	10	10	10	10	10	10



February 10, 1983  
L-83-68

Mr. R. C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. DeYoung:

Re: Turkey Point Units 3 & 4  
Docket No. 50-250, & 50-251  
I E Bulletin 82-04, Deficiencies in Primary  
Containment Electrical Penetration Assemblies

We have reviewed the Turkey Point Units 3 & 4 containment penetration design as requested by the subject bulletin, and have determined that there are no Bunker Ramo electrical penetrations at Turkey Point Units 3 & 4.

Therefore, the bulletin is not applicable.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/JEM/njb

cc: Mr. James P. O'Reilly, Region II  
Mr. Harold F. Reis, Esquire  
PNS-LI-83-048

A001

8302160241 830210  
PDR AD0CK 05000250  
Q PDR




STATE OF FLORIDA     )  
                              )  
COUNTY OF DADE     )     ss.

Robert E. Uhrig, being first duly sworn, deposes and says:


That he is Vice President of Florida Power & Light Company, the licensee herein;

That he has executed the foregoing document; that the statements made in this said document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said

  
Robert E. Uhrig

Subscribed and sworn to before me this

10th day of February, 1983

  
NOTARY PUBLIC, in and for the County of Dade,  
State of Florida

My commission expires: Notary Public, State of Florida at Large  
My Commission Expires April 20, 1988  
Bonded thru Maynard Bonding Agency



Handwritten marks or text in the top right corner.

