

CATEGORY 1

2ND COPY

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9702190312 DOC.DATE: 97/02/11 NOTARIZED: NO DOCKET #
 FACIL:50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH.NAME AUTHOR AFFILIATION
 HOVEY,R.J. Florida Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards copy of Rev 32 of plant Radiological Emergency Plan.

DISTRIBUTION CODE: A045D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: OR Submittal: Emergency Preparedness Plans, Implement'g Procedures, C

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-3 PD	1 1	CROTEAU,R	1 1
INTERNAL:	FILE CENTER 01	2 2	NRR/DRPM/PERB	1 1
	NUDOCS-ABSTRACT	1 1		
EXTERNAL:	NOAC	1 1	NRC PDR	1 1

C
A
T
E
G
O
R
Y
1

D
O
C
U
M
E
N
T

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5(EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 8 ENCL 8



FEB 11 1997

L-97-035

10 CFR 50.54(q)

10 CFR 50, Appendix E

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Radiological Emergency Plan - Revision 32

By letter L-97-023, Florida Power and Light Company (FPL) submitted a copy to the NRC of Revision 32 of the Turkey Point Radiological Emergency Plan. A discrepancy was found on the submitted copy which differed from the approved revision. Therefore, by this letter, FPL is resubmitting Revision 32. Please replace the previously submitted Revision 32, in its entirety, with this submittal, in its entirety.

FPL has determined that the revision does not decrease the effectiveness of the Emergency Plan. The changes are based on (1) achieving better consistency between the Turkey Point and St. Lucie Emergency Plans, (2) reflecting recent changes at Turkey Point and in the state and county organizations, (3) correcting an omission to the Emergency Classification Table, and (4) satisfying the commitment made by FPL in our letter L-96-309, to better describe the role of drills and exercises in Emergency Response training.

Attached is a description of the changes to the Turkey Point Radiological Emergency Plan. Pursuant to 10 CFR 50.54 (q), enclosed is one copy of the plan.

Should there be any questions, please contact us.

Very truly yours,

R. J. Hovey
Vice President
Turkey Point Plant

CLM

attachment
enclosure

9702190312 970211
PDR ADOCK 05000250
F PDR

cc: Luis A. Reyes, Regional Administrator, Region II, USNRC (2 copies)
T. P. Johnson, Senior Resident Inspector, USNRC, Turkey Point Plant (no enclosure)

A045 1/

**TURKEY POINT RADIOLOGICAL EMERGENCY PLAN
SUMMARY OF CHANGES IN REVISION 32**

The changes for Revision 32 of the Turkey Point Radiological Emergency Plan are summarized as follows:

Step 7.2.2 has been clarified to better describe the role of drills and exercises in Emergency Response training.

Section 7.3 has been revised to ensure the intent of previous Technical Specification requirements for the Emergency Plan Implementing procedures has been clearly transferred to the Turkey Point Radiological Emergency Plan.

The organization change combining supervisory duties of Health Physics and Chemistry Departments has been reflected in the document.

"Chemistry Representative" and "other trained ERO personnel on-shift" have been added to sections describing the On-shift Response Organization.

Relocation of the Monroe County Emergency Operations Center, from Plantation Key to Key Largo, has been reflected in the document.

Department of Health and Rehabilitative Services - Office of Radiation Control is now Department of Health - Bureau of Radiation Control. This has been changed, as appropriate, throughout the document.

Correction to Table 3-1, Emergency Classification Table, Item 13: under Unusual Event, Paragraph E was erroneously omitted in a previous revision. The implementing procedure (0-EPIP-20101) was and remains correct.

Various other minor editorial changes have been made, primarily to fix titles and typographical errors.

