

EASTERN CT CARDIOLOGY ASSOCIATES, LLC

43 West Middle Tpke, Manchester, CT 06040, Tel. 860-647-9494

TO:

USNRC, Region I Office
NMSB - Medical Licensing
2100 Renaissance Blvd, Suite 100
King of Prussia, PA 19406-2713

December 19, 2017

RECRG11229*17AM06:04

FROM:

Rachna Khanna
Eastern CT Cardiology Associates, LLC
Mail Control No. 601412

and

Thomas I. Knox, M.D.
Hartford Cardiology Group, LLC
Mail Control No. 601413


Mr. Lester Tripp:

The following additional information is in reference to your request dated December 18, 2017, in order to continue your review of our requested amendment:


1. a. The Hartford Cardiology Group, LLC facility located at 478 Burnside Avenue, Suite 201, East Hartford, CT, will not be used by the combined practice. The East Hartford location was not put to nuclear cardiac imaging use after it was acquired and there were no radioactive sources placed at the site by the Hartford Cardiology Group.
b. The Eastern CT Cardiology Associates, LLC License No. 06-30417-01 will add the authorized location of use of 345 North Main Street, Suite 100, West Hartford. License No. 06-30417-01 ultimately becomes the sole license. Termination of License No. 06-31314-02 will be necessary.
2. Refer to the last page for the complete inventory of sealed sources that includes sources from Eastern CT Cardiology Associates and the one operating location to Hartford Cardiology Group.
3. Refer to the last page for the leakage test results of sealed sources that includes sources from Eastern CT Cardiology Associates and the one operating location to Hartford Cardiology Group.
4. The East Hartford location was not put to use after it was acquired and there were no radioactive sources placed at the site by the Hartford Cardiology Group. More recently, the West Hartford location of the Hartford Cardiology Group has resumed patient imaging; those surveys and contamination tests are current.

We appreciate your efforts with our request and we look forward to a continued safe and effective materials program. Thank you.

Respectfully submitted,



Rachna Khanna, Administrator
Eastern CT Cardiology Associates, LLC



Thomas I. Knox, MD
Hartford Cardiology Group, LLC

Hartford Cardiology Group, W. Htfd (10/02/17) sources:

Qtr #	Source	Model	Serial #	Nom Act (uCi)	Location*	Activity (uCi)^	Leakage (uCi)	Method
IV.	Cs-137	SRV137-200U	1333-14-24	211.8	HL	171	< 0.005	AW
	Ba-133	SRV133-250U	1594-58-7	244.4	HL	207	< 0.005	AW
	Co-57 fld	CTRF13770A	1831-171	10000	HL	1575	< 0.005	AW
	Initials: PJM		Date: 10/02/17		RSO:			

Eastern CT Cardiology Associates (10/13/17) sources:

Qtr #	Source	Model	Serial #	Nom Act (uCi)	Location*	Activity (uCi)^	Leakage (uCi)	Method
IV.	Ba-133	NES-358	S358023-044	274	HL	74.7	< 0.005	AW
	Cs-137	NES-356	S356036-006	222	HL	141.5	< 0.005	AW
[SEPT '08]	Co-57	SRV-057-5M	1366-22-17	5215	HL	stored		
	Co-57 fld	PF16R05715M	1862-180	15000	HL	3475	< 0.005	AW
	Initials: PJM		Date: 10/13/17		RSO:	<u>Peter J. Mac</u>		
				Leak Test Date: 7/28/17				