

LTJ 7/29/87

50-410

PRESERVICE

Supervisor R.L. Rowson

Nuclear P.P. & G. System and Component supports

1.2.1 Applicable Code for Preservice Inspection

The PSI Plan for Unit 2 shall be in compliance with the rules and regulations of 10CFR50.55a and Section XI of the ASME Boiler and Pressure Vessel Code, 1980 Edition, including addenda through Winter 1980.

In addition to the previously referenced Code edition and addenda, the PSI Plan for supports has been prepared using appropriate guidance from the following industry standard:

- OM-4 - Examination and Performance Testing of Nuclear Power Plant Dynamic Restraints (Snubbers).

1.2.2 Later Codes

As permitted by paragraphs 10CFR50.55a(g)(2) and (g)(4), NMPC may elect, for certain components, to meet requirements set forth in later editions and addenda of the Code than those specified in the approved Plan. The later Codes selected shall have been incorporated by reference in 10CFR50.55(b)(2). Additionally, use of later Codes shall be subject to approval by the NRC.

1.2.3 Requests for Relief from Code Requirements

Under the provisions of 10CFR50.55a(g)(5)(iii), relief from Code examination and/or test requirements for components, supports, or support elements shall be requested in writing to the NRC. The request for relief shall become part of this Plan and the component examination and test records and shall contain the following information:

1. Identification of the component or support, including its name and number as given in the FSAR, its function, and the ASME III Code Class.
2. The Code requirement for which relief is being requested.
3. The basis for the request for relief.
4. The inspection periods and intervals for which the requested relief is needed.
5. Alternate tests or examinations being proposed.
6. The schedule for implementing the alternate tests or examinations.

9999999999

Nine Mile Point Unit 2

7. The impact on the overall level of plant quality and safety if it is impossible to perform an alternate examination.
8. The preservice inspection results, if any, for the components for which the relief is being requested.

When the requests for relief are due to radiation considerations, the following additional information shall be included:

1. Total estimated man-rem exposure involved in the examination.
2. Radiation levels at the test area.
3. Flushing or shielding capabilities that might reduce radiation levels.

The components for which relief from examination has been granted by the NRC will be exempted from the Code examination for which relief was requested.

Relief requests are located after the tables in Section 1 of this plan. They are assigned sequential numbers as follows:

RR-IWF-1, etc.

There are no relief requests identified at this time.

1.2.4 Supports Requiring Examinations and Tests

Appendix A lists all ASME III, Class 1, 2, 3, and ANSI B31.1 upgrade supports that require visual examination and snubbers that require visual examination and functional testing. The component supports that require inspection are located within the ASME Section III boundary of those P&IDs listed in Table 1-1.

The examination and testing requirements of ASME Section XI, Subsection IWF, and this Plan shall be limited to the Class 1, 2, 3, and ANSI B31.1 upgrade component supports for which all of the requirements of the construction code have been met.

In accordance with Section XI-1980 and Winter 1980 Addenda, IWF-2510a states, "Component supports selected for examination shall be the supports of those components that are required to be examined under IWB, IWC and IWD during the first interval" and, since IWF-1230, "support exempt

NINE MILE POINT-UNIT 2
 PRESERVICE TESTING - COMPONENT SUPPORTS
 RUN DATE 12/12/85
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

PIECL21
 PAGE 1
 INSPEC: Y

SUPPORT NO	2ASSPSSH132B4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	ASS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	15G-104-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	20-01		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TBDG	299		

SUPPORT NO	2ASSPSSP133B4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	ASS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	15G-105-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	20-01		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TBDG	297		

SUPPORT NO	2ASSPSSP134B4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	ASS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	15G-106-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	20-01		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TBDG	293		

SUPPORT NO	2CCPPSSP809A2	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	CCP	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	72RC-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	018-009		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	261		

SUPPORT NO	2CCPPSSP872A2	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	CCP	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	72TQ-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	018-007		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	261		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 2

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSH631A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72JV-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 018-046
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CCPPSSP1063A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72AAT-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-013
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP1064A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72AAU-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-008
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP603A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72HS-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-008
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP607A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72HW-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-008
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 3

INSPEC: Y

SUPPORT NO 2CCPPSSP608A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72HX-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP611A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JA-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP613A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP621A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JK-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP624A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JN-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 4

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 20CCPPSSP628A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JS-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 20CCPPSSP629A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JT-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 20CCPPSSP632A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72JW-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 20CCPPSSP640A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72KE-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 20CCPPSSP645A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72KK-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 5

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSP770A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72PU-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP811A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72RE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP812A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72RF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP814A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72RH-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP816A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72RK-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 6

INSPEC: Y

SUPPORT NO 2CCPPSSP818A3
SYSTEM CODE CCP
BZ SUPPORT DWG 72RM-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 018-008
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP819A3
SYSTEM CODE CCP
BZ SUPPORT DWG 72RN-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 018-008
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP820A3
SYSTEM CODE CCP
BZ SUPPORT DWG 72RP-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 018-011
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP821A3
SYSTEM CODE CCP
BZ SUPPORT DWG 72RQ-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 018-008
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP823A3
SYSTEM CODE CCP
BZ SUPPORT DWG 72RS-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 018-008
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 7

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSP829A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72RX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-011
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP830A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72RX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-011
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP833A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72SA-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-011
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP835A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72SC-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-011
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP836A3 VALVE
 SYSTEM CODE CCP PUMP
 BZ SUPPORT DWG 72SD-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 018-046
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 8

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSP837A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72SE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP840A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72SH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP843A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72SL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP844A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72SL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP845A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72SM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 9

INSPEC: Y

SUPPORT NO 2CCPPSSP855A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72SX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP859A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP860A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP862A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP867A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TK-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 10

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSP868A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP869A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TM-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP870A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP873A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP874A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72TS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 11

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSP877A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72TV-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-012
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP879A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72TX-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-046
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP881A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72TZ-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-012
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP884A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72UC-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-046
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CCPPSSP886A3 VALVE
SYSTEM CODE CCP PUMP
BZ SUPPORT DWG 72UF-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 018-012
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 12

INSPEC: Y

SUPPORT NO 2CCPPSSP888A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72UG-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP889A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72UH-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP894A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72UL-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP896A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72UN-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP902A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72UU-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 13

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CCPPSSP903A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72UV-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP910A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72VC-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CCPPSSP930A3
 SYSTEM CODE CCP
 BZ SUPPORT DWG 72VX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 018-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSH083A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CQ-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSSH088A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CV-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 14

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSH091A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CY-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSSP081A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CN-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP082A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP084A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CR-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP085A1
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CS-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 15

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP086A1 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CT-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP087A1 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CU-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP089A1 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CW-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP090A1 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CX-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP092A1 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CZ-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 16

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSH*P1
 SYSTEM CODE CSH
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2CSH*P1
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 175

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.330-001,049,050,051

SUPPORT NO 2CSH*P2
 SYSTEM CODE CSH
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2CSH*P2
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 175

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P222X
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.330-050-001A

SUPPORT NO 2CSHPSA001A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78H-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSA005A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78L-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSA016A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78X-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-003
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 17

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSA078A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CK-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-009
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSA103A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DL-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-019
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSA192A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78HF-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-009
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSA215A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78JE-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR008A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78P-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 18

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPC: Y

SUPPORT NO 2CSHPSR009A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78Q-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-003
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR012A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78T-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-003
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR013A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78U-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-003
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR014A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78V-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-003
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR015A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78W-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-003
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 19

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSR018A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78Z-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 178

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR019A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AA-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR029A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AM-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-005
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR030A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AN-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-004
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR079A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CL-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 281

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 20

SELECTIONS -- SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSR163A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78FZ-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-018
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 217

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR177A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78GP-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-018
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR188A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78HB-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-017
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 232

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR191A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78HE-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-009
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 234

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSR202A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78HR-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-013
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 21

INSPEC: Y

SUPPORT NO 2CSHPSR204A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78HT-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-013
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR220A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108GG-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR221A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108GJ-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR222A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108GL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR223A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108GP-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 22

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSR224A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108QS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR225A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108QT-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR266A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108GR-5 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSR283A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 108RS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSSH017A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78Y-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE

23

INSPEC: Y

SUPPORT NO 2CSHPSSH025A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AG-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2CSHPSSH026A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AH-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 178

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2CSHPSSH027A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AJ-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2CSHPSSH031A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78AP-5 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-004
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2CSHPSSH076A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78CH-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-009
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 24

SELECTIONS - SORT: BY.SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSH097A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78DE-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-019
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 224

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSSH162A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78FY-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 217

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSSH165A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GB-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSSH169A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GF-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSSH183A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GV-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 25

INSPEC: Y

SUPPORT NO 2CSHPSSH190A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78HD-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 232

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSSP010A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78R-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 207

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP050A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78BJ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP064A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78BW-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP065A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78BX-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 26

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP066A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78BY-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 178

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP070A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78CC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP095A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78DC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP096A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78DD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP099A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78DG-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 27

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP100A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DH-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP104A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DM-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP109A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP110A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DT-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP111A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DU-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 28

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP112A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DV-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 180

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP120A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78EE-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP125A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78EK-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP126A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78EL-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP131A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78ER-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 29

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP143A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78FD-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-021
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 216

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2CSHPSSP136A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78FS-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-020
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP164A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GA-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP167A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GD-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP170A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GG-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 30

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP171A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GH-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP172A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GJ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP181A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GT-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP182A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GU-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

SUPPORT NO 2CSHPSSP184A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78GW-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 025-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE

31

INSPEC: Y

SUPPORT NO 2CSHPSSP185A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78GX-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP189A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 232

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP193A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HG-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 221

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP194A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 221

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSHPSSP196A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HK-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 32

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSSP199A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP201A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSP205A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 025-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSHPSSST002A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78AE-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 199

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSSST003A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78J-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 33

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSST004A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78K-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-004
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST006A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78M-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST007A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78N-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST011A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78S-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST063A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78BV-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 34

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSST067A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78BZ-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-005
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 178

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST068A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78CA-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-005
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST071A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78CD-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST072A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78CE-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST073A2
SYSTEM CODE CSH
BZ SUPPORT DWG 78CF-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 025-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 35

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSST074A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78CF-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-004
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST075A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78CG-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-004
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 177

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST077A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78CJ-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-009
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST078A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78DF-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-019
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 225

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSHPSST101A2 VALVE
SYSTEM CODE CSH PUMP
BZ SUPPORT DWG 78DJ-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 025-019
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 36

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSST102A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78DK-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST161A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78FX-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 217

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST166A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78GC-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST168A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78GE-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST173A2 VALVE
 SYSTEM CODE CSH PUMP
 BZ SUPPORT DWG 78GK-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 025-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 37

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSHPSST174A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78GL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST175A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78GM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST176A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78GN-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST178A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78GQ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST179A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78GR-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 38

INSPEC: Y

SUPPORT NO	2CSHPSST180A2	VALVE		
SYSTEM CODE	CSH	PUMP		
BZ SUPPORT DWG	78GS-3	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	025-018	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV SEC CONT	223	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSHPSST186A2	VALVE		
SYSTEM CODE	CSH	PUMP		
BZ SUPPORT DWG	78GZ-1	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	025-017	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV SEC CONT	228	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSHPSST187A2	VALVE		
SYSTEM CODE	CSH	PUMP		
BZ SUPPORT DWG	78HA-1	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	025-017	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV SEC CONT	232	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSHPSST195A2	VALVE		
SYSTEM CODE	CSH	PUMP		
BZ SUPPORT DWG	78HJ-1	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	025-008	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV SEC CONT	203	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSHPSST197A2	VALVE		
SYSTEM CODE	CSH	PUMP		
BZ SUPPORT DWG	78HL-1	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	025-008	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV SEC CONT	195	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 39

INSPEC: Y

SUPPORT NO 2CSHPSST198A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST200A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HP-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST203A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HS-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST207A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78HW-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSHPSST218A2
 SYSTEM CODE CSH
 BZ SUPPORT DWG 78DK-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 025-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 40

INSPEC: Y

SUPPORT NO	2CSHPSST281A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	CSH	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108RN-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	025-001		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	234		
SUPPORT NO	2CSHPSST282A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	CSH	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108RP-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	025-001		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	220		
SUPPORT NO	2CSHPSST289A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	CSH	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108RN-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	025-001		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	234		
SUPPORT NO	2CSHPSST290A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	CSH	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108RP-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	025-001		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	220		
SUPPORT NO	2CSLPSSH047A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	CSL	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	130BF-5	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B, C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3, 4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	026-005		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	307		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE

41

INSPEC: Y

SUPPORT NO 2CSLPSSH051A1
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BK-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 WBO
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSP046A1
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BE-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 WBO
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP048A1
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BG-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 WBO
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP049A1
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BH-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 WBO
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP050A1
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BJ-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 WBO
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 42

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSSP052A1 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130BL-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP053A1 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130BM-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP054A1 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130BN-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP090A1 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130CX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSL*P1 VALVE
 SYSTEM CODE CSL PUMP X 2CSL*P1
 BZ SUPPORT DWG EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG N/A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 175

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.330-001-037,038

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 43

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2CSL*P2	VALVE	
SYSTEM CODE	CSL	PUMP	X 2CSL*P2
BZ SUPPORT DWG		EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE		EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	N/A
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	175

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P222X
INSTALL SPEC	NMP2-P275D
RELIEF REQ	N
REMARKS	16.320-050-002

SUPPORT NO	2CSLPSA008A2	VALVE	
SYSTEM CODE	CSL	PUMP	
BZ SUPPORT DWG	130Q-4	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-2.3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	026-003
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV NAB	192

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSLPSA011A2	VALVE	
SYSTEM CODE	CSL	PUMP	
BZ SUPPORT DWG	130T-5	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-2.3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	026-002
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV NAB	192

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSLPSA034A2	VALVE	
SYSTEM CODE	CSL	PUMP	
BZ SUPPORT DWG	130AS-2	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-2.3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	026-003
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV SEC CONT	196

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2CSLPSA077A2	VALVE	
SYSTEM CODE	CSL	PUMP	
BZ SUPPORT DWG	130CK-3	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-2.3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	026-004
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV SEC CONT	252

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 44

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSR002A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130J-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR009A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130R-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR010A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130S-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-002
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR014A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130W-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR016A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130Y-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 45

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSR017A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130Z-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR018A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AA-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR019A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AB-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 197

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR020A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 197

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR026A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AJ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 199

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEGBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 46

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSR028A2 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130AL-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-004
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR035A2 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130AT-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-002
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR059A2 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130BS-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR076A2 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130CJ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-004
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 279

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSR091A2 VALVE
 SYSTEM CODE CSL PUMP
 BZ SUPPORT DWG 130CY-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 026-1
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 190

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 020-2-2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 47

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSR093A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CY-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 190

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSH003A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130K-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-002
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 178

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSH006A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130N-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSH007A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130P-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSH024A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AG-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 48

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSSH070A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 295

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSH071A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CD-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSH073A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSP036A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AU-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSLPSSP037A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AV-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 49

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSSP040A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP042A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BA-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSLPSSP043A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BB-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSLPSSP055A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP056A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 50

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2CSLPSSP057A2	VALVE		
SYSTEM CODE	CSL	PUMP		
BZ SUPPORT DWG	130BG-2	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	026-006	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	178

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2CSLPSSP060A2	VALVE		
SYSTEM CODE	CSL	PUMP		
BZ SUPPORT DWG	130BT-2	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	026-003	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	177

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2CSLPSSP072A2	VALVE		
SYSTEM CODE	CSL	PUMP		
BZ SUPPORT DWG	130CE-1	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	026-004	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SEC CONT	283

ACCESS/INACCESS	A
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

SUPPORT NO	2CSLPSSP074A2	VALVE		
SYSTEM CODE	CSL	PUMP		
BZ SUPPORT DWG	130CG-3	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	026-005	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SEC CONT	295

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2CSLPSSP075A2	VALVE		
SYSTEM CODE	CSL	PUMP		
BZ SUPPORT DWG	130CH-4	EXAM CODE	1980 W80	
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	026-004	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SEC CONT	283

ACCESS/INACCESS	A
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 51

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSSP078A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP081A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSLPSSP082A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CG-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP083A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP085A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CT-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIEC8L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 52

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSSP086A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CU-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP087A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CU-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2CSLPSSP092A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130CZ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 026-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2CSLPSSST004A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130L-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSSST005A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130M-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 53

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSST012A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130U-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-002
WELDED ATTACH N
LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST013A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130V-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST019A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130X-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-006
WELDED ATTACH N
LOCAT BUILD/ELEV NAB 186

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST021A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AD-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-006
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 197

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST022A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AE-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 54

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2CSLPSST023A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AF-4
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST029A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AM-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST030A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AN-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 216

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST031A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AP-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 215

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2CSLPSST032A2
SYSTEM CODE CSL
BZ SUPPORT DWG 130AQ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 026-004
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE

55

INSPEC: Y

SUPPORT NO 2CSLPSST033A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AR-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 199

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSST038A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AW-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 178

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSST041A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130AZ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSST044A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2CSLPSST045A2
 SYSTEM CODE CSL
 BZ SUPPORT DWG 130BD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 026-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 56

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2CSLPST084A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	CSL	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	130CS-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	026-001		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	192		
SUPPORT NO	2DERPSSH1437A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	DER	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	85CT-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	07-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	242		
SUPPORT NO	2DERPSSP1433A1	VALVE	X 2DER*MOV129	ACCESS/INACCESS	I
SYSTEM CODE	DER	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	85CP-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE		EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT	X	ISO DWG	07-A		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV PRI CONT	245		
SUPPORT NO	2DERPSSP1434A1	VALVE	X	ACCESS/INACCESS	I
SYSTEM CODE	DER	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	85CQ-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	07-A		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV PRI CONT	242		
SUPPORT NO	2DERPSSP1435A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	DER	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	85CR-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	07-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	242		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 57

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2DERPSSP1436A1 VALVE X 2DER*MOV128
 SYSTEM CODE DER PUMP
 BZ SUPPORT DWG 85CR-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT X ISO DWG 07-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 242

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2DER03PSSP15C2 VALVE
 SYSTEM CODE DER PUMP
 BZ SUPPORT DWG 424TK-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-385BE
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 319

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2DER03PSSP16C2 VALVE
 SYSTEM CODE DER PUMP
 BZ SUPPORT DWG 423EP-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-385BE
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 323

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2EGAPSA063B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-063-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-007
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 282

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-302C, 303B

SUPPORT NO 2EGAPSR045B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-045-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-005
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-297B

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 58

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2EGAPSR052B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-052-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-298B

SUPPORT NO 2EGAPSR060B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-060-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-301B

SUPPORT NO 2EGAPSSH029A3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60AH
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 38-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSSH031A3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60AJ
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 38-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSSP003A3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60J-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 038-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 59

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2EGAPSSP006A3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60L-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2EGAPSSP008A3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60N-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-005
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 283

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2EGAPSSP009A3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60P-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 283

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2EGAPSSP016B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-016-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 280

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2EGAPSSP020B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-020-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 280

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 60

INSPEC: Y

SUPPORT NO 2EGAPSSP058B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-038-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 274

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR#1, 5.257-067-309B

SUPPORT NO 2EGAPSST003B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-003-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST004A3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60K-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-005
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST006B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-006-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-003
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST007A3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60M-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 61

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2EGAPSST013B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60T-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST015B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60V-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST016A3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60K-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST017A3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60M-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2EGAPSST022A3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60AB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEGBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 62

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2EGAPSSST023A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	EGA	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	60AC-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	38-006		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SDGB	292		
SUPPORT NO	2EGAPSSST028A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	EGA	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	60AH	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	38-005		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SDGB	292		
SUPPORT NO	2EGAPSSST030A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	EGA	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	60AJ	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	38-006		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SDGB	292		
SUPPORT NO	2EGAPSSST039B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	EGA	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	60G-039-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	5. 257-067-320B, 321B
INT ATT		ISO DWG	038-005		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SDGB	271		
SUPPORT NO	2EGAPSSST040B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	EGA	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	60G-040-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	5. 257-067-316A
INT ATT		ISO DWG	038-005		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SDGB	278		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 63

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2EGAPSSST041B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-041-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-322C, 323C

SUPPORT NO 2EGAPSSST042B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-042-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 278

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-317A

SUPPORT NO 2EGAPSSST047B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-047-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-005
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-325C

SUPPORT NO 2EGAPSSST054B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-054-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-327C

SUPPORT NO 2EGAPSSST057B3 VALVE
 SYSTEM CODE EGA PUMP
 BZ SUPPORT DWG 60G-057-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 038-007
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-308C

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 64

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2EGAPSS061B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-061-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-299C

SUPPORT NO 2EGAPSS062B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-062-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 281

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-310C

SUPPORT NO 2EGAPSS064B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-064-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-304D

SUPPORT NO 2EGAPSS065B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-065-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 275

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-306B, 307B

SUPPORT NO 2EGAPSS066B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-066-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-311A

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 65

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2EGAPSSST067B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-067-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 279

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-312C

SUPPORT NO 2EGAPSSST068B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-068-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 280

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-313C, 331A

SUPPORT NO 2EGAPSSST069B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-069-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 284

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-314C

SUPPORT NO 2EGAPSSST070B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-070-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 279

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-315D

SUPPORT NO 2EGAPSSST071B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-071-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-318B

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL

PAGE 66

INSPEC: Y

SUPPORT NO 2EGAPSS072B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-072-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-319B

SUPPORT NO 2EGAPSS073B3
 SYSTEM CODE EGA
 BZ SUPPORT DWG 60G-073-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 038-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 285

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 5. 257-067-329A, 330A

SUPPORT NO 2FWSPSR231A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KS-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 288

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301N
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSR366A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17PA-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSR367A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17PB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 67

INSPEC: Y

SUPPORT NO 2FWSPSR368A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17PC-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 047-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSR369A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17PD-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 047-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH043A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17BV-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH169A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HB-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH174A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HG-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 68

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSH179A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HN-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH181A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HQ-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH188A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HX-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH192A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JB-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 274

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS Y

SUPPORT NO 2FWSPSSH199A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JJ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 69

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSH201A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17JL-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-015
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH207A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17JS-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH212A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17JX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH218A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KD-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH223A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KJ-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 70

INSPEC: Y

SUPPORT NO 2FWSPSSH229A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KG-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH233A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KU-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 274

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS Y

SUPPORT NO 2FWSPSSH240A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17LB-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSH242A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17LD-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-018
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSSP033A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17BJ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 71

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP170A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HC-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP171A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HD-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP172A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP173A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HF-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP175A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HJ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 72

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP176A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HK-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP177A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HL-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP178A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HM-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP180A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HP-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP182A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HR-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 73

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP183A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HS-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP184A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HT-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP185A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HU-5
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP186A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HV-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP187A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17HW-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 74

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP189A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17HY-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP191A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JA-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP193A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JC-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 290

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP194A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JC-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP195A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JE-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 75

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP196A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JF-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP197A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JG-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP198A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JH-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP200A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JK-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP202A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JM-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2.

PIECBL21.

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 76

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP203A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JN-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP204A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JP-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP205A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JG-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP208A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 302

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP209A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JU-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 77

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP210A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JV-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP211A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JW-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP213A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JY-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP214A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17JZ-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP215A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KA-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 78

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2FWSPSSP216A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	FWS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	17KB-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	047-017		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 292		
SUPPORT NO	2FWSPSSP217A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	FWS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	17KC-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	047-017		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 292		
SUPPORT NO	2FWSPSSP219A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	FWS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	17KE-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	047-017		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 292		
SUPPORT NO	2FWSPSSP220A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	FWS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	17KF-6	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	047-017		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 292		
SUPPORT NO	2FWSPSSP221A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	FWS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	17KG-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	047-017		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 292		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 79

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP222A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-17
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP224A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP225A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KL-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP226A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KM-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP227A1
 SYSTEM CODE FWS
 BZ SUPPORT DWG 17KN-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 047-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 80

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP228A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KP-5 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-016
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP230A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KR-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-016
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP232A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KT-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-016
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP234A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KV-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 290

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP235A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KW-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 290

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 81

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP236A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KX-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP237A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KY-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP238A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17KZ-6 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP239A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17LA-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 304

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP241A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17LC-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 82

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP243A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17LE-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-018
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP244A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17LF-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-018
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP245A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17LG-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-018
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP246A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17LH-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-018
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2FWSPSSP363A1
SYSTEM CODE FWS
BZ SUPPORT DWG 17LH-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 047-018
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 83

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSSP364A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17JG-6 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B, C
 PIPE X EXAM METHOD VT-3, 4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-015
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP365A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17HD-5 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B, C
 PIPE X EXAM METHOD VT-3, 4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-014
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP372A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17HT-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3, 4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-013
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP373A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17PE-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3, 4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2FWSPSSP374A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17PF-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B, C
 PIPE X EXAM METHOD VT-3, 4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 292

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 84

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2FWSPSST044A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17BW-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-013
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2FWSPSST190A1 VALVE
 SYSTEM CODE FWS PUMP
 BZ SUPPORT DWG 17HZ-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 047-013
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 288

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2GTSPSSP029A2 VALVE
 SYSTEM CODE GTS PUMP
 BZ SUPPORT DWG 515AG-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 050-002
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2GTSPSSP112B2 VALVE
 SYSTEM CODE GTS PUMP
 BZ SUPPORT DWG 577 G048-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 050-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SGTB 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2GTSPSSP117B2 VALVE
 SYSTEM CODE GTS PUMP
 BZ SUPPORT DWG 577G-053-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 050-008
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SGTB 271

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 85

INSPEC: Y

SUPPORT NO 2GTSPSSP118B2
 SYSTEM CODE GTS
 BZ SUPPORT DWG 577G-054-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 050-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SGTB 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=1

SUPPORT NO 2HCSPSSP002A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140J-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2HCSPSSP013A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140V-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 237

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2HCSPSSP019A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140AB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEE CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=1

SUPPORT NO 2HCSPSSP024A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140AG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEE CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 86

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2HCSPSSP029A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140AM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEE CONT 241

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2HCSPSSP032A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140AQ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 256

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2HCSPSSP037A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140AV-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 221

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2HCSPSSP055A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140BP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD V-T3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 221

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2HCSPSSP060A2
 SYSTEM CODE HCS
 BZ SUPPORT DWG 140BU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 049-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 236

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 87

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2HVKPSSP106B3 VALVE
 SYSTEM CODE HVK PUMP
 BZ SUPPORT DWG 581G-168-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 056-001
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=1

SUPPORT NO 2HVKPSSP206A3 VALVE
 SYSTEM CODE HVK PUMP
 BZ SUPPORT DWG 581U-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 056-2
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV CBDG 271

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=1

SUPPORT NO 2ICSPSR284A1 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76EP-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 313

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2ICSPSR286A1 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76ER-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2ICSPSR287A1 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76ES-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 88

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSR291A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EV-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSR292A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EW-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSR295A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH260A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DR-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 302

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH265A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DW-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 89

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSH308A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH313A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH315A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FU-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 338

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH319A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FY-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSP261A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DS-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 302

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

PAGE 90
SYS: ALL INSPEC: Y

SUPPORT NO 21CSPSSP262A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP263A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DU-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP264A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DV-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP266A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DX-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP268A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DZ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 91

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP269A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EA-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP270A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DX-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 286

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP271A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DZ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 270

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP285A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EQ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 313

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP289A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EU-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 323

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 92

INSPEC: Y

SUPPORT NO 21CSPSSP290A1
SYSTEM CODE ICS
BZ SUPPORT DWG 76EU-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 057-007
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 323

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 21CSPSSP307A1
SYSTEM CODE ICS
BZ SUPPORT DWG 76FN-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 057-007
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 21CSPSSP309A1
SYSTEM CODE ICS
BZ SUPPORT DWG 76FG-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 057-007
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 21CSPSSP310A1
SYSTEM CODE ICS
BZ SUPPORT DWG 76FG-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 057-007
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 21CSPSSP312A1
SYSTEM CODE ICS
BZ SUPPORT DWG 76FR-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 057-007
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 93

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP314A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FT-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 333

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP316A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FV-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 338

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP317A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 334

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP318A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FV-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 338

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP320A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 334

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 94

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP321A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76GA-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 341

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP322A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76GB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 340

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP323A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76GB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 340

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSST267A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DY-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSST288A1
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76ET-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 057-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 95

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSST293A1
SYSTEM CODE ICS
BZ SUPPORT DWG 76EX-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-007
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSA205A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76BK-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-005
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSA237A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76CS-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSA296A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76FA-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-006
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSR014A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76W-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 207

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 96

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ICSPSR183A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76AJ-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 217

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR186A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76AM-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR191A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76AT-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR192A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76AU-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR234A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76CP-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 97

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSR238A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76CT-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSR245A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76DA-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-006
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 258

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSR247A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76DC-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-006
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSR251A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76DG-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-006
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSR252A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76DH-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-006
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 98

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ICSPSR253A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76DJ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 204

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR254A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76DK-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 193

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR273A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76EC-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-008
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 199

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR278A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76EH-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2ICSPSR300A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76FE-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 99

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSH002A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76J-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH003A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76K-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 179

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH010A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76S-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 207

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH023A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76AE-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH024A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76AF-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 100

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSH181A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76AG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH182A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76AH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH190A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76AS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH275A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EE-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSH279A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EJ-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 101

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSH299A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76FD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21CSPSSP208A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76BN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP209A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP212A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76BR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 232

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP213A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76BS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 102

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP216A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76BV-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP218A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76BX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP228A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76CH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP229A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76CJ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP230A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76CK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 179

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 103

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP231A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76CL-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 181

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP232A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76CM-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP233A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76CN-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP239A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76CU-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG EP-76A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP249A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76DE-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECLBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 104

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP256A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 21CSPSSP276A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 21CSPSSP277A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EG-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 21CSPSSP280A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 21CSPSSP283A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76EN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 057-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 234

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 105

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSSP297A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76FB-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP298A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76FC-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP299A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76FD-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP301A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76FF-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21CSPSSP306A2 VALVE
 SYSTEM CODE ICS PUMP
 BZ SUPPORT DWG 76FM-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 057-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 106

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ICSPSST001A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76H-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2ICSPSST022A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76AD-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2ICSPSST189A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76AR-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-005
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2ICSPSST204A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76BJ-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-005
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2ICSPSST235A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76CQ-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 107

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPSST236A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76CR-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSST240A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76CV-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-008
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSST248A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76DD-6
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-006
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 237

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSST281A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76EL-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-009
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 21CSPSST282A2
SYSTEM CODE ICS
BZ SUPPORT DWG 76EM-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 057-009
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 108

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21CSPST311A2
 SYSTEM CODE ICS
 BZ SUPPORT DWG 76DD-6
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 057-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 238

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 21SC106PSSP05C1
 SYSTEM CODE ISC
 BZ SUPPORT DWG 428SS
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG DK-301FP
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 315

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC21PSSP03C1
 SYSTEM CODE ISC
 BZ SUPPORT DWG 426GD-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DK-301FB
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 342

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC22PSSP03C1
 SYSTEM CODE ISC
 BZ SUPPORT DWG 426EA-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG DK-301FA
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 342

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC23PSSP03C1
 SYSTEM CODE ISC
 BZ SUPPORT DWG 424DX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG DK-301FA
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 342

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 109

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21SC23PSSP04C1 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FA
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 342

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC32PSSP02C1 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424EA-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FA
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC33PSSP02C1 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FN
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC33PSSP03C1 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FA
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC33PSSP04C1 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FA
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIEC5L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 110

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 21SC35PSSP03C1 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DU-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301EW
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC101PSSP02C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424KY-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FB
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 341

ACCESS/INACCESS
 HIGH RAD ZONE Y
 REMOVE FOR EXAM
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC102PSSP07C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424EA-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301EX
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 317

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC103PSSP01C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424TE-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FN
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 317

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 21SC103PSSP02C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424TE-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FN
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 317

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 111

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ISC103PSSP08C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DX-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FN
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC105PSSP07C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 430FW-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FD
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC107PSSP13C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 427ZK-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301BS
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC311PSSP11C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HJ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CQ
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC324PSSP03C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 416XM-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CS
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 112

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ISC324PSSP08C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CR
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC33PSSP08C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 424DX-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301FN
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 317

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC334PSSP03C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 416XM-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CS
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC334PSSP09C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CS
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC336PSSP11C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HJ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CG
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 113

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ISC338PSSP10C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HM-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CT
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 277

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC338PSSP11C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HY-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CT
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC339PSSP10C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 428HM-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CP
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 277

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC339PSSP12C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 416WZ-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CP
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC340PSSP03C2 VALVE
 SYSTEM CODE ISC PUMP
 BZ SUPPORT DWG 416XM-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DK-301CS
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 114

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2ISC340PSSP09C2
 SYSTEM CODE ISC
 BZ SUPPORT DWG 428HL-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DK-301CR
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC341PSSP10C2
 SYSTEM CODE ISC
 BZ SUPPORT DWG 428HH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DK-301CK
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2ISC342PSSP10C2
 SYSTEM CODE ISC
 BZ SUPPORT DWG 428HM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DK-301CU
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 277

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSR085A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CV-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301N
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR277A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139U-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 115

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSR278A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139BK-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR279A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139W-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR290A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139AG-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR306A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139AY-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 47-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR310A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2DH-5 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-016
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 116

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSR339A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2DS-5
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-013
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR340A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2DW-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR359A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EG-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-016
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR360A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EH-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-016
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR361A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EJ-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 117

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSR362A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EK-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR363A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EL-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR364A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EM-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR365A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EN-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSR366A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2EP-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 001-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 118

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSR416A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FQ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 106-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 336

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR433A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139BY-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR435A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139CA-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR437A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139CE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH081A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DU-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 119

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH083A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2CT-5
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 314

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH252A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2CX-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH258A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2DD-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH263A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2CX-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH266A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2DD-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 001-015
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL31

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 120

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH308A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DF-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 313

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH318A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DF-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 313

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH319A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EE-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 277

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH338A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DS-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH341A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DX-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 121

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH347A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2ED-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 274

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH349A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EE-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH352A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DX-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH394A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FC-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH397A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 122

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2MSSPSSH408A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	2FJ-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	107-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	318		
SUPPORT NO	2MSSPSSH409A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	2FK-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	107-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	318		
SUPPORT NO	2MSSPSSH423A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	2FR-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	106-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	337		
SUPPORT NO	2MSSPSSH430A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	2FV-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	106-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV PRI CONT	342		
SUPPORT NO	2MSSPSSP080A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	2DT-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	1	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	001-014		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV PRI CONT	311		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 123

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP082A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DV-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP084A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CU-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 310

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP251A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CW-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP253A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CY-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP254A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CZ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 124

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP255A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DA-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP256A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DB-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 288

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP257A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DC-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 288

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP259A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DE-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP260A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CW-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 125

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP261A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CY-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP262A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CU-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 310

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP264A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139H-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP267A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DE-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP268A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139K-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 126

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP280A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139Y-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP281A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139Z-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP283A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP284A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AC-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP291A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AH-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 127

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP292A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AJ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP294A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AL-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP296A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AN-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP298A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AQ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP301A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 128

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP302A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AU-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP304A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AW-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP305A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP309A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DG-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 312

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP311A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DJ-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 129

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP312A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DJ-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP313A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DK-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP314A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DK-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP315A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DK-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP316A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DL-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 130

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP317A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EE-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP320A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DL-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 286

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP321A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 1398A-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP330A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP331A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 131

INSPEC: Y

SUPPORT NO 2MSSPSSP332A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DQ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP333A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DQ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP334A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DQ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP335A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DR-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP336A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DR-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 132

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP337A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DS-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP342A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DY-7
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP343A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2DZ-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP344A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EA-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP345A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EB-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/83

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 133

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP346A1 VALVE
SYSTEM CODE MSS PUMP
BZ SUPPORT DWG 2EC-2 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 001-014
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 288

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2MSSPSSP348A1 VALVE
SYSTEM CODE MSS PUMP
BZ SUPPORT DWG 2EE-4 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 001-013
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2MSSPSSP353A1 VALVE
SYSTEM CODE MSS PUMP
BZ SUPPORT DWG 2DY-7 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 001-014
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2MSSPSSP354A1 VALVE
SYSTEM CODE MSS PUMP
BZ SUPPORT DWG 2DZ-4 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 001-014
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2MSSPSSP355A1 VALVE
SYSTEM CODE MSS PUMP
BZ SUPPORT DWG 2EF-3 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 001-014
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 134

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP382A1 VALVE X 2MSS*MOV119
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2EY-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT X ISO DWG 107-A
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP383A1 VALVE X 2MSS*MOV118
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2EZ-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT X ISO DWG 107-A
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP370A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FA-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 107-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP371A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FA-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 107-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP372A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FB-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 107-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 135

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP393A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP395A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FD-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP396A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FD-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP400A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FF-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP401A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FF-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 136

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP402A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP403A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP410A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FL-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 317

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP411A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FM-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT X
 VESSEL
 HEX

VALVE X 2MSS*MOV108
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 319

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP412A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FN-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 318

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 137

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP413A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FP-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 106-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 374

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP414A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FP-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 106-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 374

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP422A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FR-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 106-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 337

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP427A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2EE-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-13
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP428A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2FT-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 106-A
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 342

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 138

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP436A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139CB-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-302X
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP440A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139CF-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 110-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP443A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139CG-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 110-A
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSST272A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139P-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST273A1 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 139G-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 001-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 139

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSST274A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST275A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139S-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST276A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139T-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST285A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AD-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 254

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST286A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AD-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 254

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 140

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2MSSPSST287A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	139AE-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	110-B		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 255		
SUPPORT NO	2MSSPSST288A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	139AE-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	110-B		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 255		
SUPPORT NO	2MSSPSST289A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	139AF-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	110-B		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 255		
SUPPORT NO	2MSSPSST297A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	139AP-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	47-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 249		
SUPPORT NO	2MSSPSST303A1	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	139AV-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	1	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301F
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	110-A		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	PRI CONT 261		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 141

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSST307A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139AZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST323A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139BC-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 47-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST326A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139BF-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST327A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139BG-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST328A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139BH-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 001-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 142

INSPEC: Y

SUPPORT NO 2MSSPSST380A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EW-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST381A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST398A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EW-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST399A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 107-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST424A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2FS-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 106-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 340

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 143

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSST425A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2FS-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 106-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 340

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSST429A1
SYSTEM CODE MSS
BZ SUPPORT DWG 2FU-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 106-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 342

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSST431A1
SYSTEM CODE MSS
BZ SUPPORT DWG 139BW-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 110-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSST432A1
SYSTEM CODE MSS
BZ SUPPORT DWG 139BX-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 110-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSST438A1
SYSTEM CODE MSS
BZ SUPPORT DWG 139CD-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 110-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 144

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSST441A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139CH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST442A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139CG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSST450A1
 SYSTEM CODE MSS
 BZ SUPPORT DWG 139CH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 110-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSS163PSSP02C2
 SYSTEM CODE MSS
 BZ SUPPORT DWG 428HN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-302R
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSS164PSSP02C2
 SYSTEM CODE MSS
 BZ SUPPORT DWG 428HP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-302R
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 145

INSPEC: Y

SUPPORT NO 2MSS165PSSP02C2
 SYSTEM CODE MSS
 BZ SUPPORT DWG 428HQ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-302R
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSS166PSSP02C2
 SYSTEM CODE MSS
 BZ SUPPORT DWG 428HR-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-302R
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 247

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSSPSSP437A3
 SYSTEM CODE MSS
 BZ SUPPORT DWG 110S-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311E
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2MSSPSR067A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AQ-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR070A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AR-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 146

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSR072A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AS-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR368A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2ER-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-17
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR369A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2GH-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-17
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR370A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2GJ-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-17
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSR371A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2GK-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-17
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 147

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSR385A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 1398M-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-20
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 295

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH003A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2K-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH004A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2L-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH005A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AJ-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH006A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AK-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 148

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH074A4
SYSTEM CODE MSS
BZ SUPPORT DWG 2AT-3
CODE CLASS 4
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 01-04
WELDED ATTACH Y
LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH075A4
SYSTEM CODE MSS
BZ SUPPORT DWG 2BS-3
CODE CLASS 4
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 01-04
WELDED ATTACH Y
LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH101A4
SYSTEM CODE MSS
BZ SUPPORT DWG 12EA-2
CODE CLASS 4
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 01-07
WELDED ATTACH N
LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH102A4
SYSTEM CODE MSS
BZ SUPPORT DWG 12EB-2
CODE CLASS 4
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 01-07
WELDED ATTACH N
LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2MSSPSSH103A4
SYSTEM CODE MSS
BZ SUPPORT DWG 12EC-1
CODE CLASS 4
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 01-07
WELDED ATTACH N
LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 149

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH104A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12ED-1 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH105A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12EE-2 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH106A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12EF-2 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH107A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12EG-2 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH122A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2BC-5 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-06
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 150

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH154A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12W-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH216A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CC-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 296

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH218A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CE-4
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH219A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CE-4
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH220A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CE-4
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 151

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSH221A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CE-4
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSH508A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2GD-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 296

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2MSSPSSP051A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CS-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP052A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CS-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP053A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CG-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 152

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP054A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CQ-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP055A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AH-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP056A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AH-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP057A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CR-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP058A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CR-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 153

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP059A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AL-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP060A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AL-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 261

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP061A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AN-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP062A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AN-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 262

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP063A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AP-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 154

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP064A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AP-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 262

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP065A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AL-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP066A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AL-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 261

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP068A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AQ-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP069A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AQ-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECLBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 155

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP071A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AR-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP073A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AS-5
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP076A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AU-4
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP094A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AZ-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 300

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP096A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2BB-4
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 300

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 156

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2MSSPSSP097A4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	2BA-5	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	001-006		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	TBDG 300		
SUPPORT NO	2MSSPSSP099A4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	2BE-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	001-006		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	TBDG 300		
SUPPORT NO	2MSSPSSP114A4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	2BH-5	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	001-006		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	TBDG 299		
SUPPORT NO	2MSSPSSP115A4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	2BJ-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	001-006		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	TBDG 300		
SUPPORT NO	2MSSPSSP117A4	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	MSS	PUMP		HIGH RAD ZONE	N
BZ SUPPORT DWG	2BK-5	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	4	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=1
INT ATT		ISO DWG	001-006		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	TBDG 296		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 157

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP120A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2BL-5 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-06
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP121A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 2BM-5 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-06
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP141A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12H-1 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP142A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12J-2 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP143A4 VALVE
 SYSTEM CODE MSS PUMP
 BZ SUPPORT DWG 12K-2 EXAM CODE 1980 W80
 CODE CLASS 4 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 01-07
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 158

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP144A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12L-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP145A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12M-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP146A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12N-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP147A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12P-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP148A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12Q-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 159

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP149A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12R-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP150A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12S-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP151A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12T-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP152A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12U-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 298

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP204A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2BT-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 303

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 160

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP205A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CB-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP207A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2BW-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP208A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2BX-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 295

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP209A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2BY-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 296

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP210A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2BZ-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 296

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 161

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP211A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CA-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 299

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP217A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CD-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-03
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 296

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP226A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CL-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 287

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP227A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CM-2
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 287

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP228A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CN-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 287

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 162

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP229A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CN-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO -
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 286

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP230A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CP-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 286

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP231A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2CP-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-04
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 287

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP367A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2EQ-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 001-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP378A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AR-3
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 163

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2MSSPSSP379A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 2AS-5
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 01-05
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSSPSSP426A4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 12U
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 01-07
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TBDG 294

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2MSS118PSSP13C4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 428FD-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-302T
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 254

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2 P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2MSS118PSSP14C4
 SYSTEM CODE MSS
 BZ SUPPORT DWG 428FE-1
 CODE CLASS 4
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-302T
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 254

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2 P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RCSPSSH001A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70H-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 265

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-8

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 164

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSH002A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70H-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 265

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-9

SUPPORT NO 2RCSPSSH003A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70J-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-1B

SUPPORT NO 2RCSPSSH004A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70J-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-1A

SUPPORT NO 2RCSPSSH005A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70J-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-1A

SUPPORT NO 2RCSPSSH006A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70K-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-1B

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 165

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSH007A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70H-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 265

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-8

SUPPORT NO 2RCSPSSH008A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70H-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 265

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-9

SUPPORT NO 2RCSPSSH009A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70L-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-2

SUPPORT NO 2RCSPSSH010A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70L-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-3

SUPPORT NO 2RCSPSSH011A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70L-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-4

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 166

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSH012A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1A
 BZ SUPPORT DWG 70L-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-5

SUPPORT NO 2RCSPSSH013A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1B
 BZ SUPPORT DWG 70L-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-2

SUPPORT NO 2RCSPSSH014A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1B
 BZ SUPPORT DWG 70L-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-3

SUPPORT NO 2RCSPSSH015A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1B
 BZ SUPPORT DWG 70L-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-4

SUPPORT NO 2RCSPSSH016A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1B
 BZ SUPPORT DWG 70L-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-5

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 167

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSH017A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70M-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HB-7

SUPPORT NO 2RCSPSSH018A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70M-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS HA-7

SUPPORT NO 2RCSPSSP019A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70N-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-14

SUPPORT NO 2RCSPSSP020A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70N-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-14

SUPPORT NO 2RCSPSSP021A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 168

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPPSSP022A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-4

SUPPORT NO 2RCSPPSSP023A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-15

SUPPORT NO 2RCSPPSSP024A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-16

SUPPORT NO 2RCSPPSSP025A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-3

SUPPORT NO 2RCSPPSSP026A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 258

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-4

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 169

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP027A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-15

SUPPORT NO 2RCSPSSP028A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70P-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-16

SUPPORT NO 2RCSPSSP029A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-1

SUPPORT NO 2RCSPSSP030A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-2

SUPPORT NO 2RCSPSSP031A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 273

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-17

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 170

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP032A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 273

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-18

SUPPORT NO 2RCSPSSP033A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-1

SUPPORT NO 2RCSPSSP034A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-2

SUPPORT NO 2RCSPSSP035A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 273

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-17

SUPPORT NO 2RCSPSSP036A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70Q-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 273

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-18

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 171

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP037A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-19

SUPPORT NO 2RCSPSSP038A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-21

SUPPORT NO 2RCSPSSP039A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-19

SUPPORT NO 2RCSPSSP040A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-21

SUPPORT NO 2RCSPSSP041A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70S-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-6

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 172

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS. ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP042A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70T-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-8

SUPPORT NO 2RCSPSSP043A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70U-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-8

SUPPORT NO 2RCSPSSP044A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70V-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-7

SUPPORT NO 2RCSPSSP045A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70W-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-7

SUPPORT NO 2RCSPSSP046A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70X-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-6

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 173

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP047A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70Y-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-12

SUPPORT NO 2RCSPSSP048A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70Z-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-12

SUPPORT NO 2RCSPSSP049A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70AA-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-23

SUPPORT NO 2RCSPSSP050A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70AA-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-23

SUPPORT NO 2RCSPSSP051A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70N-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-13

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 174

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP052A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70N-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-13

SUPPORT NO 2RCSPSSP053A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AA-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-24

SUPPORT NO 2RCSPSSP054A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AA-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-24

SUPPORT NO 2RCSPSSP055A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-25

SUPPORT NO 2RCSPSSP056A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-5

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 175

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP057A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70AC-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-5

SUPPORT NO 2RCSPSSP058A1 VALVE
 SYSTEM CODE RCS PUMP
 BZ SUPPORT DWG 70AC-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-25

SUPPORT NO 2RCSPSSP061A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1A
 BZ SUPPORT DWG 70AF-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-9

SUPPORT NO 2RCSPSSP062A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1A
 BZ SUPPORT DWG 70AG-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-10

SUPPORT NO 2RCSPSSP063A1 VALVE
 SYSTEM CODE RCS PUMP X 2RCS*P1A
 BZ SUPPORT DWG 70AH-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 64-00
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-11

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 176

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP064A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AJ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-9

SUPPORT NO 2RCSPSSP065A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AK-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-10

SUPPORT NO 2RCSPSSP066A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-11

SUPPORT NO 2RCSPSSP067A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-20

SUPPORT NO 2RCSPSSP068A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-20

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 177

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSPSSP069A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SA-22

SUPPORT NO 2RCSPSSP070A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70R-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 275

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3, SB-22

SUPPORT NO 2RCSPSST059A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AD-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS RA-1

SUPPORT NO 2RCSPSST060A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG 70AE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 64-00
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS RB-1

SUPPORT NO 2RCSRA2A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 64-00, SH 1
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS RA-2, 16.030-001-100, 101

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 178

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RCSRB2A1
 SYSTEM CODE RCS
 BZ SUPPORT DWG
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RCS*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 64-00, SH 4
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS RB-2, 16.030-001-100, 101

SUPPORT NO CRD HCU
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC P800A
 RELIEF REQ N
 REMARKS 185 CRD HCU SUPPORTS

SUPPORT NO 2RDSSP-1A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-1B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-10B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

NINE MILE POINT-UNIT 2

PIEC8L21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL PAGE 179
 INSPEC: Y

SUPPORT NO 2RDSSP-11A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-12A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-12B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-13B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-14A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 180

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO. 2RDSSP-15A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-15B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-16A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-16B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-18A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 181

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RDSSP-18B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-19B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-2B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-22A
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 1
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-23B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 182

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RDSSP-24A
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 1
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-25B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-26A
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 1
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-3A
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 1
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-3B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 183

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RDSSP-31A
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 1
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-31B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-4A
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 1
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-4B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-5B
SYSTEM CODE RDS
BZ SUPPORT DWG
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 65-00, SH 2
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS BY REACTOR CONTROLS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 184

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPC: Y

SUPPORT NO 2RDSSP-6A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-7B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-8A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-8B
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 2
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

SUPPORT NO 2RDSSP-9A
 SYSTEM CODE RDS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 65-00, SH 1
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS BY REACTOR CONTROLS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 185

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR1009A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71ALM-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 66-47
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH1006A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71ALJ-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-047
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 293

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH1029A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71ALX-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-051
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH1042A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMK-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 177-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH1049A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMR-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 177-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 186

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH345A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71LM-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-050
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH351A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71LT-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-050
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH383A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71MW-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH384A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71MX-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH428A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71PX-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-051
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 187

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH534A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71TM-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-051
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH875A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AGL-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-052
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH897A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AGN-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-052
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH903A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AGS-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-052
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 313

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH938A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AHX-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-050
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 314

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 188

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH941A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AJA-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH973A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKG-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH976A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKK-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 266

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH984A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKR-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH993A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKZ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 189

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP1008A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALL-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-047
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP1040A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMJ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT X
 VESSEL
 HEX

VALVE X 2RHS*MOV67A
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 177-A
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1041A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMJ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT X
 VESSEL
 HEX

VALVE X 2RHS*MOV67A
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 177-A
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1043A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 177-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1044A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMM-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 190
INSPEC: Y

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

SUPPORT NO 2RHSPSSP1045A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMN-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM-CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP1046A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMP-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER X
INT ATT X
VESSEL
HEX

VALVE X 2RHS*MOV67B
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 177-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP1047A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMP-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER X
INT ATT X
VESSEL
HEX

VALVE X 2RHS*MOV67B
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 177-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP1048A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMR-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 177-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP1055A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AMW-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER X
INT ATT X
VESSEL
HEX

VALVE X 2RHS*MOV112
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-055
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 191

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP1036A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1057A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMY-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP295A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JM-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP296A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JN-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 293

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP297A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JQ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 192

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP301A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP302A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP304A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JV-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP305A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JW-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP307A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JY-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 193

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP308A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP309A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KA-6
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP310A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KB-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP311A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KC-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP346A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LN-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 194

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP347A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP348A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LQ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 314

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP349A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LR-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP350A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP352A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LU-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 195

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP354A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LW-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP355A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LX-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 314

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP356A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LY-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP357A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LZ-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP358A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MA-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 196

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP380A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71MU-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 259.

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP381A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71NB-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP382A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71MV-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP385A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71MY-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP386A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71MZ-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-054
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 197

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP387A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NA-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-054
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP834A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AEE-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-054
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP836A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AEG-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP873A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AGK-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-052
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP896A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AGM-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-052
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 304

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 198

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP879A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-052
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 312

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP900A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-052
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 315

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP901A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGR-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-052
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 314

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP902A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGR-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-052
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 315

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP904A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-052
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 199

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP905A1 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AGU-2 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-052
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2RHSPSSP924A1 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AHJ-3 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-052
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 311

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2RHSPSSP939A1 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AHY-4 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-052
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2RHSPSSP940A1 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AHZ-2 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-055
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 250

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=3

SUPPORT NO 2RHSPSSP942A1 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AJB-3 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-055
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 200

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP943A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AJC-5
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP970A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKD-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP971A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKE-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP972A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKF-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP973A1
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKJ-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 201

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP977A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKL-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-055
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP978A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKM-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-055
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP979A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKN-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-053
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP980A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKN-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-53
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP982A1
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKP-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-053
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 254

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 202

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP983A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AKQ-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP985A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AKS-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 253

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP986A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AKS-4 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 252

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP987A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AKT-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP988A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AKU-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 316

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 203

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST1007A1 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ALK-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-047
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHS*E1A VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG N/A
 VESSEL WELDED ATTACH N
 HEX X 2RHS*E1A LOCAT BUILD/ELEV NAB 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.310-001-007

SUPPORT NO 2RHS*E1B VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG N/A
 VESSEL WELDED ATTACH N
 HEX X 2RHS*E1A LOCAT BUILD/ELEV SAB 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.310-001-007

SUPPORT NO 2RHS*P1A VALVE
 SYSTEM CODE RHS PUMP X 2RHS*P1A
 BZ SUPPORT DWG EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG N/A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 175

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.310-001-007

SUPPORT NO 2RHS*P1B VALVE
 SYSTEM CODE RHS PUMP X 2RHS*P1B
 BZ SUPPORT DWG EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG N/A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 175

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.310-001-007

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 204

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHS*P1C
 SYSTEM CODE RHS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RHS*P1C
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 175

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.310-001-007

SUPPORT NO 2RHS*P2
 SYSTEM CODE RHS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2RHS*P2
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 175

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P222X
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 2.170-050-027

SUPPORT NO 2RHSPSA015A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71X-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA030A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AN-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 212

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA048A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 205

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSA051A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71BK-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-027
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 199

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA1003A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ALF-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-060
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA128A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13R-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-007
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SAB 209

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA194A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13BA-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-005
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 212

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA195A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13BB-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-006
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SAB 207

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 206

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSA239A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GL-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA285A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JB-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA291A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 216

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA312A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA322A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KP-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-019
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 256

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 207

INSPEC: Y

SUPPORT NO 2RHSPSA328A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71KV-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-049
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA333A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71LA-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-049
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA344A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71LL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-057
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 285

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA402A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-058
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA418A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71PK-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 208

INSPEC: Y

SUPPORT NO 2RHSPSA419A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71PL-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-048
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA571A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71UL-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-032
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 216

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA672A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZB-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-030
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA750A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA765A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CG-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-011
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 209

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSA768A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABQ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA769A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABR-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-034
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA788A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ACH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA805A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ADA-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSA808A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ADD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 210

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSA823A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71ADT-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-031		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	215		
SUPPORT NO	2RHSPSA876A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13DH-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-009		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	190		
SUPPORT NO	2RHSPSA920A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AHE-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-021		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	200		
SUPPORT NO	2RHSPSA921A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AHF-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-047		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	292		
SUPPORT NO	2RHSPSR019A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AB-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-017		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	206		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 211

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR025A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AH-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR027A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AK-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR029A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-28
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR042A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR043A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BB-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 212

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR057A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71BR-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-020
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CNT 189

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR1002A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ALE-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-060
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CNT 235

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR1010A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ALN-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-047
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CNT 292

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR1017A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ALR-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-058
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CNT 227

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR1027A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 13ALV-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-005
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CNT 190

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 213

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR1034A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR1036A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AME-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR1058A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMZ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR111A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DX-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR118A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13H-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 214

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR119A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13J-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-007
WELDED ATTACH Y
LOCAT BUILD/ELEV SAB 209

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR123A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13M-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-007
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR124A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13N-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-007
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR129A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13S-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-007
WELDED ATTACH Y
LOCAT BUILD/ELEV SAB 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR135A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71EK-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-034
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 215

INSPEC: Y

SUPPORT NO 2RHSPSR136A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71EL-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-034
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR151A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71EW-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-027
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR158A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71FD-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-019
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR161A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71FH-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-020
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 225

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR163A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13AF-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-009
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 216

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR164A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13AG-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-010
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR166A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13AJ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-010
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR173A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13AA-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-005
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR174A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13AB-4
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-006
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR178A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13AK-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-010
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 194

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 217

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSR180A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13AM-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKND		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-011		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	NAB 208		
SUPPORT NO	2RHSPSR181A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13AN-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKND		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-011		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SEC CONT 208		
SUPPORT NO	2RHSPSR184A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13AR-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKND		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-011		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SEC CONT 202		
SUPPORT NO	2RHSPSR192A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13AY-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKND		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-005		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SEC CONT 194		
SUPPORT NO	2RHSPSR196A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13J-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKND		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-006		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SAB 207		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 218

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR240A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71GM-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-020
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 199

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR243A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71GG-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-020
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR244A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71GR-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-020
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR247A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71GU-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-026
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR253A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71HA-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-026
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 280

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 219

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR254A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HB-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR255A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HC-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 234

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR278A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HV-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR286A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JC-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR287A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALLSYS: ALL PAGE 220
INSPEC: Y

SUPPORT NO 2RHSPSR290A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71JG-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-016
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 220

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR327A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71KU-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-018
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 285

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR335A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71LC-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-057
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR342A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71LJ-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-057
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR343A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71LK-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-057
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 280

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 221

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR392A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NQ-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-018
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR394A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NJ-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-019
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR399A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NP-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 234

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR403A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NT-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-019
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 285

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSR404A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NV-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 222

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSR403A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71NW-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-048
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR420A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71PM-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-048
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR421A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71PN-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-048
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR422A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71PP-4 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-048
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSR429A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71PY-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-048
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL

PAGE 223
 INSPEC: Y

SUPPORT NO 2RHSPSR461A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71GW-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 301

SUPPORT NO 2RHSPSR463A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71GY-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 301

SUPPORT NO 2RHSPSR470A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71RF-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 301

SUPPORT NO 2RHSPSR498A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71SG-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-042
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 194

SUPPORT NO 2RHSPSR806A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADB-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-042
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 224

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSR878A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AFU-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-013		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	195		
SUPPORT NO	2RHSPSR930A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AHQ-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-031		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	283		
SUPPORT NO	2RHSPSR931A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AHR-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-031		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	286		
SUPPORT NO	2RHSPSSH026A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AJ-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-028		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	206		
SUPPORT NO	2RHSPSSH035A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71AT-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-026		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	184		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 225

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH037A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AV-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH038A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AW-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH050A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BJ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH052A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BL-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH053A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 226

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH054A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BN-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH055A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH058A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH059A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BT-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH061A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BV-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 227

INSPEC: Y

SUPPORT NO 2RHSPSSH062A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BW-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH063A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BX-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH064A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BY-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH065A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BZ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH066A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CA-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 228

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH068A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71CC-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1, 2, 3, 4
EXAM CAT F-B, C
EXAM METHOD VT-3, 4
EXAM PROCEDURE LTR
ISO DWG 066-025
WELDED ATTACH Y
LOCAT BUILD/ELEV SAB 177

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH069A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71CD-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1, 2, 3, 4
EXAM CAT F-B, C
EXAM METHOD VT-3, 4
EXAM PROCEDURE LTR
ISO DWG 066-025
WELDED ATTACH Y
LOCAT BUILD/ELEV SAB 188

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH070A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71CE-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1, 2, 3, 4
EXAM CAT F-B, C
EXAM METHOD VT-3, 4
EXAM PROCEDURE LTR
ISO DWG 066-025
WELDED ATTACH Y
LOCAT BUILD/ELEV SAB 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH071A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71CF-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1, 2, 3, 4
EXAM CAT F-B, C
EXAM METHOD VT-3, 4
EXAM PROCEDURE LTR
ISO DWG 066-025
WELDED ATTACH Y
LOCAT BUILD/ELEV SAB 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH073A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71CH-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1, 2, 3, 4
EXAM CAT F-C
EXAM METHOD VT-3, 4
EXAM PROCEDURE LTR
ISO DWG 066-024
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE: 229

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSSH075A2	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71CK-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-016
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV	SEC CONT 202

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2RHSPSSH078A2	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71CN-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-022
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV	SAB 183

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2RHSPSSH079A2	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71CP-2	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-022
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV	SAB 177

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2RHSPSSH080A2	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71CQ-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-021
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV	SEC CONT 196

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2RHSPSSH081A2	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71CR-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-022
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV	SAB 183

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 230

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH082A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO --
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH083A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CT-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH084A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH085A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CV-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH086A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CW-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 231

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH087A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH088A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CY-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH089A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CZ-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH090A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 181

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH091A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 232

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSSH092A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71DC-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-014		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	NAB 189		
SUPPORT NO	2RHSPSSH095A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71DF-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-014		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	NAB 207		
SUPPORT NO	2RHSPSSH096A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71DG-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-034		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	NAB 185		
SUPPORT NO	2RHSPSSH097A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71DH-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-029		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	SAB 189		
SUPPORT NO	2RHSPSSH098A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71DJ-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-029		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SAB 177		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 233

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH099A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 188

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH100A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DL-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH1018A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALS-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH102A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DN-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH107A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DT-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 234

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH108A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DU-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH125A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13P-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH153A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EY-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH156A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71FB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH157A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71FC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 235

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH160A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71FG-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 220

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2RHSPSSH171A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13Y-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2RHSPSSH232A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BR-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2RHSPSSH233A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2RHSPSSH246A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GT-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 236

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH252A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71GZ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-026
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH259A2
SYSTEM CODE RHS
BZ SUPPORT DWG 13BZ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-009
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 234

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH288A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71JE-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH323A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71KG-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSSH325A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71KS-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-018
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 293

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 237

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH339A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LF-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 280

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH341A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LH-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH359A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MB-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH372A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MN-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH377A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MR-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 238

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSSH378A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71MS-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-019		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	294		
SUPPORT NO	2RHSPSSH388A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71NC-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-018		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	283		
SUPPORT NO	2RHSPSSH398A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71NN-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	2-SPRINGS
INT ATT		ISO DWG	066-032		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	234		
SUPPORT NO	2RHSPSSH423A2	VALVE		ACCESS/INACCESS	I
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	71PR-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-048		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV PRI CONT	297		
SUPPORT NO	2RHSPSSH674A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	13CD-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	066-009		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	218		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 239

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH687A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CV-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH697A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CW-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH736A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CJ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH745A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH751A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC9L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 240

INSPEC: Y

SUPPORT NO 2RHSPSSH794A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ACP-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH851A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AEP-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH865A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AFL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH877A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AFT-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-013
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSH891A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AGH-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC6L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 241

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSH932A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AHS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-047
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSSPA402A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-058
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP021A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AD-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP031A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AP-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-026
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 193

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP032A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AQ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-026
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 193

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 242

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP033A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP034A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP041A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AZ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP044A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP045A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71BD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 243

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP049A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71BH-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-027
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP094A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71DE-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-014
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1000A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ALC-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-060
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 244

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP1001A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ALD-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1005A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ALH-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-036
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 244

INSPEC: Y

SUPPORT NO 2RHSPSSP1016A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-047
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP1020A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALT-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP1021A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALT-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP1028A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13ALW-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP1030A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 245

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP1035A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AMD-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-057
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1054A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AMV-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-021
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1059A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13ALX-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-012
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 205

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP1063A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ANC-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP1074A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ANG-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 246

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP1079A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ANG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP121A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13L-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 204

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP122A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 204

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP126A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP127A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13G-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 247

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP152A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EX-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP170A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CZ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP172A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13Z-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP209A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BG-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP212A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 248

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP213A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP220A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-038
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 210

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP228A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BM-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 227

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP229A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP230A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 249

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP234A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP241A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GN-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP242A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP245A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP248A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GV-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 250

INSPEC: Y

SUPPORT NO 2RHSPSSP256A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71HD-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-038
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 210

SUPPORT NO 2RHSPSSP257A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13BX-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 234

SUPPORT NO 2RHSPSSP258A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13BY-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

SUPPORT NO 2RHSPSSP263A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71HE-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 235

SUPPORT NO 2RHSPSSP264A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71HF-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 251

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP267A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HJ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP268A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP269A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP270A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 221

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP277A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-034
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 252
INSPEC: Y

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

SUPPORT NO 2RHSPSSP279A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71HW-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP280A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71HX-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP281A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71HY-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP282A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71GN-4
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-020
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP298A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71JP-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-051
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 253

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP313A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KE-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP314A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP315A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP316A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP317A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KJ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 186

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 254

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO. 2RHSPSSP318A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KK-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP319A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KL-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP320A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 181

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP321A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP324A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 255

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP326A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KT-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP330A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KX-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP331A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP338A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LE-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 280

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP360A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MC-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 256

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP362A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ME-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP365A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP366A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP370A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MM-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP371A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MM-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 257

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP373A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71MP-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-049
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP376A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ME-5 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-049
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP389A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ND-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP391A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NF-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 275

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP396A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NL-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 258

INSP: Y

SUPPORT NO 2RHSPSSP397A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71NM-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 234

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP416A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71PH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-041
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP417A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71PJ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-041
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP425A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71PT-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-048
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP469A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71RE-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 259

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP474A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71RK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-030
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP476A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71RL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP479A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71RN-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-030
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 212

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP480A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71RQ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP483A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71RT-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIEGBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 260

INSPEC: Y

SUPPORT NO 2RHSPSSP487A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71RX-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-027
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2RHSPSSP489A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71RZ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-042
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 207

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP490A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71RZ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-042
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP491A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71RS-4
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-023
WELDED ATTACH N
LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP495A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71SD-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-027
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 221

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 261

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP497A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SF-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP500A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SJ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP501A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SK-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP502A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SL-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP505A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 262

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP506A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SP-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP507A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP508A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SQ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP509A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SR-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP510A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SS-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 263

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP511A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP513A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SU-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 193

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP514A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SV-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP515A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SW-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP516A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 264

INSPEC: Y

SUPPORT NO 2RHSPSSP518A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71SZ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP524A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP525A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TE-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP533A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP626A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71WH-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 265

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP675A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CE-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 218

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP678A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZE-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 179

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP685A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CT-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP688A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DA-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP689A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DB-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 266

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP690A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DC-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP691A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP692A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 212

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP694A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP695A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CS-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 267

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP698A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 233

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP699A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CY-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP700A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CZ
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 66-05
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP704A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZJ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP707A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 268

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP708A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZN-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 182

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP710A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZQ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP711A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZR-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP714A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP715A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZV-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 269

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP716A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZW-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP718A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP719A2
 SYSTEM CODE RHS
 BZ-SUPPORT DWG 71ZZ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP724A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAE-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP725A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAG-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 270

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSSP726A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71AAH-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-022		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	188		
SUPPORT NO	2RHSPSSP727A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71AAJ-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-022		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	183		
SUPPORT NO	2RHSPSSP728A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71AAJ-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-022		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	183		
SUPPORT NO	2RHSPSSP730A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71AAL-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-022		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SAB	180		
SUPPORT NO	2RHSPSSP732A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71AAP-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-023		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	187		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 271

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP737A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CK-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 206

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP738A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 208

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP739A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAS-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 207

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP743A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAW-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 207

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP744A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAW-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 203

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 272

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP746A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 207

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP754A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABF-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 210

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP764A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-040
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 209

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSSP767A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABP-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 204

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP770A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABS-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 273

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP771A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABT-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP772A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABT-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP773A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP774A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABU-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP775A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABV-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL

PAGE 274
INSPEC: Y

SUPPORT NO 2RHSPSSP776A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ABV-4 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-024
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP777A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ABW-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-024
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP778A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ABX-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-024
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP780A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ABZ-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-047
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2RHSPSSP785A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71ACE-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-024
VESSEL WELDED ATTACH N
HE LOCAT BUILD/ELEV SAB 207

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 275

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP791A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ACL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP800A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ACV-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP801A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ADX-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP802A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ACX-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP803A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ACY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 182

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 276

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSSP807A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71ADC-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-029		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SAB	189		
SUPPORT NO	2RHSPSSP809A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71ADE-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-029		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	189		
SUPPORT NO	2RHSPSSP811A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71ADG-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=2
INT ATT		ISO DWG	066-042		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	183		
SUPPORT NO	2RHSPSSP817A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71ADN-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-024		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	187		
SUPPORT NO	2RHSPSSP818A2	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	RHS	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	71AEK-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	2	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	066-024		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SAB	180		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 277

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP822A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP825A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADW-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-029
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 177

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP827A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADX-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-029
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP830A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADZ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 250

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP837A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AEH-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-025
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 278

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP838A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AEH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP839A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AEJ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP840A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AEJ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP841A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AEL-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP847A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AEM-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 279

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP852A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AEG-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-031
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP856A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AFB-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-028
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP864A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AFK-1 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-031
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP868A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AFM-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-025
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SAB 186

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP870A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71AFP-2 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER X EXAM PROCEDURE LTR
INT ATT ISO DWG 066-042
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
HIGH RAD ZONE N
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 280

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP872A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFG-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP879A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFV-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP880A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFW-6
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP881A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFX-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 188

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP882A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFY-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 188

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 281

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP883A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFZ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP884A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGA-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP885A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP886A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGC-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP887A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGD-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 186

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 282

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP888A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGE-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP890A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP892A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGJ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-047
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP906A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGV-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP908A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 283

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP909A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP910A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP911A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGZ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP912A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP913A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 284

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP913A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHB-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP916A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHB-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP917A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHB-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP918A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP919A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 285

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSSP922A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71AHG-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX
VALVE PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-021
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP929A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71AHP-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX
VALVE PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-031
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP937A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71AHW-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX
VALVE PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-021
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP989A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKV-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX
VALVE PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-031
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2RHSPSSP991A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71AKX-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX
VALVE PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 066-026
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 286

INSPEC: Y

SUPPORT NO 2RHSPSSP992A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKY-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO -
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2RHSPSSP995A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALB-
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-041
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP998A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DL-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2RHSPSSP999A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALC-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 066-060
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 244

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2RHSPSST016A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71Y-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 287

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST020A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AC-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST022A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AE-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST024A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AG-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST028A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-028
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 222

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST036A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AU-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-026
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 288

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST039A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AX-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-026
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST040A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71AY-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-026
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST046A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71BE-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-025
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST047A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71BF-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-025
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 2-STRUTS

SUPPORT NO 2RHSPSST056A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71BQ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 289

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST067A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CB-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST072A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71CG-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 2-STRUTS

SUPPORT NO 2RHSPSST101A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DM-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST1011A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ALP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-047
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 292

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST1012A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DM-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 290

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST1013A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DN-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST1014A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DP-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST1032A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST1033A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 238

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST1051A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMT-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 291

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST1053A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AMT-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST112A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DY-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST113A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71DZ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-042
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST114A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS 2-STRUTS

SUPPORT NO 2RHSPSST115A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-030
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE-MILE-POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING -- COMPONENT SUPPORTS

PAGE 292

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST116A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-030
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST120A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13K-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST130A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EE-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ
 REMARKS

SUPPORT NO 2RHSPSST131A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EF-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST132A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71EG-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 293

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST133A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71EH-1
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-034
WELDED ATTACH N
LOCAT BUILD/ELEV NAB 185

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST134A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71EJ-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-034
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST137A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71EM-2
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST138A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71EN-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST139A2
SYSTEM CODE RHS
BZ SUPPORT DWG 71EP-3
CODE CLASS 2
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 066-021
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 294

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST162A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71FJ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST165A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13AH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST175A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13AC-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST179A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13AL-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST182A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13AP-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 204

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 295

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST183A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13AQ-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-011
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST185A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13AS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 199

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST186A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13AS-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 199

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST188A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13AU-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST189A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13AV-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 296

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST190A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13AW-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST231A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BQ-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST235A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BT-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST249A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GW-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST250A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 297

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST251A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71GY-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST262A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST266A2
 SYSTEM CODE RHS
 BZ-SUPPORT DWG 71HH-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST272A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71HP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST289A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL31

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 298

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST292A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71JF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST329A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KW-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST332A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71KZ-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST334A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LB-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST340A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71LG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 280

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 299

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST361A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MD-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST363A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MF-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST364A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MG-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-49
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST367A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MJ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST368A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MK-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 300

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST369A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ML-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 303

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST374A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MQ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST375A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71MQ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC N1P2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST390A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71NE-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST393A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71NH-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 301

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST400A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71NQ-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 224

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST424A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71PS-4 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST426A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71PW-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST427A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71PW-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST460A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71QU-5 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-048
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECHL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 302

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST462A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71QX-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-048
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST464A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71QZ-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-017
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST471A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71RQ-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-017
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST472A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71RH-3 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-017
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2RHSPSST473A2 VALVE
SYSTEM CODE RHS PUMP
BZ SUPPORT DWG 71RJ-4 EXAM CODE 1980 W80
CODE CLASS 2 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 066-023
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV S AUXBAY 183

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 303

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST478A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71RN-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 213

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST481A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71RR-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 205

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST492A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71SA-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-027
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 212

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST499A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71SH-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 196

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST503A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71SL-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-023
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV S AUXBAY 180

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 304

INSPEC: Y

SUPPORT NO 2RHSPSST519A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TA-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST527A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST530A2
 SYSTEM CODE RHS
 BZ-SUPPORT DWG 71TJ-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST538A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST541A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 211

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 305

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST552A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71TX-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-027
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 210

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST554A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71TZ-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-027
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST555A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71UA-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 198

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST556A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71UA-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 199

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST682A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13CF-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 306

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST683A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CG-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST684A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST686A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CU-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST693A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 211

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST702A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 307

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST705A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13BT-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST709A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZP-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST712A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZS-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST713A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZT-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST717A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ZX-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 308

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST721A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST722A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAC-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-034
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST729A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAL-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SAB 180

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST733A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CH-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST748A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABA-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 309

INSPEC: Y

SUPPORT NO 2RHSPSST753A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71TR-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 211

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST759A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13CM-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 209

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST766A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABN-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-034
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST770A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ABS-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST810A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71ADF-4
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

PAGE 310
 SYS: ALL INSPEC: Y

SUPPORT NO 2RHSPSST812A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADH-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-042
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST819A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADP-3 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-024
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 204

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST821A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADR-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-030
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST824A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 71ADU-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 238

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST855A2 VALVE
 SYSTEM CODE RHS PUMP
 BZ SUPPORT DWG 13DE-2 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 066-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 210

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 311

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST867A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AFN-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST871A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST875A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DG-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST889A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AGF-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST925A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 312

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST926A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHK-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST927A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHM-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 280

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST928A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AHN-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST990A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AKW-5
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2RHSPSST996A2
 SYSTEM CODE RHS
 BZ SUPPORT DWG 13DJ-3
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 313

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2RHSPSST977A2	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	13DK-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-006
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	190

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2RHS337PSSP04C2	VALVE	X
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	428ST-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE		EXAM METHOD	VT-3,4
SNUBBER	X 2RHS*MOV80B	EXAM PROCEDURE	LTR
INT ATT	X	ISO DWG	DP-371BJ
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	234

ACCESS/INACCESS	A
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301F
RELIEF REQ	N
REMARKS	DR=3

SUPPORT NO	2RHS351PSSP04C2	VALVE	X
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	428ZL-1	EXAM CODE	1980 W80
CODE CLASS	2	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE		EXAM METHOD	VT-3,4
SNUBBER	X 2RHS*MOV80A	EXAM PROCEDURE	LTR
INT ATT	X	ISO DWG	DP-301BJ
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	234

ACCESS/INACCESS	A
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301F
RELIEF REQ	N
REMARKS	DR=3

SUPPORT NO	2RHSPSSP159A3	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71FE-1	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER	X	EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-029
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV SAB	181

ACCESS/INACCESS	A
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

SUPPORT NO	2RHSPSST117A3	VALVE	
SYSTEM CODE	RHS	PUMP	
BZ SUPPORT DWG	71ED-1	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	066-029
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SAB	181

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 314

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2RHSPSST735A3
 SYSTEM CODE RHS
 BZ SUPPORT DWG 71AAR-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 066-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 181

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO RPV SKIRT
 SYSTEM CODE RPV
 BZ SUPPORT DWG
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL X 2MSS*REV1
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-A
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P301V
 RELIEF REQ N
 REMARKS 16.010-001-167,187

SUPPORT NO 2SFC*E1A
 SYSTEM CODE SFC
 BZ SUPPORT DWG
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL X 2SFC*E1A
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 215

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P221X
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.550-072-003,036

SUPPORT NO 2SFC*E1B
 SYSTEM CODE SFC
 BZ SUPPORT DWG
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL X 2SFC*E1B
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 215

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P221X
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.550-072-003,036

SUPPORT NO 2SFC*P1A
 SYSTEM CODE SFC
 BZ SUPPORT DWG
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2SFC*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P222X
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.550-050-011

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 315

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFC*P1B
 SYSTEM CODE SFC
 BZ SUPPORT DWG
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2SFC*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P222X
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.550-050-011

SUPPORT NO 2SFCPSA035A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77AT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-019
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SFCPSA058A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77BQ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 286

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SFCPSA212A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77BS-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SFCPSA216A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77BW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 316

INSPEC: Y

SUPPORT NO	2SFCPSA228A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	77CH-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	007-029		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	260		
SUPPORT NO	2SFCPSA238A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	77CT-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	007-022		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	228		
SUPPORT NO	2SFCPSA245A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	77DA-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	007-049		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	259		
SUPPORT NO	2SFCPSA356A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	77HP-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	007-031		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	298		
SUPPORT NO	2SFCPSR026A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	77AJ-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	007-015		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	233		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 317

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSR027A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77AK-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-015
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR036A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77AU-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR041A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77AY-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR057A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BP-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-014
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 276

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR215A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BV-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-014
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 256

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 318

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSR227A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77CG-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSR231A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77CL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSR233A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77CN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSR234A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77CP-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSR240A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77CV-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 319

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSR244A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77CZ-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 230

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR246A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77M-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR247A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77P-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR248A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77R-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR249A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77S-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 320

INSPEC: Y

SUPPORT NO 2SFCPSR250A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77U-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-020
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR255A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DH-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 225

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR260A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DN-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-049
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR267A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DY-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-017
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR268A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DZ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-017
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 321

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSR336A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77GU-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR344A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77HC-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR345A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77HD-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR353A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77HL-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-029
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 275

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR359A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77HR-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-014
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 302

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2.

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 322

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSR363A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77HU-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 308

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SFCPSR383A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77JH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 345

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SFCPSR394A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77JU-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 324

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SFCPSR395A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77JV-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 341

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS SHOULD BE Y

SUPPORT NO 2SFCPSR399A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77JY-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 007-040
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 323

INSPEC: Y

SUPPORT NO 2SFCPSR400A3 VALVE
SYSTEM CODE SFC PUMP
BZ SUPPORT DWG 77JZ-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 007-040
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR679A3 VALVE
SYSTEM CODE SFC PUMP
BZ SUPPORT DWG 77UC-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 007-010
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 311

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR695A3 VALVE
SYSTEM CODE SFC PUMP
BZ SUPPORT DWG 77UT-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 007-031
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR696A3 VALVE
SYSTEM CODE SFC PUMP
BZ SUPPORT DWG 77UV-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 007-031
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSR713A3 VALVE
SYSTEM CODE SFC PUMP
BZ SUPPORT DWG 77VL-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 007-040
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 324

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSSH028A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77AL-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 007-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSSH323A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77GF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 007-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSSH355A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77HN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 007-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSSH396A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77JW-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 007-040
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSSP029A3
 SYSTEM CODE SFC
 BZ SUPPORT DWG 77AM-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B, C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 007-038
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 225

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 325

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSSP030A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AN-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-017
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP217A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77BX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-027
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP334A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GS-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP344A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GS-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 291

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP350A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77HH-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-029
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 308

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 326

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSSP486A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77MA-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD FT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-048
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 303

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP561A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77PR-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-066
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 330

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP574A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GD-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-064
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP578A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77QH-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-058
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 350

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SFCPSSP603A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77RG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 344

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/83

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 327

INSPEC: Y

SUPPORT NO	2SFCPSSP616A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	77RR-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	007-062		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	311		
SUPPORT NO	2SFCPSSP618A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	77RT-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	007-062		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	311		
SUPPORT NO	2SFCPSSP620A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	77RU-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	007-062		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	311		
SUPPORT NO	2SFCPSSP651A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	77TB-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	007-063		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	299		
SUPPORT NO	2SFCPSSP699A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SFC	PUMP		HIGH RAD ZONE	Y
BZ SUPPORT DWG	77UY-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	Y
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3,4	RELIEF REQ	N
SNUBBER	X	EXAM PROCEDURE	LTR	REMARKS	DR=3
INT ATT		ISO DWG	007-063		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	299		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 328

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSSP702A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77VB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-063
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 25FCPSSP707A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77VB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-063
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 25FCPSST001A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77H-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-016
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST021A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AD-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST022A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AE-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 329

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSST023A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AF-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST024A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AG-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST025A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AH-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST031A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AP-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-015
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
 HIGH RAD ZONE-
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST032A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77AQ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 330

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSST034A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77AS-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 233

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST037A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77AV-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST043A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BA-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST047A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BE-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST055A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BM-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 331

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSST056A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BN-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-015
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST220A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77BZ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-016
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST230A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77CK-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-019
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 235

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST239A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77CU-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 228

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST254A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DG-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-022
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 332

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSST261A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DP-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-049
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST263A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DR-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-049
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 253

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST264A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77DR-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-049
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 253

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST325A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77GH-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-031
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25FCPSST327A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77GK-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-031
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 294

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 333

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25FCPSST328A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GL-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST329A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GM-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST330A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GN-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 315

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST332A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GG-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25FCPSST335A3 VALVE
 SYSTEM CODE SFC PUMP
 BZ SUPPORT DWG 77GT-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 007-030
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 334

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SFCPSST338A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77GW-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST343A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77HB-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST352A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77HK-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST358A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77GM-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-030
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 299

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SFCPSST382A3
SYSTEM CODE SFC
BZ SUPPORT DWG 77JG-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 007-010
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 345

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 335

INSPEC: Y

SUPPORT NO	2SFCPSST385A3	VALVE	
SYSTEM CODE	SFC	PUMP	
BZ SUPPORT DWG	77JK-1	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	007-010
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	348

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SFCPSST401A3	VALVE	
SYSTEM CODE	SFC	PUMP	
BZ SUPPORT DWG	77KA-1	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	007-040
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	296

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SFCPSST428A3	VALVE	
SYSTEM CODE	SFC	PUMP	
BZ SUPPORT DWG	77KZ-2	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	007-031
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	298

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SFCPSST676A3	VALVE	
SYSTEM CODE	SFC	PUMP	
BZ SUPPORT DWG	77UA-1	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	007-031
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	295

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SFCPSST719A3	VALVE	
SYSTEM CODE	SFC	PUMP	
BZ SUPPORT DWG	77VQ-1	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	007-019
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	233

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 336

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SLSPSR060A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSR062A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BC-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSR064A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BD-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSR068A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSR070A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 337

INSPEC: Y

SUPPORT NO 2SLSPSR072A1 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75BH-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 88-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSSH074A1 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75BJ-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 88-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSSH100A1 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75CB-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 88-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSSH113A1 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75CH-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 88-A
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSSP054A1 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75AY-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 88-B
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 338

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SLSPSSP075A1
SYSTEM CODE SLS
BZ SUPPORT DWG 75BJ-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 88-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SLSPSSP092A1
SYSTEM CODE SLS
BZ SUPPORT DWG 75BU-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 88-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SLSPSSP103A1
SYSTEM CODE SLS
BZ SUPPORT DWG 75CB-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 88-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SLSPSSP106A1
SYSTEM CODE SLS
BZ SUPPORT DWG 75CC-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 88-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 308

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SLSPSSP114A1
SYSTEM CODE SLS
BZ SUPPORT DWG 75CH-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 88-A
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301F
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 339

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SLSPSST076A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSST077A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 301

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSST078A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75BL-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 307

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSST099A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75CA-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 300

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SLSPSST116A1
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75CK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 88-B
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 340

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SLS*P1A
 SYSTEM CODE SLS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2SLS*P1A
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.130-001-036

SUPPORT NO 2SLS*P1B
 SYSTEM CODE SLS
 BZ SUPPORT DWG
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP X 2SLS*P1B
 EXAM CODE 1980 W80
 EXAM ITEM F-1
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG N/A
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC P800A
 INSTALL SPEC NMP2-P275D
 RELIEF REQ N
 REMARKS 16.130-001-036

SUPPORT NO 2SLSPSSP017A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75S-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 067-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SLSPSSP018A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75T-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 067-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SLSPSSP024A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75Z-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 067-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 341

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SLSPSSP025A2 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75AA-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 067-001
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SLSPSSP088A2 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75BS-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-375T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SLSPSSP089A2 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75BS-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-375T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SLSPSSP091A2 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75BT-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-375T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 309

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SLSPSSP098A2 VALVE
 SYSTEM CODE SLS PUMP
 BZ SUPPORT DWG 75BZ-1 EXAM CODE 1980 W80
 CODE CLASS 2 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-375T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 342

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SLSPSSP105A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75CB-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-375T
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SLSPSSP108A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75CD-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-375T
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SLSPSSP109A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75CE-2
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-375T
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SLSPSSP110A2
 SYSTEM CODE SLS
 BZ SUPPORT DWG 75CF-1
 CODE CLASS 2
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-375T
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 306

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSA001A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11H-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
 HIGH RAD ZONE N
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 343

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSA002A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11J-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 073-017
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSA007A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11EH-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 073-007
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSA012A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11MZ-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 073-003
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSA013A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11NA-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 073-004
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSA276A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11MR-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 073-010
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 289

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 344

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25VVPSA279A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11NU-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-014
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 287

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSR049A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11AG-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-007
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSR080A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11V-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-016
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSR102A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11CH-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-014
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSR110A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11CR-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-014
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 345

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSR115A3 VALVE
SYSTEM CODE SVV PUMP
BZ SUPPORT DWG 11CW-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 073-017
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSR139A3 VALVE
SYSTEM CODE SVV PUMP
BZ SUPPORT DWG 11DU-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 073-017
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSR157A3 VALVE
SYSTEM CODE SVV PUMP
BZ SUPPORT DWG 11EL-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 073-016
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSR174A3 VALVE
SYSTEM CODE SVV PUMP
BZ SUPPORT DWG 11FB-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 073-007
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSR253A3 VALVE
SYSTEM CODE SVV PUMP
BZ SUPPORT DWG 11JC-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 073-003
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 346

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25VVPSR255A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11JC-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSR265A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LF-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 073-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSR280A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LF-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSH027A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AB-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 270

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25VVPSH030A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-003
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 347

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSH067A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SVVPSSH127A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SVVPSSH137A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DS-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SVVPSSH149A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EC-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SVVPSSH175A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11FB-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 348

INSPEC: Y

SUPPORT NO 2SVVPSSH378A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LH-6
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-010
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSSH390A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LL-6
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-014
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SVVPSSP017A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11S-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-002
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP019A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11U-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-002
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP020A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11U-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-002
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 349

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP022A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11Y-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP023A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11Z-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP024A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11Z-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP025A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP026A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 350

INSPEC: Y

SUPPORT NO 2SVVPSSP028A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11AC-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-003
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP029A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11AC-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-003
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP031A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11AE-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-008
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP032A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11AF-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-008
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP034A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11AH-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-006
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 351

INSPEC: Y

SUPPORT NO 2SVVPSSP035A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP037A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 260

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP038A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP039A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AN-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP040A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 352

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP041A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AQ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP043A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AS-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP044A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AT-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 259

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP045A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AU-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP046A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 248

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 353

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP047A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP048A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP050A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AJ-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP056A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11KH-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP057A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AZ-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 354

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25VVPSSP058A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BA-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-003
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP059A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BB-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-003
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP060A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11VD-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-003
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP061A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BB-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-004
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 270

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP062A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11VE-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-004
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 270

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21-

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 355
INSPEC: Y

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

SUPPORT NO 2SVVPSSP063A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11BB-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-005
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2SVVPSSP064A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11VF-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-005
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2SVVPSSP065A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11BE-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-009
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 255

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2SVVPSSP066A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11BF-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-010
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

SUPPORT NO 2SVVPSSP068A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11BH-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-010
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 356

INSPEC: Y

SUPPORT NO 2SVVPSSP069A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP070A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BJ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP071A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BJ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP072A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BK-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 266

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP075A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BP-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 357

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP076A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BQ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP077A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AZ-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 264

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP082A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11N-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP083A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BS-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 252

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP086A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11BT-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 358

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP088A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BV-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-020
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 268

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS S SUPPRS, DR=2

SUPPORT NO 2SVVPSSP090A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BW-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-013
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP091A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP092A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BY-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP093A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11CB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-020
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 254

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21.

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 359

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25VVPSSP097A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP098A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP099A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-020
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP100A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP101A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CG-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 360

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25VVPSSP103A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CJ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP104A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CK-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP105A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CL-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP106A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CM-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 252

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP111A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CS-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 361

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP112A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP113A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CU-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 249

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP116A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP117A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CY-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP118A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CZ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 362

INSPEC: Y

SUPPORT NO 2SVVPSSP119A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DA-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP121A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DC-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-015
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP124A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP126A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP128A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DJ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 363

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP129A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11DJ-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-021
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP131A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11DM-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-019
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP132A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11DN-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-013
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP135A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11DQ-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-021
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP138A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11DT-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-017
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 364

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP140A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP143A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DQ-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP144A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11DX-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP147A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EA-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP151A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EE-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 365

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP152A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EF-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP153A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP154A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EJ-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP155A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EJ-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP156A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EK-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 366

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP158A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP159A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EN-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP161A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP162A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ER-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP163A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ER-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 367

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP164A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11ET-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-013
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 268

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP165A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11EU-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 276

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP166A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11EV-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-009
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP167A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11EW-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP168A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11EX-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-010
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 368

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP169A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11EZ-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP171A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11FA-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-008
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP258A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11KH-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-001
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP261A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-002
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP262A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11BC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-002
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 369

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SVVPSSP266A3	VALVE	
SYSTEM CODE	SVV	PUMP	
BZ SUPPORT DWG	11MF-4	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER	X	EXAM PROCEDURE	LTR
INT ATT		ISO DWG	073-016
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV	PRI CONT 297

ACCESS/INACCESS	I
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

SUPPORT NO	2SVVPSSP267A3	VALVE	
SYSTEM CODE	SVV	PUMP	
BZ SUPPORT DWG	11MG-3	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER	X	EXAM PROCEDURE	LTR
INT ATT		ISO DWG	073-016
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV	PRI CONT 295

ACCESS/INACCESS	I
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

SUPPORT NO	2SVVPSSP268A3	VALVE	
SYSTEM CODE	SVV	PUMP	
BZ SUPPORT DWG	11MH-5	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER	X	EXAM PROCEDURE	LTR
INT ATT		ISO DWG	073-017
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV	PRI CONT 294

ACCESS/INACCESS	I
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

SUPPORT NO	2SVVPSSP269A3	VALVE	
SYSTEM CODE	SVV	PUMP	
BZ SUPPORT DWG	11MJ-3	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER	X	EXAM PROCEDURE	LTR
INT ATT		ISO DWG	073-017
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV	PRI CONT 294

ACCESS/INACCESS	I
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

SUPPORT NO	2SVVPSSP270A3	VALVE	
SYSTEM CODE	SVV	PUMP	
BZ SUPPORT DWG	11MK-3	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C
PIPE	X	EXAM METHOD	VT-3,4
SNUBBER	X	EXAM PROCEDURE	LTR
INT ATT		ISO DWG	073-018
VESSEL		WELDED ATTACH	Y
HEX		LOCAT BUILD/ELEV	PRI CONT 297

ACCESS/INACCESS	I
HIGH RAD ZONE	Y
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL PAGE 370
 INSPEC: Y

SUPPORT NO 2SVVPSSP271A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11ML-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-018
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP272A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11MM-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-020
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP273A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11ML-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-020
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP274A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11MP-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-021
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP275A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11MG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-021
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 371

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP282A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ND-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 279

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP283A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP284A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NF-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP285A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NG-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 272

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP286A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 372

INSPEC: Y

SUPPORT NO 2SVVPSSP287A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NJ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 271

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP288A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NK-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 269

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP289A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NL-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP293A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NQ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP296A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NT-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-034
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 373

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP305A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11PC-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-034
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP317A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11PQ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-036
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP337A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11JQ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP342A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11JQ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP358A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11KM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-044
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 374

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP368A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11KX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-048
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP376A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LG-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP377A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LG-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP379A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LJ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP380A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LK-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-011
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 375

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP381A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LK-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-011
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP383A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LJ-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-011
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP384A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LN-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-013
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP385A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LN-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-013
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP387A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11LP-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-013
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 376

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP388A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LQ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP389A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LQ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP391A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LR-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP392A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP393A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 377

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP394A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LU-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP395A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP396A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-008
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP397A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-008
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP398A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL

PAGE 378
 INSPEC: Y

SUPPORT NO 2SVVPSSP399A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP400A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LY-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-001
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP401A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LZ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-001
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP402A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11MA-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 296

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP403A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11MB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-002
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 379

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP404A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11MC-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-003
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP405A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11MB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-003
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP406A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP407A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11MD-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP408A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11LT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 380

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP409A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ME-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-005
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 294

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP426A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11QH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-049
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 281

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP451A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11RC-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP456A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11RH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP458A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11RK-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 381

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25VVPSSP464A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11NT-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP468A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11RS-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP471A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11RW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 277

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP475A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11EA-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 280

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 25VVPSSP481A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11SC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311G
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 382

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP484A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11SE-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-040
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 251

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP485A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11QY-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-051
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 262

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP489A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11SJ-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311Q
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP507A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11TD-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311D
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP529A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11TY-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311F
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
 SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL PAGE 383
 INSPEC: Y

SUPPORT NO 2SVVPSSP544A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11UP-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311P
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP549A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11UU-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311G
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP552A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11UX-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311J
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP554A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11UZ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 295

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP555A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11UZ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 384

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP557A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11VB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP584A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WD-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-029
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 284

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP585A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WD-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-029
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 285

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP594A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WN-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311U
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP595A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WP-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311U
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 385

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP600A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WR-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311U
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP602A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WT-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 073-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 278

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP603A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WU-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311H
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP604A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11VP-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311H
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP606A3 VALVE
 SYSTEM CODE SVV PUMP
 BZ SUPPORT DWG 11WW-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-311V
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 386

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP609A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11WY-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311V
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP614A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11XD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311V
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP616A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11XF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311V
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP627A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11XS-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311K
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP635A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11XZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311S
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 387

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP636A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11YA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311L
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP638A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11YC-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311L
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP644A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11YJ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-018
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 282

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP653A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11YS-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311R
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP662A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11YY-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311N
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 388

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP669A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11ZE-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG DP-311M
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP671A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11ZG-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG DP-311M
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP674A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11ZJ-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG DP-311M
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP675A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11ZK-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 073-043
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 274

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

SUPPORT NO 2SVVPSSP679A3
SYSTEM CODE SVV
BZ SUPPORT DWG 11ZP-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG DP-311G
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 389

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SVVPSSP680A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ZQ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG DP-311Q
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP684A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11CT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH Y
 LOCAT BUILD/ELEV PRI CONT 246

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP686A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ZV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 297

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP690A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11ZZ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 298

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SVVPSSP692A3
 SYSTEM CODE SVV
 BZ SUPPORT DWG 11AAB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 073-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 390

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWP*P1A
SYSTEM CODE SWP
BZ SUPPORT DWG
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP X 2SWP*P1A
EXAM CODE 1980 W80
EXAM ITEM F-1
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG N/A
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBWELL 224

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P222X
INSTALL SPEC NMP2-P275D
RELIEF REQ N
REMARKS 2. 170-050-026

SUPPORT NO 2SWP*P1B
SYSTEM CODE SWP
BZ SUPPORT DWG
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP X 2SWP*P1B
EXAM CODE 1980 W80
EXAM ITEM F-1
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG N/A
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBWELL 224

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P222X
INSTALL SPEC NMP2-P275D
RELIEF REQ N
REMARKS 2. 170-050-026

SUPPORT NO 2SWP*P1C
SYSTEM CODE SWP
BZ SUPPORT DWG
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP X 2SWP*P1C
EXAM CODE 1980 W80
EXAM ITEM F-1
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG N/A
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBWELL 224

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P222X
INSTALL SPEC NMP2-P275D
RELIEF REQ N
REMARKS 2. 170-050-026

SUPPORT NO 2SWP*P1D
SYSTEM CODE SWP
BZ SUPPORT DWG
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP X 2SWP*P1D
EXAM CODE 1980 W80
EXAM ITEM F-1
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG N/A
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBWELL 224

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P222X
INSTALL SPEC NMP2-P275D
RELIEF REQ N
REMARKS 2. 170-050-026

SUPPORT NO 2SWP*P1E
SYSTEM CODE SWP
BZ SUPPORT DWG
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP X 2SWP*P1E
EXAM CODE 1980 W80
EXAM ITEM F-1
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG N/A
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBWELL 224

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P222X
INSTALL SPEC NMP2-P275D
RELIEF REQ N
REMARKS 2. 170-050-026

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 391

INSPEC: Y

SUPPORT NO	2SWP*P1F	VALVE		
SYSTEM CODE	SWP	PUMP	X 2SWP*P1F	
BZ SUPPORT DWG		EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE		EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	N/A	
VESSEL		WELDED ATTACH	N.	
HEX		LOCAT BUILD/ELEV	SCRNWELL 224	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P222X
INSTALL SPEC	NMP2-P275D
RELIEF REQ	N
REMARKS	2.170-050-026

SUPPORT NO	2SWPPSA039A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	108RW-3	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-009	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	TUNN 246	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSA044A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	108NJ-1	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-010	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	TUNN 248	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSA045A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	108NB-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-008	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	TUNN 246	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSA100A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	108TA-3	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-024	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	TUNN 245	

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 392

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSA1001A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WK-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1084A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19YF-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-57
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 279

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1130A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SB-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1131A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108KJ-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1134A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108KN-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-057
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 393

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSA1141A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 192V-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-065
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1152A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AAF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-062
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 274

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA117A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-012
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA118A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-111
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1222A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RA-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 394

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSA1235A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108SD-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-006		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	TUNN		247
SUPPORT NO	2SWPPSA1237A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108SE-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-007		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	TUNN		254
SUPPORT NO	2SWPPSA1421A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19ABH-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	21-196		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB		258
SUPPORT NO	2SWPPSA1422A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19ABJ-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-199		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB		256
SUPPORT NO	2SWPPSA1423A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19ABK-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-026		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB		258

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 395

INSPEC: Y

SUPPORT NO 2SWPPSA1424A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ABL-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-194
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 256

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1461A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581H-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-131
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1462A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581J-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-127
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA1463A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581J-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-134
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA314A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UE-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-047
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 193

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 396

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSA315A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 200

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA361A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19KS-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA439A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19NE-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-045
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA512A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA541A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 397

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSA559A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19SE-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-060
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA818A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EH-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-049
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SAB 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA825A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19ER-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-51
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA832A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 212

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA842A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FH-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 398

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSA862A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GC-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-046
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 209

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA864A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GE-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-047
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 200

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSA872A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GN-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-039
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV NAB 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR001B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TG-705 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-11
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR002B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TG-707 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-11
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 399

INSPEC: Y

SUPPORT NO 2SWPPSR028A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108NS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR029A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108NS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR030A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR031B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-375-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR035A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JY-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-026
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 253

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 400

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR037B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TP-115-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-010
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR038B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TP-116-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN. 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR040A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108SC-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-016
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR042A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108SC-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-010
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR043A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108SC-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2.3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 401

INSPEC: Y

SUPPORT NO 2SWPPSR046A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108MU-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-009
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR047A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108MU-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-016
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR049A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108MU-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-010
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR050A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108MU-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-008
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR051A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108MW-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-009
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 402

INSPEC: Y

SUPPORT NO 2SWPPSR052A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108MW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR061B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-357-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR062B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-360-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR077B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-089-S2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR078B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-090-S2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 403

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR080A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108MX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR081A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108MX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR083B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-106-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR084B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-353-S4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR086B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-111-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 404

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR087B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-112-S2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR089B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-123-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR090B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-124-S4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR099A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1000A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WJ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 405

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1002A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WL-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-156
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1003A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WL-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-063
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1004A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WL-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-151
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1005A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WL-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-155
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR101A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-025
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 406

INSPEC: Y

SUPPORT NO 2SWPPSR1016A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WT-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1017A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WT-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1024A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WZ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1025A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WZ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1026A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XA-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 279

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 407

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR104B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TP-826-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-025
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1043A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19XJ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-159
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 303

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1044A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19XJ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-156
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 303

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1045A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19XK-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-156
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1047A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19XK-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-159
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 408

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1049A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19XL-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-159
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 301

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR10583 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TP-829-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-024
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1050A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19XL-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-158
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1054A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108JW-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-016
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1055A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108JW-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-009
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 409

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1057A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR106B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-830-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1067A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1072A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19YA-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1085A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19-YG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 410

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1088A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19YJ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-155
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR109A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108NP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR111A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-011
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1110A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19YW-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-160
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 290

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR112A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-012
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 411

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR113B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TP-449-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-012
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR114A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108KF-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-012
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR115B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TP-468-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-012
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR116A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108KR-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-012
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR1167A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108PL-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKND
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-024
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 412

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSR1168A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108PV-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-024		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	245		
SUPPORT NO	2SWPPSR1176A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108NL-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-025		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	254		
SUPPORT NO	2SWPPSR1177A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108QA-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-014		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	246		
SUPPORT NO	2SWPPSR1180A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108QA-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-013		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	246		
SUPPORT NO	2SWPPSR119A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108PU-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-025		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	245		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 413

INSPEC: Y

SUPPORT NO 2SWPPSR120A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108PU-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-024
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR122A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108MF-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-024
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1223A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108RB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1224A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108RC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-024
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1225A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108RE-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-016
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC9L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 414

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1226A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RF-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP. MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1227A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1228A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RH-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1229A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RJ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR123A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 415

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1230A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RK-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1234A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1238A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1239A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR124A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 416

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1241A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SH-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1242A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SH-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1243A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SL-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1244A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SL-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1245A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SM-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-013
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 417

INSPEC: Y

SUPPORT NO 2SWPPSR1246A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SM-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-014
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1248A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SN-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1249A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SN-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR125A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108PL-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-025
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1250A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 418

INSPEC: Y

SUPPORT NO 2SWPPSR1251A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SQ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSR1258A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSR1259A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSR1261B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 196-111-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-196
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSR1262B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 196-112-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1.2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-196
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL31

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 419

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1263B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-113-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-197
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1264B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-114-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-197
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 260

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1265B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-115-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-197
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1266B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-116-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-197
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1268B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-118-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-198
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 420

INSPEC: Y

SUPPORT NO	2SWPPSR1269B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-119-6	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-198		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB 271		
SUPPORT NO	2SWPPSR1274B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-124-53	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-198		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB 262		
SUPPORT NO	2SWPPSR1276B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-126-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-198		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB 256		
SUPPORT NO	2SWPPSR1278B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-128-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-199		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB 256		
SUPPORT NO	2SWPPSR1280B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-130-1	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-196		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SDGB 269		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 421

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSR1282B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-132-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2.3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-199		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SDGB	269		
SUPPORT NO	2SWPPSR1287B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-143-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2.3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-194		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SDGB	256		
SUPPORT NO	2SWPPSR1288B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-144-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2.3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-194		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SDGB	256		
SUPPORT NO	2SWPPSR1290B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-146-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-194		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SDGB	264		
SUPPORT NO	2SWPPSR1291B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19G-147-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-194		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SDGB	256		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 422

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1292B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-148-53 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-192
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1293B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-149-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1294B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-150-52 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1296B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-152-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 270

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR130B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-155-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-123
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SBDG 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 423

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1302B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-158-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-192
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1303B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-159-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-190
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1304B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-160-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-190
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1306B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-163-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-190
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1307B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-164-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-194
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 265

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 424

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1309B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-166-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-195
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR133A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BH-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR135A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BH-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-02
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR136A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BH-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-23
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR140A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BJ-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-023
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 425

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR1427A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108UY-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-026
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR143A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108BL-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-02
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1430A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108VA-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-028
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 256

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1431A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108VA-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-029
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR144A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108BL-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-23
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 426

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR146A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BL-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR1471A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR149A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BM-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-02
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR150A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BM-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-23
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR152A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BM-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-04
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC8L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 427

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR163A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BS-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-8
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR166A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BS-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-8
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR168A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BT-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-8
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR169A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BT-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-8
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR171A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BU-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-8
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 236

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 428

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR174A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BV-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR177A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BX-8
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 210

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR182A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108CA-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-002
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR183A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108CA-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-023
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR196A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108CA-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-23
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC9L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 429

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR197A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108CA-7 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-02
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR205A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108CJ-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-02
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR206A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108CJ-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-23
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR215A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19W-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBWELL 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR216A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AZ-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 430

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR218A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AC-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNEWELL 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR226A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AL-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR234A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AU-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR241A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19BB-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-018
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR245A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19JP-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-047
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 431

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR246A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19JG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-047
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR253A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AA-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-020
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR254A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR298A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108EB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-02
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR299A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108EB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-23
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 432

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO' 2SWPPSR312A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-046
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 195

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR341A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108EB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-002
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR342A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108EB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-23
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR374A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19LE-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR379A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19LK-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 433

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR404A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19MD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 220

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR433A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19NB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-045
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR444A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108BU-9
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-004
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 236

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR474A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19PB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-047
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 217

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR475A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19PC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-047
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 209

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 434

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR477A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PE-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-059
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR485A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PN-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B,C
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-058
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR491A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PU-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-058
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR493A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PW-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-055
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR496A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PZ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-055
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIEC2L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 435

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR499A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QC-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2.3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-059
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR505A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QJ-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2.3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-055
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR506A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QJ-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2.3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-058
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR508A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QL-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2.3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-056
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR509A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QM-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2.3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-055
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

PAGE 436
SYS: ALL INSPEC: Y

SUPPORT NO 2SWPPSR510A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QM-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-058
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR520A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19GW-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-058
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 243

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR523A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19QZ-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-059
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR524A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19RA-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-055
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 248

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR525A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19RA-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-058
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 247

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 437

INSPEC: Y

SUPPORT NO 2SWPPSR531A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR532A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR540A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GL-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR548A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR549A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RW-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-046
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 438

INSPEC: Y

SUPPORT NO	2SWPPSR550A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HK-6	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-006		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	247		
SUPPORT NO	2SWPPSR551A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HL-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-008		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	257		
SUPPORT NO	2SWPPSR553A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19RY-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-046		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV SEC CONT	194		
SUPPORT NO	2SWPPSR555A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19SA-7	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-050		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	195		
SUPPORT NO	2SWPPSR565A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HP-5	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-006		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	248		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 439

INSPEC: Y

SUPPORT NO 2SWPPSR566A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HQ-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-007
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR567A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HQ-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-007
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR570A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HR-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-007
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR584A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR585A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 440

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR586A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR587A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR588A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-010
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR589A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR590A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108HW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-008
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 441

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR591A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108HW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR592A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108HW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR593A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108HW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR594A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108HW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR595A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108HW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 442

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSR596A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HW-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-010		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	248		
SUPPORT NO	2SWPPSR597A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HW-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-010		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	248		
SUPPORT NO	2SWPPSR598A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HW-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-010		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	248		
SUPPORT NO	2SWPPSR599A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108HW-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-010		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	248		
SUPPORT NO	2SWPPSR627A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19UJ-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-058		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV SEC CONT	242		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 443

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR628A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19UJ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-055
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR650A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108JM-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-146
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR653A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19VH-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-060
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 193

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR662A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108JG-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-146
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR663A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19VQ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-060
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 211

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 444

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSR664A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	10BJK-6	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-006		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	248		
SUPPORT NO	2SWPPSR690A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111BE-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR692A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111BF-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1,2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR693A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111BG-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR694A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111BH-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 445

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR695A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 111BJ-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-107
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR696A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 111BK-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-107
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR697A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 111H-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-107
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR698A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 111J-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-107
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR699A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 111K-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-107
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 446

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSR700A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111L-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR701A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111M-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR702A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111N-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR703A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111P-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		
SUPPORT NO	2SWPPSR704A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	111Q-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-107		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	250		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 447

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR705A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111S-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-107
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR706A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111T-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-107
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR707A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111U-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-107
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR708A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-106
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR709A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111W-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-106
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 448

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR710A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111X-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR711A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111Y-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR712A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111Z-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR713A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AA-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR714A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AJ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 449

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR715A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR716A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AD-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR717A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AE-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR718A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AF-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2.3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR719A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AG-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2.3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 450

SELECTIONS - SORT: BY: SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR720A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AH-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR721A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AR-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR722A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AK-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR723A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AL-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR724A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AM-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL2:

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 451

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR725A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AN-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR726A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AP-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR727A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AQ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR729A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AT-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR730A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AU-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 492

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR731A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AV-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR732A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AW-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR733A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AX-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-106
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR734A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111BE-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-105
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNBWELL 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR736A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111BG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-105
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 453

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR737A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BH-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR738A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BJ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR739A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BK-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR740A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111H-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR741A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111J-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 454

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR742A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111K-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-105
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR743A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111L-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-105
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR744A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111M-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-105
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR745A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111N-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-105
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR746A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111P-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-105
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE .. 435

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR747A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111G-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR748A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111S-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR749A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111T-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR750A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111U-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR751A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 456

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR752A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111W-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR753A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111X-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR754A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111Y-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR755A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111Z-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR756A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AA-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC2L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 457

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR757A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AJ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR758A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR759A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR760A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR761A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 458

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR762A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AG-4 EXAM CODE 1980 WBO
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR763A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AH-2 EXAM CODE 1980 WBO
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR764A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AR-2 EXAM CODE 1980 WBO
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR765A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AK-2 EXAM CODE 1980 WBO
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR766A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 111AL-2 EXAM CODE 1980 WBO
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-104
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 459

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR767A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR768A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR769A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AP-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR770A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AQ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR772A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 460

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR773A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR774A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR775A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR777A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-104
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR808A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19DX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-048
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 461

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR809A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19DY-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR810A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19DZ-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR814A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19ED-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR815A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EE-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-048
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR816A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EF-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-049
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 462

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR817A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EG-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-049
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR821A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EM-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-051
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR822A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EN-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-051
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR833A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19EY-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-53
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 205

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR835A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FA-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 201

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 463

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR836A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FB-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR837A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FE-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR841A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR843A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FJ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-046
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR845A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FL-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-047
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 464

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR846A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FM-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-046
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR847A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FN-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-046
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR851A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FR-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-047
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR852A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR853A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111AY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-107
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNWELL 250

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 465

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR855A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-051
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR856A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FW-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-051
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR857A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FX-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-052
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR860A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GA-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-046
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR863A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GD-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 466

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR865A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19GF-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-053
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR881A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19GW-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-039
WELDED ATTACH N
LOCAT BUILD/ELEV NAB 218

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS NO WELD

SUPPORT NO 2SWPPSR888A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19HD-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-039
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR889A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19HE-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-039
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR890A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19HF-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-039
WELDED ATTACH N
LOCAT BUILD/ELEV NAB 208

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 467

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR891A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19HG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH Y
 LOCAT BUILD/ELEV NAB 189

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR897A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19HN-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 192

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR969A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VQ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 211

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR970A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VX-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 236

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR971A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VX-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2.3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 236

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 468

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR972A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VY-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR973A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VY-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR983A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-065
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR984A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-062
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSR985A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WE-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

SYS: ALL

PAGE 469
INSPEC: Y

SUPPORT NO 2SWPPSR988A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WF-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-063
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR989A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WG-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-063
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR991A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WD-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-057
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR992A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WD-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-054
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR994A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WH-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-063
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 470

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSR995A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WH-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-057
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR996A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WH-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-054
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR997A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WJ-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-156
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR998A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WJ-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-063
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSR999A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WJ-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-057
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIEC2L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 471

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH1027A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XA-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 276

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH1052A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH1076A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ZM-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 281

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH1078A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ZN-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 282

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH1148A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AAC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-062
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 269

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 472

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH1272B3
SYSTEM CODE SWP
BZ SUPPORT DWG 19G-122-S5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-198
WELDED ATTACH Y
LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH172A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108BU-9
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-004
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 231

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH175A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108BW-7
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-003
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 215

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH208A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19BY-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-020
WELDED ATTACH Y
LOCAT BUILD/ELEV SCRNEWELL 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH214A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19AY-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-017
WELDED ATTACH Y
LOCAT BUILD/ELEV SCRNEWELL 247

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 473

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH219A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AD-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-019
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH222B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-035-8
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-019
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH224A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AJ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH227A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XU-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSH229B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-037-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-017
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 474

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH230A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19A0-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-021
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SCRNEWELL 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH236B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19G-038-6 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-021
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH237B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19G-039-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-021
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH239A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19AY-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-018
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SCRNEWELL 247

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH243B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19G-053-6 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-018
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 475

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH244B3
SYSTEM CODE SWP
BZ SUPPORT DWG 19G-054-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-018
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH248A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108CX-6
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-003
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH249A3
SYSTEM CODE SWP
BZ SUPPORT DWG 108CX-6
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-004
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH255A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19BV-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-020
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH256A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19BW-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-017
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 476

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSSH257A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19CD-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1, 2, 3, 4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B, C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3, 4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-020		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SCRNWELL 244		
SUPPORT NO	2SWPPSSH258A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19CE-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1, 2, 3, 4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B, C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3, 4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-022		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	SCRNWELL 265		
SUPPORT NO	2SWPPSSH265A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19CM-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1, 2, 3, 4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B, C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3, 4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-022		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	SCRNWELL 265		
SUPPORT NO	2SWPPSSH267A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19CP-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1, 2, 3, 4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B, C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3, 4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-022		
VESSEL		WELDED ATTACH	N		
HEX		LOCAT BUILD/ELEV	SCRNWELL 265		
SUPPORT NO	2SWPPSSH313A3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	19UD-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-1, 2, 3, 4	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B, C	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3, 4	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	2 SPRINGS
INT ATT		ISO DWG	021-046		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV	SEC CONT 206		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 477
INSPC: Y

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

SUPPORT NO 2SWPPSSH434A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19NC-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-045
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS

SUPPORT NO 2SWPPSSH435A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19NC-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-045
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS

SUPPORT NO 2SWPPSSH451A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19NM-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-053
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 220

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS

SUPPORT NO 2SWPPSSH562A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19SH-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-059
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS

SUPPORT NO 2SWPPSSH654A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19VJ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-056
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REG N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 478

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH688A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19BT-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM B-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-045
WELDED ATTACH N
LOCAT BUILD/ELEV NAB 181

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH844A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19FK-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-050
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH874A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19GP-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3,4
EXAM CAT F-C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-049
WELDED ATTACH N
LOCAT BUILD/ELEV SAB 181

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH892A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19HH-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-039
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSSH949A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19TA-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 021-039
WELDED ATTACH Y
LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE: 479

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSH975A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108JS-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-032
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSSP1035A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XF-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-022
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1036A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XG-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-022
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1037A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XG-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-022
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1038A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19CJ-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-022
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIEC2L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 480

INSPEC: Y

SUPPORT NO 2SWPPSSP1053A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XP-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-022
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1075A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WT-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-060
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1077A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WT-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-064
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 289

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1086A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19-YG-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-054
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 293

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1147A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AAB-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-062
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 269

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 481

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP1160A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108MT-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1162A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108MZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1169A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SWPPSSP1170A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AAS-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-062
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 266

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1171A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 482

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP1172A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PY-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1173A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1212A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108GU-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1213A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108GU-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1216A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108GW-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 483

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP1217A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108GW-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1247A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SM-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-014
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SWPPSSP1252A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SWPPSSP1254A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SWPPSSP1257A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 484

INSPEC: Y

SUPPORT NO 2SWPPSSP1260A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108SZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 249

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=2

SUPPORT NO 2SWPPSSP1270B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-120-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-198
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1271B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-121-S3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-198
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1286B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-134-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-198
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1316A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TL-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 485

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP1317A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2SWPPSSP1346B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-173-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-193
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1489A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 258

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1490A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-028
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 257

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1595A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 486

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP1627A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1628A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1632A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108VC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 21-27
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1634A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581L-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-125
 WELDED ATTACH Y
 LOCAT BUILD/ELEV CBDG 271

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP1646A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 21-107
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 497

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP228A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AN-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-017
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP235A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP242A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19BC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP251A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108CY-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-004
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP252A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108CY-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-003
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 488

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP259A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19CF-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNEWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP262A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19CJ-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-022
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNEWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP263A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19CK-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNEWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP264A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19CL-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNEWELL 262

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP266A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19CN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNEWELL 265

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 489

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP436A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ND-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-045
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP437A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ND-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-045
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 192

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP457A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19NP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 21-56
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP458A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19NQ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP630A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UL-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 490

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP631A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP634A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UG-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP635A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP636A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP635A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VK-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 262

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 491

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSSP656A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VL-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP658A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VN-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-150
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 189

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP848A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BL-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 21-106
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNNEL 250

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP854A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-107
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SCRNBELL 250

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

SUPPORT NO 2SWPPSSP873A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 111BN-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-105
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
 HIGH RAD ZONE N
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 492

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSST059A3	VALVE	
SYSTEM CODE	SWP	PUMP	
BZ SUPPORT DWG	108ME-2	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	021-007
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV TUNN	254

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST060A3	VALVE	
SYSTEM CODE	SWP	PUMP	
BZ SUPPORT DWG	108MC-3	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	021-007
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV TUNN	254

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST072B3	VALVE	
SYSTEM CODE	SWP	PUMP	
BZ SUPPORT DWG	108TP-371-5	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	021-007
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV TUNN	254

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST073A3	VALVE	
SYSTEM CODE	SWP	PUMP	
BZ SUPPORT DWG	108MD-3	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	021-007
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV TUNN	254

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST1008A3	VALVE	
SYSTEM CODE	SWP	PUMP	
BZ SUPPORT DWG	19WP-3	EXAM CODE	1980 W80
CODE CLASS	3	EXAM ITEM	F-1,2,3
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B
PIPE	X	EXAM METHOD	VT-3
SNUBBER		EXAM PROCEDURE	LTR
INT ATT		ISO DWG	021-151
VESSEL		WELDED ATTACH	N
HEX		LOCAT BUILD/ELEV SEC CONT	299

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIEC5L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 493

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1009A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WP-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-151
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1010A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WQ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-159
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1011A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WQ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-159
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1012A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WR-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-156
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1013A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19WR-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-156
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21.

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 494

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1014A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-155
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1015A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-155
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1028A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-065
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 285

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1029A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-065
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 285

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1030A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XC-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-062
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 284

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL31

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 495

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1031A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XC-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-062
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 285

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1032A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XD-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1033A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XD-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-064
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1034A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-060
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 300

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1040A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19XH-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-159
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 303

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 496

INSPEC: Y

SUPPORT NO 2SWPPSST1051A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XM-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-064
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1058A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XT-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-158
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1059A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19XT-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-158
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 298

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1092A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19YM-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-159
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 302

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1093A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19YN-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-156
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 302

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 497

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1136A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19ZS-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-065
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 269

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1139A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19ZT-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-065
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 269

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1151A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19AAE-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-062
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV SEC CONT 269

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1153A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19AAG-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-062
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 269

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1155A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19AAJ-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-062
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV PRI CONT 267

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 498

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST116B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-112-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-127
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1218A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108QX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1231A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108RV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1236A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PD-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-006
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST124B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-149-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-121
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 499

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1253A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SU-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1256A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108SX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST126B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-151-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-121
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1267B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-117-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-197
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST127B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-152-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-121
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 500

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1273B3
SYSTEM CODE SWP
BZ SUPPORT DWG 190-123-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-198
WELDED ATTACH N
LOCAT BUILD/ELEV SDGB 267

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1275B3
SYSTEM CODE SWP
BZ SUPPORT DWG 190-125-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-198
WELDED ATTACH N
LOCAT BUILD/ELEV SDGB 256

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1277B3
SYSTEM CODE SWP
BZ SUPPORT DWG 190-127-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-198
WELDED ATTACH N
LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1279B3
SYSTEM CODE SWP
BZ SUPPORT DWG 190-129-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-196
WELDED ATTACH Y
LOCAT BUILD/ELEV SDGB 269

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST128B3
SYSTEM CODE SWP
BZ SUPPORT DWG 581G-153-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-164
WELDED ATTACH N
LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING -- COMPONENT SUPPORTS

PAGE 501

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1281B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-131-53 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-199
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 269

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSST1285B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-133-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-197
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSST1295B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-151-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSST1297B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-153-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWPPSST1298B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-154-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 502

INSPEC: Y

SUPPORT NO 2SWPPSST1299B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-155-56 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1300B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-156-53 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1301B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-157-52 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-192
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1305B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-162-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-190
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1308B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-165-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-194
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 503

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1311A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AAX-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-065
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 267

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1312A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AAY-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-065
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1314A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19ABA-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-065
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 264

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST132A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108NZ-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1334B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-169-52 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-190
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 504

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST134483
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-171-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-191
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 271

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST134583
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-172-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-193
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST134783
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-174-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-199
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 269

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST134883
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-175-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-196
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 269

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST134983
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-176-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-193
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 272

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 505

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1350B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-177-52 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-190
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1351B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-178-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-192
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 264

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1353B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-180-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-198
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 262

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1354B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-181-53 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-193
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 268

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1355B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-161-53 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-190
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SDGB 265

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 506

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1366A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ABE-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1425A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108UX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-111
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1426A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108UX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-111
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1605A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ACM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-151
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST1606A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ACM-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-155
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 507

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST1607A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19ACN-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-155
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 299

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST1636A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19CC-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-20
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNEWELL 238

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST207A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19BZ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-020
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNEWELL 226

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST211A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19CB-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-020
WELDED ATTACH Y
LOCAT BUILD/ELEV SCRNEWELL 229

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST212A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19CC-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-020
WELDED ATTACH N
LOCAT BUILD/ELEV SCRNEWELL 239

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 508

INSPEC: Y

SUPPORT NO 2SWPPSST217A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19BA-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST220A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AE-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 232

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST223A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AH-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 243

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST225A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AK-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 232

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST231A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19AR-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-021
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNWELL 239

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 509

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST232A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AS-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBELL 238

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST233A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19AT-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBELL 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST240A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19Z-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-018
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNBELL 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST401A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19MB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 181

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST402A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19MC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 510

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST403A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19MC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV SAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST407A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ME-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST408A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19ME-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST459A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19NR-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST460A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19NS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 511

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST461A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NT-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST462A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NU-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST463A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NV-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST464A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NW-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST465A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 512

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST466A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3,4
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST467A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NY-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST468A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NY-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST469A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NZ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST470A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19NZ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 513

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST471A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19PA-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST472A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19PA-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST476A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19PD-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-047
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 207

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST479A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19PG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST480A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19PH-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 514

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST481A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PJ-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-056
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST482A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PJ-5
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-059
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST483A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PL-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-059
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST484A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PM-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-056
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST486A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19PP-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-056
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 515

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST487A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19PG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST490A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19PT-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST494A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19PX-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST495A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19PY-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST497A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 516

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST498A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19QB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-055
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST501A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19QE-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 251

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST502A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19QF-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 253

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST503A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19QG-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-059
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST504A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19QH-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-056
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 517

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST507A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 190K-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST511A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GN-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST517A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST518A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19QT-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-056
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 249

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST526A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 518

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST527A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST535A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RH-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST536A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RJ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST554A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19RZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 206

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST556A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19SB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-050
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 188

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 519

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST563A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19SJ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-055
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST564A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19SK-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-058
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST637A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19US-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-059
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST640A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19UZ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST641A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VA-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 520

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST643A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST644A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST645A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST646A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-057
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST647A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19VF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-054
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 521

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST648A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19VG-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-054
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST659A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19VP-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-064
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 202

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST660A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19VP-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-064
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 203

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST682A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19BM-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-045
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 186

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST683A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19BN-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-045
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 188

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 522

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWPPSST684A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19BP-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-045	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	184

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST685A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19BQ-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-045	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	184

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST686A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19BR-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-045	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	181

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST687A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19BS-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-045	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	181

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	2SWPPSST689A3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19BU-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-045	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	NAB	183

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 523

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST691A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111R-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-107
WELDED ATTACH Y
LOCAT BUILD/ELEV SCRNBELL 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST728A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111AS-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-106
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 243

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST735A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111V-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-105
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 250

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST776A3
SYSTEM CODE SWP
BZ SUPPORT DWG 111BC-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-104
WELDED ATTACH N
LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST791B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TP-391-6
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 21-07
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 524

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST811A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19EA-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-048
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST812A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19EB-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-048
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST813A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19EC-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-048
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST819A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19EJ-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-060
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWPPSST820A3
SYSTEM CODE SWP
BZ SUPPORT DWG 19EK-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-060
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 525

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST823A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19EP-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST824A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19EQ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-051
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST834A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19EZ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 205

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST837A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 187

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST838A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19FD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 185

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 526

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST840A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FF-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-053
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 183

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST849A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FP-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST850A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FQ-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-046
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 191

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST858A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19FY-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-052
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST861A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 527

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST867A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GH-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST868A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GJ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SAB 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST870A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GL-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-050
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 190

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST871A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GM-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-052
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 182

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST875A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GQ-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-045
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 184

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 528

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPIC: Y

SUPPORT NO 2SWPPSST876A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GR-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST877A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST878A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GT-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST879A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GU-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST880A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19GV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 221

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 529

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST883A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GY-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-039
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST884A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19GZ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-039
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST885A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19HA-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-039
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST886A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19HB-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-039
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST887A3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19HC-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-039
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV NAB 233

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 530

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST893A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19HJ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-039
 WELDED ATTACH N
 LOCAT BUILD/ELEV NAB 181

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST901A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19EZ-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-053
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 205

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST977A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST978A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WA-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWPPSST979A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19WB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-063
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 531

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWPPSST980A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19WB-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-063
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SEC CONT 297

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR001B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TQ-705-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-012
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR002B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TQ-707-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-011
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR004B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TQ-725-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-029
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR005B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TQ-726-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-028
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 532

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWQPSR006B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108TG-732-2	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-027		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	242		
SUPPORT NO	2SWQPSR007B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108TG-733-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-026		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	240		
SUPPORT NO	2SWQPSR008B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108TG-740-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-029		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	246		
SUPPORT NO	2SWQPSR009B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108TG-741-3	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-028		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	244		
SUPPORT NO	2SWQPSR010B3	VALVE		ACCESS/INACCESS	A
SYSTEM CODE	SWP	PUMP		HIGH RAD ZONE	
BZ SUPPORT DWG	108TG-742-4	EXAM CODE	1980 W80	REMOVE FOR EXAM	N
CODE CLASS	3	EXAM ITEM	F-2,3	DESIGN SPEC	NMP2-P301N
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	INSTALL SPEC	NMP2-P301J
PIPE	X	EXAM METHOD	VT-3	RELIEF REQ	N
SNUBBER		EXAM PROCEDURE	LTR	REMARKS	
INT ATT		ISO DWG	021-026		
VESSEL		WELDED ATTACH	Y		
HEX		LOCAT BUILD/ELEV TUNN	240		

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 532

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25WQPSR011B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TQ-743-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-027
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR012B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TQ-754-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-029
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR013B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TQ-755-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-028
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR014B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TQ-756-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-026
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR015B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 108TQ-757-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-027
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85 PRESERVICE TESTING - COMPONENT SUPPORTS
SELECTIONS - SORT: BY SYS CODE CLASS: ALL DATE: ALL

PAGE 534
SYS: ALL INSPEC: Y

SUPPORT NO 2SWQPSR016B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TG-768-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-029
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWQPSR017B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TG-769-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-028
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWQPSR018B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TG-770-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-026
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWQPSR019B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TG-771-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-027
VESSEL WELDED ATTACH Y
HEX LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWQPSR020A3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108JZ-4 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-029
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE . 535

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWGPSR021A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JZ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-028
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSR022A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JZ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-026
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSR023A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JZ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-027
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSR024B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TQ-795-S3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSR025B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TQ-796-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-028
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 536

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSR026B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-797-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-026
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR027B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-798-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-027
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR028A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-029
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR029A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-028
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSR030B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-374-7
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 537

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSR031A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KD-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-027
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR032A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-029
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 258

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR033A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-028
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR034A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-027
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR036B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-830-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-29
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 538

INSPEC: Y

SUPPORT NO 2SWGPSR037B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TQ-831-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 21-28
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 257

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR038B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TQ-835-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 21-27
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR039B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TQ-836-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 021-026
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 253

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR040B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TQ-840-4
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 21-29
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 259

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2SWGPSR041B3
SYSTEM CODE SWP
BZ SUPPORT DWG 108TQ-841-2
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-2,3
EXAM CAT F-B
EXAM METHOD VT-3
EXAM PROCEDURE LTR
ISO DWG 21-28
WELDED ATTACH Y
LOCAT BUILD/ELEV TUNN 257

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 539

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25WQPSR042B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-844-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-27
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR043B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-845-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-26
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR044B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-848-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-27
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR045B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-849-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-28
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WQPSR046B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-852-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-27
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 540

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSR047B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TG-853-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-26
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR098B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-089-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-126
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 266

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR101B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-092-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-126
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR102B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-093-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-126
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR107B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-098-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 277

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 541

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSR117B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-113-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-127
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR187A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PP-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR193A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KG-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-011
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 244

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR194A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KG-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSR195A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108KG-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 542

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSR197A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR198A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 247

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR199A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 248

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR200A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR528B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TR-140-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-025
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 208

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 543

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSR532B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-092-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-117
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNBELL 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR543B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-103-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 231

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR550B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-110-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 226

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR758B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-022-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-134
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

SUPPORT NO 2SWQPSR759B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-023-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-134
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 544

INSPEC: Y

SUPPORT NO	25WQPSR760B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	581G-024-4	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-134	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SDGB	256

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	25WQPSSH542B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-102-4	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-020	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SCRNWELL	226

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	25WQPSSH544B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-104-4	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-017	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SCRNWELL	226

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	25WQPSSH546B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-106-3	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-021	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	SCRNWELL	263

ACCESS/INACCESS	A
HIGH RAD ZONE	
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

SUPPORT NO	25WQPSSP538B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-098-4	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-019	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SCRNWELL	236

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 545

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO	2SWGPSSP539B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-097-3	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-019	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SCRNWELL 226	

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2SWGPSSP540B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-100-2	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-020	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	SCRNWELL 231	

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2SWGPSSP547B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-107-4	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-021	
VESSEL		WELDED ATTACH	N	
HEX		LOCAT BUILD/ELEV	SCRNWELL 226	

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2SWGPSSP548B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	19G-108-5	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3,4	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B,C	
PIPE	X	EXAM METHOD	VT-3,4	
SNUBBER	X	EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-021	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	SCRNWELL 226	

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	Y
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	DR=1

SUPPORT NO	2SWGPSSST060B3	VALVE		
SYSTEM CODE	SWP	PUMP		
BZ SUPPORT DWG	581G-004-5	EXAM CODE	1980 W80	
CODE CLASS	3	EXAM ITEM	F-1,2,3	
TYPE OF SUPPORT/COMP MKNO		EXAM CAT	F-B	
PIPE	X	EXAM METHOD	VT-3	
SNUBBER		EXAM PROCEDURE	LTR	
INT ATT		ISO DWG	021-131	
VESSEL		WELDED ATTACH	Y	
HEX		LOCAT BUILD/ELEV	CBDG 255	

ACCESS/INACCESS	A
HIGH RAD ZONE	N
REMOVE FOR EXAM	N
DESIGN SPEC	NMP2-P301N
INSTALL SPEC	NMP2-P301J
RELIEF REQ	N
REMARKS	

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 546

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWGPSST061B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-005-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-131
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSST062B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-131
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSST066B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-017-6 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-134
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSST067B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-018-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-134
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWGPSST068B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-019-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-134
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 547

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSST069B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-020-S5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-134
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST1214A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JZ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-26
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST1215A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108JZ-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-27
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST125B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-150-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-121
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST175B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 19G-055-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-118
 WELDED ATTACH N
 LOCAT BUILD/ELEV SCRNWELL 242

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 548

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25WQPSST525B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TR-137-2 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-025
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 252

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25WQPSST526B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TR-138-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-025
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 230

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25WQPSST527B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TR-139-3 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-025
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 211

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25WQPSST530B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 108TR-142-1 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-025
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV TUNN 254

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 25WQPSST533B3 VALVE
SYSTEM CODE SWP PUMP
BZ SUPPORT DWG 19G-093-5 EXAM CODE 1980 W80
CODE CLASS 3 EXAM ITEM F-1,2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 021-117
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV SCRNEWELL 240

ACCESS/INACCESS A
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 549

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSST534B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-094-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-117
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST536B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-096-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-117
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST537B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-097-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-117
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 240

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST541B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-101-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-020
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SCRNBELL 229

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST545B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 19G-105-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-017
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 260

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 550

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWQPSST549B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 190-109-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-018
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SCRNBELL 241

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWQPSST757B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-021-S5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-134
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 256

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR753B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-007-0 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-131
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR754B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-008-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 21-131
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR755B3 VALVE
 SYSTEM CODE SWP PUMP
 BZ SUPPORT DWG 581G-009-5 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-2,3
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
 PIPE X EXAM METHOD VT-3
 SNUBBER EXAM PROCEDURE LTR
 INT ATT ISO DWG 021-131
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV CBDG 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 551

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWRPSR75683
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-010-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-131
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 256

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR763A3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108PW-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-016
 WELDED ATTACH N
 LOCAT BUILD/ELEV TUNN 246

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR773B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-107-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-127
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR774B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-108-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-127
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR775B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-109-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-127
 WELDED ATTACH Y
 LOCAT BUILD/ELEV CBDG 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC8L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE . 552

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2SWRPSR776B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-110-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-127
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR777B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-111-5
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-127
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR778B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-144-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-121
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR780B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-146-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-121
 WELDED ATTACH Y
 LOCAT BUILD/ELEV SDGB 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2SWRPSR781B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-147-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-121
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 257

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIEC8L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 553

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 25WRPSR782B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-148-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B,C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-121
 WELDED ATTACH N
 LOCAT BUILD/ELEV CBDG 255

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WRPSR793B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-775-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 21-25
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 245

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WRPSR806B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 108TP-151-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-024
 WELDED ATTACH Y
 LOCAT BUILD/ELEV TUNN 222

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 25WRPSST779B3
 SYSTEM CODE SWP
 BZ SUPPORT DWG 581G-145-S3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 021-121
 WELDED ATTACH N
 LOCAT BUILD/ELEV SDGB 259

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSR571A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FB-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 554

INSPEC: Y

SUPPORT NO 2WCSPSR582A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FM-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-C
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSR588A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FU-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSR634A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSR635A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSR660A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74JU-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 555

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSR661A1 VALVE
SYSTEM CODE WCS PUMP
BZ SUPPORT DWG 74JV-1 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-2,3
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B
PIPE X EXAM METHOD VT-3
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 009-006
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2WCSPSSH561A1 VALVE
SYSTEM CODE WCS PUMP
BZ SUPPORT DWG 74ER-5 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 009-006
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2WCSPSSH566A1 VALVE
SYSTEM CODE WCS PUMP
BZ SUPPORT DWG 74EW-3 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 009-006
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2WCSPSSH572A1 VALVE
SYSTEM CODE WCS PUMP
BZ SUPPORT DWG 74FC-4 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 009-006
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

SUPPORT NO 2WCSPSSH590A1 VALVE
SYSTEM CODE WCS PUMP
BZ SUPPORT DWG 74FW-3 EXAM CODE 1980 W80
CODE CLASS 1 EXAM ITEM F-1,2,3,4
TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
PIPE X EXAM METHOD VT-3,4
SNUBBER EXAM PROCEDURE LTR
INT ATT ISO DWG 009-006
VESSEL WELDED ATTACH N
HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE
REMOVE FOR EXAM N
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 596

INSPEC: Y

SUPPORT NO 2WCSPSSH599A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GF-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH605A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GM-4
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH610A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH613A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GV-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH616A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GY-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 557

INSPEC: Y

SUPPORT NO 2WCSPSSH619A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HB-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH621A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HD-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH625A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HH-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH696A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH698A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LJ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 598

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSH716A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74MB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 254

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH721A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74MG-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH878A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SW-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 100-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSH891A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 94-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSP1116A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ABJ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 559

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP1121A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ABN-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP562A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ES-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP565A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74EV-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP567A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74EX-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-006
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 261

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP568A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74EY-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 560

INSPEC: Y

SUPPORT NO 2WCSPSSP569A1
SYSTEM CODE WCS
BZ SUPPORT DWG 74EZ-4
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-005
WELDED ATTACH Y
LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP573A1
SYSTEM CODE WCS
BZ SUPPORT DWG 74FD-3
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-006
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP579A1
SYSTEM CODE WCS
BZ SUPPORT DWG 74FK-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-006
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP580A1
SYSTEM CODE WCS
BZ SUPPORT DWG 74FL-2
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-006
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP581A1
SYSTEM CODE WCS
BZ SUPPORT DWG 74FN-1
CODE CLASS 1
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-006
WELDED ATTACH N
LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 561

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP583A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FP-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP584A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FG-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP586A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP589A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FV-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP591A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FX-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 562

INSPEC: Y

SUPPORT NO 2WCSPSSP592A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FY-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP593A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 257

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP594A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GA-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 256

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP595A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GB-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP596A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GC-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 247

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 563

INSPEC: Y

SUPPORT NO 2WCSPSSP597A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GD-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP598A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP600A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GG-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP601A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP603A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 564

INSPEC: Y

SUPPORT NO 2WCSPSSP604A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74GL-2 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP606A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74GN-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP607A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74GP-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP608A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74GQ-3 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP609A1 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74GR-1 EXAM CODE 1980 W80
 CODE CLASS 1 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-005
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 565

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP612A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GU-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP614A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GW-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP615A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP617A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GZ-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP618A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HA-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 566

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP620A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HC-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP622A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HE-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP623A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HF-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP626A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HJ-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP695A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LF-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 567

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP697A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP699A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LK-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 254

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP701A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LM-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP704A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LQ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP705A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LR-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 568

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP707A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LT-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP712A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LX-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP713A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LY-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 261

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP714A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LZ-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 255

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP715A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74MA-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 254

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIEC3L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 569

INSPEC: Y

SUPPORT NO 2WCSPSSP719A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ME-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP720A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74MF-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP722A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74MH-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 252

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP862A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP874A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SS-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 100-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 570

INSPEC: Y

SUPPORT NO 2WCSPSSP886A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TE-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 94-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 244

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP928A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UX-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 12-A
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 243

ACCESS/INACCESS I
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSST570A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FA-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSST574A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FE-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSST575A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FF-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 571

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSST585A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FR-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSST587A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FT-3
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-006
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 263

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSST611A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74GT-2
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-005
 WELDED ATTACH N
 LOCAT BUILD/ELEV PRI CONT 245

ACCESS/INACCESS I
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSST703A1
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74LP-1
 CODE CLASS 1
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3
 EXAM CAT F-B
 EXAM METHOD VT-3
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 263

ACCESS/INACCESS A
 HIGH RAD ZONE
 REMOVE FOR EXAM N
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS

SUPPORT NO 2WCSPSSP1002A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 317

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 572

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP1007A3
SYSTEM CODE WCS
BZ SUPPORT DWG 74XZ-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-013
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 317

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP1010A3
SYSTEM CODE WCS
BZ SUPPORT DWG 74YC-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-024
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 334

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP1011A3
SYSTEM CODE WCS
BZ SUPPORT DWG 74YD-3
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-024
WELDED ATTACH Y
LOCAT BUILD/ELEV SEC CONT 334

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP1014A3
SYSTEM CODE WCS
BZ SUPPORT DWG 74YG-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-031
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

SUPPORT NO 2WCSPSSP1016A3
SYSTEM CODE WCS
BZ SUPPORT DWG 74YJ-1
CODE CLASS 3
TYPE OF SUPPORT/COMP MKNO
PIPE X
SNUBBER X
INT ATT
VESSEL
HEX

VALVE
PUMP
EXAM CODE 1980 W80
EXAM ITEM F-1,2,3,4
EXAM CAT F-B,C
EXAM METHOD VT-3,4
EXAM PROCEDURE LTR
ISO DWG 009-031
WELDED ATTACH N
LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
HIGH RAD ZONE Y
REMOVE FOR EXAM Y
DESIGN SPEC NMP2-P301N
INSTALL SPEC NMP2-P301J
RELIEF REQ N
REMARKS DR=3

NINE MILE POINT-UNIT 2

PIEC8L21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 573

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP1018A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74YL-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-012
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1032A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74YX-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG DP-374T
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 331

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301F
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1035A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZA-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1036A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZA-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-031
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1038A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 340

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 574

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP1039A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ZC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 339

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1040A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ZD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 340

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1041A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ZD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 340

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1042A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ZE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 335

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1044A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ZG-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 330

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 575

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP1046A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZE-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-032
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 335

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1051A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZP-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-034
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1052A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZP-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-034
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 335

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1053A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZQ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-034
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 334

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP1058A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZU-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-033
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 334

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 576

INSPEC: Y

SUPPORT NO 2WCSPSSP1066A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74ZZ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-033
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 334

SUPPORT NO 2WCSPSSP1069A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AAC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-034
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 328

SUPPORT NO 2WCSPSSP1070A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AAD-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-034
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 335

SUPPORT NO 2WCSPSSP1071A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AAD-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-034
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 335

SUPPORT NO 2WCSPSSP1077A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AAJ-3 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-023
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 334

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 577

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP1115A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74YC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 334

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP428A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74J-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP431A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74M-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 220

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP432A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74N-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 224

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP434A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74Q-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 232

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 578

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP447A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AD-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-007
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP452A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AJ-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-014
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 276

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP456A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AN-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-014
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 278

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP457A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AP-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-014
 VESSEL WELDED ATTACH Y
 HEX LOCAT BUILD/ELEV SEC CONT 283

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP460A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74AS-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKNO EXAM CAT F-C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-014
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 302

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 579

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP462A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74AU-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-014
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 310

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP464A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74AW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 316

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP467A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74AZ-6
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP472A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74BE-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP474A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74BG-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 580

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP484A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74BS-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 230

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP490A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74BY-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 223

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP492A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74CA-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP498A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74CG-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 311

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP499A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74CH-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-010
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 310

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 581

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP576A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 243

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP578A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74FJ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 242

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP627A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HK-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-007
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 219

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP631A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-008
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 302

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP638A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74HW-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 312

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 582

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP663A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74JX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 312

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP664A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74JY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 312

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP667A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74KB-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 312

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP668A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74KC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 313

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP669A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74KD-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX
 VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 313

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 583

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP675A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74KK-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 319

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP681A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74KR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 318

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP687A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74KX-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-009
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 313

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP750A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74NC-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 316

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP753A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74NF-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 316

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 584

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP758A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74NL-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 316

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP763A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74NR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-013
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 316

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP818A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74QR-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 342

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP829A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74QY-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 341

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP834A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74RB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 339

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 585

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP842A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74RK-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP864A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SG-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP866A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SJ-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP867A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SK-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP871A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SP-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REG N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 586

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP875A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74ST-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP877A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SV-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 342

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP879A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SX-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 340

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP880A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74SY-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 340

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP887A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TF-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 587

INSPEC: Y

SUPPORT NO 2WCSPSSP894A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TM-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 342

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP895A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TN-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 342

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP896A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 342

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP899A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TT-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 337

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP900A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TT-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKND
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1, 2, 3, 4
 EXAM CAT F-B, C
 EXAM METHOD VT-3, 4
 EXAM PROCEDURE LTR
 ISO DWG 009-021
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 337

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 588

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP901A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TU-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP902A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TV-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP905A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74TY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP910A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UD-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP917A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UL-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 589

INSPEC: Y

SUPPORT NO 2WCSPSSP918A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UM-4
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP920A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UP-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 324

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP921A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UQ-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP922A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UR-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP924A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UT-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 590

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP925A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UU-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-032
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 338

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP926A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UV-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP929A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74UY-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 324

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP932A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VB-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP935A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VE-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 591

INSPEC: Y

SUPPORT NO 2WCSPSSP936A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VF-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP937A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VG-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 330

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP940A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VK-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-022
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 330

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP941A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VL-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP943A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74VN-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-019
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 324

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECLBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

PAGE 592

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

INSPEC: Y

SUPPORT NO 2WCSPSSP946A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74VR-4 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-022
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 329

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP947A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74VS-1 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-022
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 329

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP959A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74WC-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP964A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74WH-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-019
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 324

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP966A3 VALVE
 SYSTEM CODE WCS PUMP
 BZ SUPPORT DWG 74WK-2 EXAM CODE 1980 W80
 CODE CLASS 3 EXAM ITEM F-1,2,3,4
 TYPE OF SUPPORT/COMP MKND EXAM CAT F-B,C
 PIPE X EXAM METHOD VT-3,4
 SNUBBER X EXAM PROCEDURE LTR
 INT ATT ISO DWG 009-024
 VESSEL WELDED ATTACH N
 HEX LOCAT BUILD/ELEV SEC CONT 335

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 593

INSPEC: Y

SUPPORT NO 2WCSPSSP967A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74WL-3
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 336

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP970A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74WP-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 330

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP973A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74WS-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 337

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP976A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74WV-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 329

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP981A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XB-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-012
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 322

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 594

INSPEC: Y

SUPPORT NO 2WCSPSSP982A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XC-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 337

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP984A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XE-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 335

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP985A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XF-2
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-024
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 335

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP991A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 337

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

SUPPORT NO 2WCSPSSP992A3
 SYSTEM CODE WCS
 BZ SUPPORT DWG 74XL-1
 CODE CLASS 3
 TYPE OF SUPPORT/COMP MKNO
 PIPE X
 SNUBBER X
 INT ATT
 VESSEL
 HEX

VALVE
 PUMP
 EXAM CODE 1980 W80
 EXAM ITEM F-1,2,3,4
 EXAM CAT F-B,C
 EXAM METHOD VT-3,4
 EXAM PROCEDURE LTR
 ISO DWG 009-031
 WELDED ATTACH N
 LOCAT BUILD/ELEV SEC CONT 337

ACCESS/INACCESS A
 HIGH RAD ZONE Y
 REMOVE FOR EXAM Y
 DESIGN SPEC NMP2-P301N
 INSTALL SPEC NMP2-P301J
 RELIEF REQ N
 REMARKS DR=3

NINE MILE POINT-UNIT 2

PIECBL21

RUN DATE 12/12/85

PRESERVICE TESTING - COMPONENT SUPPORTS

SELECTIONS - SORT: BY SYS

CODE CLASS: ALL

DATE: ALL

SYS: ALL

PAGE 595

INSPEC: Y

SUPPORT NO 2WCSPSSP998A3

SYSTEM CODE WCS

BZ SUPPORT DWG 74XS-1

CODE CLASS 3

TYPE OF SUPPORT/COMP MKNO

PIPE X

SNUBBER X

INT ATT

VESSEL

HEX

VALVE

PUMP

EXAM CODE 1980 W80

EXAM ITEM F-1,2,3,4

EXAM CAT F-B,C

EXAM METHOD VT-3,4

EXAM PROCEDURE LTR

ISO DWG 009-031

WELDED ATTACH N

LOCAT BUILD/ELEV SEC CONT 329

ACCESS/INACCESS

HIGH RAD ZONE

REMOVE FOR EXAM

DESIGN SPEC NMP2-P301N

INSTALL SPEC NMP2-P301J

RELIEF REQ N

REMARKS DR=3

