

THE CHURCH OF  
**JESUS CHRIST**  
OF LATTER-DAY SAINTS

RUPERT ID FM GROUP  
1814 H Street  
Rupert, Idaho 83350-1054  
Phone: 1-208-434-1421  
Toll free: 1-866-434-1421  
Facsimile: 1-208-434-1423

January 8, 2018

Director of FSME  
Attn: GLTS  
USNRC  
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on January 8, 2018 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Rhonda Shaw @ 208-434-1421.

Sincerely,



Rhonda Shaw  
Rupert ID AA

Encl.

## SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	<del>2430-10000</del> <b>FMACE-235158</b>
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

Heyburn 1,2

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
<del>1</del>	<del>SRB Tech.</del>	<del>B100</del>	<del>578581</del>	<del>08</del>	<del>1994</del>	<del>20 "Ci"</del>
2	SRB Tech.	B100	669522	08	2001	20 "Ci"
3	SRB Tech.	B100	578670	08	1994	20 "Ci"
4	SRB Tech.	B100	578679	08	1994	20 "Ci"
5	SRB Tech.	B100	578678	08	1994	20 "Ci"
6	SRB Tech.	B100	578664	08	1994	20 "Ci"
7	SRB Tech.	B100	578665	08	1994	20 "Ci"
8	SRB Tech.	B100	578672	08	1994	20 "Ci"
9	SRB Tech.	B100	578666	08	1994	20 "Ci"
10	SRB Tech.	B100	667512	04	2001	20 "Ci"
11	SRB Tech.	B100	669647	08	2001	20 "Ci"
12	SRB Tech.	B100	667514	04	2001	20 "Ci"
13	SRB Tech.	B100	667516	04	2001	20 "Ci"
14	SRB Tech.	B100	578671	08	1994	20 "Ci"
15	SRB Tech.	B100	667513	04	2001	20 "Ci"

*\*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

## SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	2430102023
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Tech.	B100	578662	08	1994	20 "Ci"
2	SRB Tech.	B100	578663	08	1994	20 "Ci"
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

*\*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

**Once we have received and processed this information an RMA number will be issued.**

**If you have more signs that this form holds, please copy additional pages and filling all necessary information.**

## SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #s	FMACQ- <del>188175</del> 235162
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@idschurch.org

Lakeview

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	SRB Tech.	B100	599226	11	1995	20 "CI"
2	<del>SRB Tech.</del>	<del>B100</del>	<del>599226</del>	<del>11</del>	<del>1995</del>	<del>20 "CI"</del>
3	SRB Tech.	B100	599228	11	1995	20 "CI"
4	SRB Tech.	B100	599222	11	1995	20 "CI"
5	SRB Tech.	B100	599227	11	1995	20 "CI"
6	SRB Tech.	B100	599224	11	1995	20 "CI"
7	SRB Tech.	B100	599223	11	1995	20 "CI"
8	SRB Tech.	B100	599214	11	1995	20 "CI"
9	SRB Tech.	B100	599219	11	1995	20 "CI"
10	SRB Tech.	B100	599213	11	1995	20 "CI"
11	SRB Tech.	B100	599216	11	1995	20 "CI"
12	SRB Tech.	B100	599220	11	1995	20 "CI"
12	SRB Tech.	B100	599217	11	1995	20 "CI"
14						
15						

\*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

240

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

## SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	10-30-17
Address 1	1814 H Street	Isolite RMA #	
Address 2		EWS Order #	
Address 3		MTS Order #/s	FMACQ- <del>235163</del> 235163
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	ShawR@ldschurch.org

*Rockland*

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SRB Tech.	B100	603987	04	1996	20 "Ci"
2	SRB Tech.	B100	604252	04	1996	20 "Ci"
3	SRB Tech.	B100	604253	04	1996	20 "Ci"
4	SRB Tech.	B100	603990	04	1996	20 "Ci"
5	SRB Tech.	B100	603991	04	1996	20 "Ci"
6	SRB Tech.	B100	603986	04	1996	20 "Ci"
7	SRB Tech.	B100	603989	04	1996	20 "Ci"
8	SRB Tech.	B100	603988	04	1996	20 "Ci"
9	SRB Tech.	B100	604248	04	1996	20 "Ci"
10	SRB Tech.	B100	603983	04	1996	20 "Ci"
11	SRB Tech.	B100	603984	04	1996	20 "Ci"
12	SRB Tech.	B100	603985	04	1996	20 "Ci"
13	SRB Tech.	B100	604249	04	1996	20 "Ci"
14	SRB Tech.	B100	604250	04	1996	20 "Ci"
15	SRB Tech.	B100	604251	04	1996	20 "Ci"

*\*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

300

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.