

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

**REPORT
SOURCE**

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	2	2	0	7	0	3	1	9	7	9	8	0	6	1	4	7	9	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During refueling outage, a Core Spray System snubber, 40-HS-10, was found

0 3 | to be inoperable. This resulted in minimal safety implications.

0 4 |

0 5 |

0 6 |

0 7 |

0 8 |

7 8 9

09		SYSTEM CODE S F		CAUSE CODE E	CAUSE SUBCODE B	COMPONENT CODE S U P P O R T		COMP. SUBCODE D	VALVE SUBCODE Z				
7	8	9	10	11	12	13	14	15	16				
LER/RO REPORT NUMBER 17		EVENT YEAR 7 9			SEQUENTIAL REPORT NO. 0 1 4			OCURRENCE CODE 0 3	REPORT TYPE L	REVISION NO. 0			
21		22		23	24		26	27	28	29	30	31	32
ACTION TAKEN D		FUTURE ACTION Z		EFFECT ON PLANT Z	SHUTDOWN METHOD Z		HOURS 0 0 0 0	ATTACHMENT SUBMITTED N	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER A	COMPONENT MANUFACTURER I 2 0 7		
33	34	35	36	37	38	39	40	41	42	43	44	47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Worn piston seals on Core Spray Snubber 40-HS-10 caused a loss of fluid
1 1 from the snubber thereby making it inoperable. The seals were replaced,
1 2 the snubber was tested for operability, and it was reinstalled. This
1 3 resulted in minimal safety implications.
1 4

8 9
FACILITY STATUS (28) H % POWER (29) 0 0 0 OTHER STATUS (30) NA METHOD OF DISCOVERY (31) B Snubber inspection DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT (33) Z RELEASED OF RELEASE (34) Z AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL EXPOSURES (37) 0 0 0 TYPE (38) Z DESCRIPTION (39) NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL INJURIES (40) 0 0 0 DESCRIPTION (41) NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

LOSS OF OR DAMAGE TO FACILITY (42) Z TYPE (43) NA DESCRIPTION (44) NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PUBLICITY (45) N ISSUED (46) NA DESCRIPTION (47) NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

7906220408 S
NRC USE ONLY
68 69

PHONE: (315) 343-2110 Ext. 1306

