

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N Y N M P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 2 0 7 0 6 2 3 8 0 8 20 7 2 2 8 0 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation supervisory review of recorder indications re-
0 3 vealed that the condenser inlet/circulating water discharge delta temp
0 4 exceeded the 31.2°F Tech Spec limit for more than 8 hrs. in a 24 hour
0 5 period on days of 6/20-23/80. Since the delta temp was a maximum of 32°F
0 6 during the entire period, there was no significant environmental effect.
0 7
0 8

0 9 SYSTEM CODE H F 11 CAUSE CODE A 12 CAUSE SUBCODE A 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 8 0 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 X 19 B 20 A 21 0 4 4 4 N 23 N 24 Z 25 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Shift operations personnel evaluation of temperature chart recorder at
1 1 times in question did not consider the delta temp indication as being in
1 2 violation. However upon supervisory review of the recorder indications
1 3 it was determined that the Tech Spec limit was being exceeded, and an
1 4 immediate station load reduction was taken. In addition the chart

1 5 FACILITY STATUS E 28 % POWER 0 9 9 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Supervisory Review 32
7 8 9 10 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
7 8 9 10 80

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
7 8 9 10 80

NRC USE ONLY

8007290 600 NAME OF PREPARER Paul Harrison

PHONE: 315-343-2110 X 1212

ATTACHMENT LER 80-11

Cause Description and Corrective Actions (Continued)

recorder scale is being expanded to increase accuracy of the recorder, and a technical specification change has been submitted to increase the allowable delta temp to 35⁰F.

ATTACHMENT LER 80-11

Cause Description and Corrective Actions (Continued)

recorder scale is being expanded to increase accuracy of the recorder,
and a technical specification change has been submitted to increase
the allowable delta temp to 35⁰F.

مجلس