

**LICENSEE EVENT REPORT**

**CONTROL BLOCK:**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14		LICENSE NUMBER										25	LICENSE TYPE					30		57	CAT	58

**CON'T**

0	1	REPORT SOURCE		L	6	0	5	0	0	0	2	2	0	7	0	9	2	7	8	0	8	1	0	2	4	8	0	9
7	8	60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0	2	During normal operation, a Low Power Range Monitor (LPRM)
0	3	detector failed with two others in the same channel
0	4	previously out of service. This rendered #18
0	5	Average Power Range Monitor (APRM) unit inoperable
0	6	
0	7	
0	8	

SYSTEM CODE I B (11)		CAUSE CODE E (12)		CAUSE SUBCODE A (13)		COMP. SUBCODE E (15)		VALVE SUBCODE Z (16)	
EVENT YEAR 8 0 (21) (22)		SEQUENTIAL REPORT NO. 0 2 2 (24) (25) (26)		OCCURRENCE CODE 0 3 (28) (29)		REPORT TYPE L (30)		REVISION NO. 0 (32)	
ACTION TAKEN X (18)		FUTURE ACTION A (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 0 (22) (23) (24) (25)	
ATTACHMENT SUBMITTED N (23)		NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER N (25)		COMPONENT MANUFACTURER G 0 8 0 (26) (27) (28) (29)			

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Investigation determined detector failure was caused by internal shorting. The immediate condition of an inoperable APRM was rectified by placing the APRM in the bypass mode as allowed by Tech Specs.

1 1

1 2

1 3 Final rectification will entail LPRM detector replacement during the next refueling outage.

1 4

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				
1	5	E	28	0	9	8	29	NA	A	31	Alarm Response	32
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						
1	6	Z	33	Z	34	NA	NA	36				
PERSONNEL EXPOSURES		TYPE		DESCRIPTION								
1	7	0	0	0	37	Z	38	NA	39			
PERSONNEL INJURIES		DESCRIPTION										
1	8	0	0	0	40	NA	41					
LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION										
1	9	Z	42	NA	43							
PUBLICITY		DESCRIPTION										
2	0	N	44	NA	45							

8010810454

NRC USE ONLY

81010310 454

**NRC USE ONLY**

NAME OF PREPARER Paul Harrison

PHONE: (315) 343-2110 Ext. 1212

